

**Note: This document has not been finalised.****LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

To: ECICS Limited  
10 Eunus Road 8  
#09-04A Singapore Post Centre  
Singapore 408600From: LKK Auto Consultants Pte Ltd  
51 Ubi Ave 1 #01-25  
Paya Ubi Industrial Park  
Singapore 408933

Attn:

Date: 13 Jun 2024

**Preliminary Advice**

Insured Vehicle No	: YN6032Z	Accident Date	: 09/06/2024
TP Vehicle No	: SLA3806A	Assignment Date	: 13/06/2024
Make	: NISSAN NOTE	Est. Duration of Repair	: 3
Date of Inspection	: 12/06/2024		
Inspection At	: TAN CHONG MOTOR (HQ) 19 UBI ROAD 4 SINGAPORE 408623		

**Point of Impact / General Description of Damages**

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	3,861.72
Revised Amount	:S\$	2,736.72
Check Items (Estimated)	:S\$	50.00
Total	:S\$	2,786.72
Lump Sum Repair	:S\$	

**Total Loss Consideration**

New for Old Value	:S\$
Pre-Accident Value	:S\$
COE / PARF Rebate	:S\$
Salvage Value	:S\$
Margin for Repair	:S\$

**Remarks**

- ( ) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- ( ) The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- ( X ) Other comments : Please note that the preliminary advice amount (Revised & Check Items) stated are subject to consistency check, part prices and labour cost.