

BLUWEL AUTOMOTIVE SERVICE PTE LTD
1 KAKI BUKIT AVE 6 # 01-28/53/55/56
SINGAPORE 417883 TEL :67452088

Not Authorised
23/7/24
4/s # 6000
4 days
the ph. At 11p -

VEHICLE No: SMG 8389K

1PC	BOOTLID	Do/But	\$1,266.10	/
1PC	BOOTLID REAR LOGO	su	\$68.50	X
1PC	BOOTLID 'COROLLA' EMBLEM	111	\$62.80	/
1PC	BOOTLID 'ALTIS' EMBLEM	111	\$58.00	/
1PC	BOOTLID OUTER CHROME MOULDING	11	\$399.20	X
1PC	BOOTLID INNER LOCK	Damage/111	\$409.10	/
1PC	BOOTLID LOCK STRICKER	11	\$66.80	X
1PC	BOOTLID WEATHERSTRIP	111	\$282.30	/
2PCS	BOOTLID REFLECTORS @\$450.90	11	\$901.80	X
1PC	BOOTLID INNER TRIM	11	\$366.10	X
2PCS	BOOTLID HINGES @\$145.00	su	\$290.00	X
1PC	REAR BUMPER	Do/2e	\$755.10	/
1PC	REAR BUMPER BEAM	But	\$505.40	/
2PCS	REAR BUMPER REFLECTORS @\$60.00	11	\$120.00	X
2PCS	REAR BUMPER SIDE RETAINERS @\$65.00	11	\$130.00	X
1SET	REAR BUMPER CLIPS	111	\$50.00	/
1PC	REAR BUMPER UNDER COVER	111	\$248.20	/
1PC	REAR END PANEL	Do/But	\$808.20	/
1PC	REAR END PANEL TOP GARNISH	111	\$362.30	/
2PCS	TAILLAMPS @\$980.00	111	\$1,960.00	/
2PCS	TAILLAMP HOUSING PANELS @\$408.00	11	\$816.00	X
1PC	REAR ANTENNA SENSOR	11	\$241.20	X
1PC	REAR FLOOR PANEL	11	\$1,145.20	X
1PC	REAR FLOOR PANEL TOP BOARD	111	\$420.50	/
2PCS	REAR FENDERS @\$1091.20	11	\$2,182.40	X
			\$13,915.20	
			LESS 25%	\$10,436.40

S.NETT

1SET	REAR BUMPER REVERSE SENSOR	111/111/111	\$280.00	200
1PC	REAR END PANEL SEALANT	111	\$50.00	30
1SET	REAR FLOOR PANEL INSULATOR	11	\$250.00	X
			\$50.00	20
			\$80.00	30

TO CHECK WIRING

TO DISMANTLE & REPLACED REVERSE SENSOR

TO DISMANTLE & REFIX BOOTLID MECHANISM
 TO DISMANTLE & REFIX CUSHION UPHOLSTERY
 TO DISMANTLE & REFIX REAR WINDSCREEN
 TO SPRAY RUST PROOFING
 LABOUR FOR PANEL BEATING & REPLACED PARTS
 TO PUTTY & SPRAY PAINTING

	\$100.00	50
	\$120.00	60
11	\$120.00	x
	\$100.00	60
	\$1,200.00	750
	\$1,500.00	1000
TOTAL	\$14,286.40	

LKK Auto Consultants hence notify
 the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
 is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

27078
 252
 5308.50
 230
 1970
 7508.50
 202
 6006.