

1ST AUTOMOTIVE SERVICES PTE LTD

Address: 53 Ubi Ave 1 #01-23 S(408934)
Contact: 83686767

Estimate for SNF5415G(Toyota Sienta)

Not Authorized
as
notes

12/07/24

5 days d/c \$3800/
the photo. All in -

*REAR BOOT LID Tailgate	Body 2D	\$1,131.50 ✓
*REAR BOOT LID TOYOTA LOGO	111	\$67.40 ✓
*REAR BOOT LID OUTER HANDLE	11	\$485.70 X
*REAR BOOT LID TOP LOCK	SC	\$373.70 X
*REAR BOOT RUBBER	111	\$353.00 ✓
*REAR BOOT LID L/R SIDE REFLECTOR	11	\$656.70 X
*TAILGATE WIPER MOTOR	11	\$455.80 X
*TAILGATE LOCK CATCH	11	\$46.00 X
*TAILGATE INNER TRIM	11	\$586.00 X
*REAR END PANEL top	Body 2D	\$661.71 ✓
*REAR END PANEL LOCK GARNISH	111	\$212.79 ✓
*REAR END PANEL LOCK GARNISH CLIPS	11	\$32.00 X
*TAIL LAMP L/R	11	\$939.40 X
*REAR BUMPER TOP protector centre	DD	\$498.70 ✓
*REAR BUMPER BOTTOM	DD	\$367.95 ✓
*REAR BUMPER CLIPS	111	\$40.00 ✓
*REAR BUMPER TOP BRACKET	11	\$175.80 X
*REAR BUMPER SIDE RETAINER L/R	11	\$184.60 X
*REAR BUMPER SIDE PROTECTOR L/R	01 111 111 111	\$169.95 ✓
*REAR BUMPER CENTER PROTECTOR	11	\$267.90 X
*REAR BUMPER SIDE PROTECTOR L/R	11 11	\$157.52 X
*REAR BUMPER REFLECTOR	11	\$250.40 X
*REAR WINDSCREEN MOULDING	NS	\$133.70 X
*TAILGATE DETECTOR	11	\$321.00 X
*TAILGATE DETECTOR WIREHARNES	11	\$589.00 X
*REAR BUMPER TOW COVER	11	\$43.90 X
*REAR FENDER INNER TRIM	11	\$1,378.00 X
*REAR FENDER INNER COWLING	11	\$203.00 X
*REAR FLOOR PANEL	11	\$784.00 X
*REAR FLOOR PANEL TOP BOARD	11	\$716.00 X
*REAR TOOL BOX GARNISH	11	\$585.00 X
*REAR EXHAUST SILENCER	11	\$899.20 X
*REAR EXHAUST MOUNTING	11	\$90.00 X
*REAR EXHAUST HEAT PLATE	11	\$166.00 X
		\$14,023.32
Less 25%		\$3,505.83
		\$10,517.49

S/NETT

*REAR BUMPER CLIP	111	\$50.00 40 5/11
*TAIL LAMP CLIP	11	\$32.00 X

1 set

1 set

*TAILGATE WINDSCREEN SEALANT	111	\$80.00	40	s/w
*TAILGATE WINDSCREEN INNER SEAL	111	\$80.00	20	s/w
*TAILGATE OUTER GARNISH CLIP	11	\$40.00	X	
*TAILGATE INNER TRIM CLIP	11	\$50.00	X	
*REAR FENDER INNER TRIM CLIPS	11	\$60.00	X	
*REAR FENDER INNER COWLING CLIPS	11	\$60.00	X	
*REAR END PANEL TOP GARNISH CLIPS	11	\$40.00	X	
*REAR END PANEL Sealant	111	\$120.00	40	s/w
*REAR FLOOR PANEL INSULATION SEAL	11	\$150.00	X	
*REVERSE CAMERA	11	\$600.00	X	
*REVERSE SENSOR	10/10/2018	\$280.00	200	s/w
		\$1,642.00		
PANEL BEATING, REMOVAL AND REPLACING PARTS		\$1,600.00	700	
TO SPRAY PAINT AFFECTED AREA		\$1,600.00	800	
TUFF COAT		\$300.00	60	
WIRING CHECK		\$120.00	20	
REMOVE AND REFIX CUSHION SEAT / UPHOLSTERY AND ROOF LINING TO FACILITATE REPAIR		\$250.00	80	
TRANSFER TAILGATE MECHANISM		\$150.00	60	
CONDUCT WATER LEAKAGE TEST	11	\$60.00	X	
REMOVE AND REFIX TAILGATE WINDSCREEN		\$150.00	120	
REMOVE AND REFIX REAR EXHAUST PIPE	11	\$150.00	X	
REMOVE AND INSTALL REVERSE CAMERA AND TEST FUNCTION	11	\$200.00	X	
REMOVE AND INSTALL REVERSE SENSOR AND CHECK FUNCTIONER		\$200.00	40	
		\$4,780.00		
TOTAL		\$16,939.49		

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged parts before resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

P- 3384-50
252
P- 2539-13
S.N- 340
L- 1880
4749.13
202
3807