



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No.
19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

MS LIBERTY INSURANCE PTE LTD	Ref:	CS/LIP24070210/Uvh3
ONE RAFFLES QUAY #25-01 NORTH TOWER	Date:	11/07/2024
SINGAPORE 048583	Code:	LIP

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	TRC 5597H	Veh. Inspected	SMZ 288X
Policy No.	-	Coverage	0
Claim No.	AVS24/2120	Excess	\$0.00
Assign From	ANDY SEAH	Assign Date	10/07/2024

2. Vehicle Details

Make & Model	TOYOTA HARRIER G (A)	C.C	1998
Engine No.	8ARZ146073	Year of Reg.	27/03/2019
Chassis No.	JTEKB3GH40J003943	Colour	RED
Odometer	98865 KM	Steering	IN ORDER
Brakes	IN ORDER	General	GOOD
Modification(s)	RIMS: SPORTS RIM		

3. Conditions of Tyres

	Size	Make	Balance (mm)
R/H Front Tyre	235/50R19	GOODYEAR	5
L/H Front Tyre	235/50R19	GOODYEAR	5
R/H Rear Tyre	235/50R19	GOODYEAR	5
L/H Rear Tyre	235/50R19	GOODYEAR	5

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE O/S BODY.

DAMAGES SEE DETAILS.

5. General Information

Accident Date	24/06/2024	Inspection Date	11/07/2024
Survey held at	JOO HAK KEE AUTO PTE LTD - 3007 UBI ROAD 1 #01-406 KAMPONG UBI INDUSTRIAL ESTATE SINGAPORE 408701		

5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: 3 Working Days