

9 EGNATV

b.p. v.k.

BIFROST AUTO PTE LTD

8 KAKI BUKIT AVE 4, PREMIER @ KAKI BUKIT

#01-49 SINGAPORE 415875

Tel: +65 64524457

Fax: +65 64524584

TP China

Xiao Chen

Vehicle number: SNJ285B

Make & Model: Mazda 3

Chassis number: JM6BP2SAAAP1151675

No.	Description of spare parts	Qty	Amount S\$
1	Bonnet <i>new</i>	1	\$ 1,045.50
2	Front bumper <i>torn</i>	1	\$ 994.32
3	Front bumper clips <i>new</i>	1set	\$ 70.00
4	Front bumper LH fog lamp cover	1	\$ 89.40
5	Front bumper RH side retainer <i>new</i>	1	\$ 23.52
6	Front bumper LH side retainer	1	\$ 23.52
7	Front bumper RH chrome moulding <i>new</i>	1	\$ 341.95
8	Front bumper RH chrome moulding rivets (small) <i>new</i>	1set	\$ 74.20
9	Front bumper RH chrome moulding rivets (big) <i>new</i>	1set	\$ 22.28
10	Front bumper LH bracket <i>new</i>	1	\$ 67.69
11	Front bumper LH parking sensor <i>new</i>	1	\$ 221.00
12	LH headlamp assy <i>new</i>	1	\$ 4,156.79
13	Front LH fender <i>Dented</i>	1	\$ 357.97
14	Front LH fender splash shield <i>torn</i>	1	\$ 202.00
15	Front LH fender splash shield clips <i>new</i>	1set	\$ 60.00
16	Front LH sport rim (Original) <i>new</i>	1	\$ 1,264.29
17	Front LH wheel bearing <i>new</i>	1	\$ 611.75
18	Front LH shock absorber <i>new</i>	1	\$ 378.79
19	Front LH shock absorber upper mounting <i>new</i>	1	\$ 101.00
20	Front LH shock absorber upper mounting bearing <i>new</i>	1	\$ 56.00
21	Front LH shock absorber stopper	1	\$ 42.00
22	Front LH knuckle arm	1	\$ 431.10
23	Front LH lower arm	1	\$ 496.03
24	Front LH tie rod end	1	\$ 95.15
25	Front LH drive shaft <i>new</i>	1	\$ 1,138.40
26	Front LH sway bar linkage	1	\$ 174.20
27	Steering rack and pinion	1	\$ 2,019.80
28	I-stop capacitor	1	\$ 4,123.00
29	LH side mirror housing <i>new</i>	1	\$ 984.30

5544.24
4435.39

SN 750

\$ 18,620.45
Parts less 20% \$ 3,724.09
Total: \$ 14,896.36

No.	Special Nett Items	Qty	Amount S\$
1	Front LH tyre <i>new</i>	1	\$ 500.00
2	Brake fluid <i>new</i>	1	\$ 75.00
Total:			\$ 575.00

No.	Labour and painting	Amount S\$
1	Labour charges to remove, check, replace and reinstall damages bodyparts. To panel beating, cut/weld and realign all affected panels and areas	\$ 1,400.00
2	Spray painting on affected areas and panels	\$ 1,300.00
3	Check wiring and lighting system on affected areas	\$ 80.00
4	Apply rust coating chemical on affected areas and panels	\$ 60.00
5	Refocus and adjust headlamps assy	\$ 50.00
6	Remove and replace front bumper parking sensors to assist repair	\$ 100.00
7	Test drive and adjust wheel alignment system	\$ 150.00
8	Remove and replace front undercarriage parts to assist repair	\$ 550.00
9	Perform diagnostic and re-program after accident repairs	\$ 380.00
Total:		\$ 2,670.00

Agreed Amount: _____ (Part by Part / Lump sum)
Working days: _____

1060

Total: 6245.39

US SK ✓

Spare Parts: \$ 14,896.36
Special Nett: \$ 575.00
Labour: \$ 2,670.00
Total: \$ 18,141.36

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Adrian L
2/5 11/07/24
04 Rep