

Kaki Bukit AutoHub
 2 Kaki Bukit Ave 2
 #01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
 Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
 E-Mail : sales@n51.com.sg
 Company Reg. No. : 200616038C
 GST Registration No. : 200616038C

TECHCOM ENGINEERING PTE LTD
 2 YISHUN INDUSTRIAL ST 1 #04-11
 SINGAPORE 633688

TP INC
 Xiao Chan.

Contact : 86870588

TAX INVOICE

Repair Code : CLM18301

Date in : 10/07/2024

Vehicle Num. : GBF8027R

Model : TOYOTA HIACE VAN TURBO 5 DR MANUAL

Chassis/Eng# : JTFHT02PX00216689/1KD2686970

Parts and Labour Assesment

Description of part	Qty	Unit Price	1890 Amount
FRONT RH DOOR <i>Dented</i>	1	2245.20	2,245.20
FRONT RH DOOR CHECKER	1	96.50	+ 96.50
FRONT RH DOOR HINGE (LOWER) <i>2</i>	1	199.40	+ 199.40
FRONT RH DOOR HINGE (TOP)	1	199.40	+ 199.40
FRONT RH DOOR INNER ARCH GARNISH <i>new</i>	1	95.70	+ 95.70
FRONT RH DOOR INNER TRIM BOARD <i>could</i>	1	852.70	852.70
FRONT RH DOOR MECHANISM LOCK <i>new</i>	1	613.30	+ 613.30
FRONT RH DOOR SIDE MIRROR ASSY <i>lit</i>	1	1492.90	1,492.90
FRONT RH DOOR WEATHER STRIP <i>new</i>	1	249.40	+ 249.40
FRONT RH DOOR WEATHER STRIP (ARCH) <i>new</i>	1	55.20	+ 55.20
FRONT RH DOOR WINDOW REGULATOR WITH MOTOR <i>And</i>	1	347.70	✓ 347.70
FRONT RH DOOR WIRE HARNESS	1	526.70	+ 526.70
FRONT RH DOOR WIRE HARNESS COVER <i>new</i>	1	867.50	+ 867.50
FRONT RH HEADLAMP <i>new</i>	1	791.40	+ 791.40
FRONT RH STEP GARNISH <i>lit</i>	1	175.40	✓ 175.40
FRONT RH STEP PANEL <i>Regis</i>	1	78.90	+ 78.90

*** This is a computer-generated document which requires no signature.***

Kaki Bukit AutoHub
 2 Kaki Bukit Ave 2
 #01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
 Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
 E-Mail : sales@n51.com.sg
 Company Reg. No. : 200616038C
 GST Registration No. : 200616038C

TECHCOM ENGINEERING PTE LTD
 2 YISHUN INDUSTRIAL ST 1 #04-11
 SINGAPORE 633688

Contact : 86870588

TAX INVOICE

Repair Code : CLM18301
 Date in : 10/07/2024
 Vehicle Num. : GBF8027R
 Model : TOYOTA HIACE VAN TURBO 5 DR MANUAL
 Chassis/Eng# : JTFHT02PX00216689/1KD2686970

Subtotal before discount		8,887.30
Percentage discount 25%	4793.10	2,221.83
Sub-total 1		6,665.48
FRONT RH DOOR 3D ART WORK STICKER <i>new</i>	1	450.00 <i>200 450.00</i>
FRONT RH DOOR COMPANY DETAIL STICKER <i>new</i>	1	25.00 <i>✓ 25.00</i>
FRONT RH DOOR INNER TRIM BOARD CLIPS - SET <i>new</i>	1	50.00 <i>30 50.00</i>
Subtotal before discount		525.00
Percentage discount 0%		0.00
Sub-total 2		525.00
Parts-total		7,190.48

LABOUR

- To remove, reinstall electrical wiring harness, check lighting and resetting headlamp focussing. (to FR)
- To transfer door glass, regulator gear, motor, railing, channel, trim board, mechanism lock and handle.
- To re-spray painting on the change bodyparts, repair portion, and where consistent to the accident.
- To provide labour, workmanship to change the above damaged bodyparts, repair, re-construct and re-align body structure, body alignments and damaged consistent to the accident.
- To apply anti-rust chemical on repaired and replaced panel

30	80.00 <i>✓</i>
60	120.00 <i>✓</i>
500	800.00 <i>✓</i>
300	750.00 <i>✓</i>
30	80.00 <i>✓</i>

Labour Total 1,830.00
 Parts & Labour Total 9,020.48

LKK Auto Consultants hereby notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

*** This is a computer-generated document which requires no signature.***

Acknowledged by Repairer

Signature:

Date:

page 2

Adrian Lj
W/S 11/07/24.

3.61K

03 Days
total 4544.82
W/S: 3.6K