



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No.
19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

MS INCOME INSURANCE LTD	Ref:	CS/INC24070213/Aqh3e2
75 BRAS BASAH ROAD	Date:	23/12/2024
INCOME CENTRE SINGAPORE 189557	Code:	INC

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	XE 8922B	Veh. Inspected	GBF 8027R
Policy No.	-	Coverage	0
Claim No.	MT/1284768-002	Excess	\$0.00
Assign From	SHAFAWATI	Assign Date	11/07/2024

2. Vehicle Details

Make & Model	TOYOTA HIACE	C.C	2982
Engine No.	1KD2686970	Year of Reg.	17/03/2017
Chassis No.	JTFHT02PX00216689	Colour	SILVER
Odometer	259315 KM	Steering	IN ORDER
Brakes	IN ORDER	General	GOOD
Modification(s)	RIMS: NIL		

3. Conditions of Tyres

	Size	Make	Balance (mm)
R/H Front Tyre	195 R15C	CONDOR	6
L/H Front Tyre	195 R15C	CONDOR	6
R/H Rear Tyre	195 R15C	YOKOHAMA	6
L/H Rear Tyre	195 R15C	YOKOHAMA	6

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE O/S BODY

DAMAGES SEE DETAILS.

5. General Information

Accident Date	04/07/2024	Inspection Date	11/07/2024 (11:45)
Survey held at	N-51 AUTOMOTIVE PTE LTD - 2 KAKI BUKIT AVE 2 #01-17 KAKI BUKIT AUTOHUB SINGAPORE 417921		

5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: 3 Working Days