



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,  
Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No.  
19-9607198-R

## Affiliated to Federation Internationale Des Experts En Automobile

MS MS FIRST CAPITAL INSURANCE LTD	Ref:	CS/FCI24070215/Kvp3e2
16 RAFFLES QUAY	Date:	11/07/2024
#42-01 HONG LEONG BUILDING	Code:	FCI2
SINGAPORE 048581		

### 1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SHB 6270S	Veh. Inspected	SHB 7670P
Policy No.	D-24101861MFCT	Coverage	0
Claim No.	D24005932MFCT	Excess	\$0.00
Assign From	CAROLINE	Assign Date	11/07/2024

### 2. Vehicle Details

Make & Model	TOYOTA PRIUS (A)	C.C	1798
Engine No.	2ZR2C42877	Year of Reg.	16/08/2019
Chassis No.	JTDKB3FU003082681	Colour	METALLIC PEARL WHITE / RED
Odometer	508692 KM	Steering	IN ORDER
Brakes	IN ORDER	General	GOOD
Modification(s)	RIMS: STANDARD ALLOY RIM		

### 3. Conditions of Tyres

	Size	Make	Balance (mm)
R/H Front Tyre	195/65R15	SAILUN	7
L/H Front Tyre	195/65R15	SAILUN	7
R/H Rear Tyre	195/65R15	WANLI	6
L/H Rear Tyre	195/65R15	WANLI	6

### 4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.

DAMAGES SEE DETAILS.

### 5. General Information

Accident Date	04/07/2024	Inspection Date	11/07/2024
Survey held at	TRANS-CAB AUTO SERVICES PTE LTD NO.2 ANG MO KIO ST 63 SINGAPORE 569111		

### 5a. Remarks

A) DAMAGES CONSISTENT TO ACCIDENT REPORT.  
B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.  
C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

### 5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: 3 Working Days