

NOT AUTHORIZED
L1 Sy @ 3150p
Penny After Pain

AAD2407-037

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel Nc Fax No. : 62571330

CO./ GST Reg. No. 201019626G

SHB7670P

Vehicle No.:

Chassis No.:

Co UEN.:

Vehicle Make:

Vehicle Model:

Date of Accident:

Third Party Insurer:

Date of Registration:

11 JUL 2024

SHB7670P

JTDKB3FU003082681

200303878K

TOYOTA

PRIUS

4/7/2024

SMB 62705 / FCI

16/8/2019

PART

- 1 COVER, REAR BUMPER
- 1 COVER, REAR BUMPER, LOWER
- 1 RETAINER, REAR BUMPER SIDE, RH
- 1 RETAINER, REAR BUMPER SIDE, LH
- 1 SEAL, REAR BUMPER SIDE, RH
- 1 SEAL, REAR BUMPER SIDE, LH
- 1 GUARD, REAR BUMPER, CENTER
- 1 REINFORCEMENT SUB-ASSY, REAR BUMPER
- 1 FILLER, REAR BUMPER EXTENSION, RH
- 1 FILLER, REAR BUMPER EXTENSION, LH
- 1 COVER, FLOOR UNDER, RH
- 1 COVER, FLOOR UNDER, LH
- 1 COVER, REAR FLOOR
- 1 COVER, BACK DOOR TRIM
- 1 PANEL SUB-ASSY, BODY LOWER BACK
- 1 LENS & BODY, REAR COMBINATION LAMP, LH (UPPER)
- 1 LENS AND BODY, REAR LAMP, LH
- 1 COVER, REAR COMBINATION LAMP, LH
- 1 LENS & BODY, REAR COMBINATION LAMP, RH (UPPER)
- 1 LENS AND BODY, REAR LAMP, RH
- 1 COVER, REAR COMBINATION LAMP, RH
- 1 PANEL SUB-ASSY, BACK DOOR
- 1 BOARD ASSY, BACK DOOR TRIM
- 1 PANEL ASSY, BACK DOOR TRIM, UPPER
- 1 BOARD, BACK DOOR TRIM
- 1 BOX, DECK FLOOR, REAR
- 1 BOX, DECK FLOOR, RH
- 1 BOX, DECK FLOOR, LH
- 1 STAY ASSY, BACK DOOR, LH
- 1 STAY ASSY, BACK DOOR, RH

LIST

\$	CMA	558.39	✓
\$	MT	19.43	✓
\$	RL	148.58	X
\$	ASJUM	148.58	✓
\$	RL	111.41	X
\$	RL	111.41	X
\$	RL	726.92	✓
\$	RL	419.90	✓
\$	RL	155.72	X
\$	MY	62705	X
\$	RL	220.50	X
\$	DIR	304.92	✓
\$	MT	290.43	✓
\$	RL	31.50	X
\$	RL	824.46	X
\$	RL	559.13	
\$	RL	634.73	
\$	RL	81.48	
\$	RL	570.15	
\$	RL	634.73	
\$	RL	81.48	
\$	RL	1,443.86	
\$	RL	326.76	
\$	RL	65.73	
\$	RL	284.55	X
\$	RL	133.25	
\$	RL	395.12	
\$	RL	394.38	
\$	RL	305.66	X
\$	RL	305.66	

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel Nc Fax No. : 62571330

CO./ GST Reg. No. 201019626G

SHB7670P

- 1 HINGE ASSY, BACK DOOR, LH
- 1 HINGE ASSY, BACK DOOR, RH
- 1 GARNISH SUB-ASSY, BACK DOOR, OUTSIDE
- 1 PLATE, LUGGAGE COMPARTMENT DOOR NAME, NO.2
- 1 PLATE, BACK DOOR NAME, NO.1
- 1 ORNAMENT SUB-ASSY, BACK DOOR

AAD2407-

\$	R	77.18	X
\$	R	77.18	X
\$	Pr	1,171.38	X
\$	M	68.88	—
\$	M	68.88	—
\$	M	90.30	—
TOTAL		\$ 11,998.25	
25%	\$	2,999.56	
	\$	8,998.68	

SPECIAL NETT**1SET PARKING AID**

- 1 REAR BUMPER CLIP
- 1 REAR RH BUMPER RETAINER CLIP
- 1 REAR NUMBER PLATE
- 1 FENDER LINER CLIP
- 1 REAR TAIL LAMP CLIP
- 1 END PANEL INNER TRIM CLIP
- 1 BOOT STICKER TRANSCAB
- 1 BOOT STICKER TEL NO
- 1 REAR BUMPER PROTECTOR
- 2 WINDSCREEN SEALANT
- 1 WINDSCREEN MOULDING
- 1 WINDSCREEN INNER SPONGE SEAL

\$	Del	700.00	220sn
\$	M	65.00	60sn
\$	nn	65.00	X
\$	Pr	180.00	X
\$	nn	65.00	X
\$	nn	65.00	X
\$	nn	60.00	X
\$	M	100.00	30sn
\$	M	100.00	30sn
\$	M	180.00	40sn
\$	nn	150.00	X
\$	nn	200.00	X
\$	nn	130.00	X
TOTAL		\$ 2,060.00	
TOTAL PARTS		\$ 11,058.68	

LABOUR

To rust-proofing of the affected areas.

\$ nn 600.00 X

Putty and spray painting of the affected portion.

\$ 1,200.00 8801

Panel beating, knocking and straightening the necessary portion, remove and renewal of parts, adjust and realign the same

\$ 2,000.00 5001

To transfer of tailgate fittings and conduct water seepage test.

\$ nn 170.00 X

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel Nc Fax No. : 62571330

CO./ GST Reg. No. 201019626G

SHB7670P

To remove and refit interior fittings, trimmings, garnish,
fittings and other, to enable repair.

\$ *nn* 380.00 X

To reinstall rear bumper parking sensor.

\$ 170.00 *501*

To check steering geometry and computer wheel alignment \$ *nn* 220.00 X

To Transfer Of Fender Fittings, Attachments And Perform
Water Seepage Test.

\$ *nn* 170.00 X**TOTAL \$ 4,910.00****OVERALL TOTAL \$ 15,968.68***3 days*

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: