

ASSIGNMENT

From: _____ Date: _____
Estimated Cost: _____
OD / TP / WS / TP RES / OD RES / EVA / INV / MV
To Inspect Vehicle No: FBN1676X
at Workshop m/s BHM
of _____
Insured: _____
Policy No. _____
Claims No. _____
Sum Insured: _____ Excess: _____
(Client's Record)
Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

A	
N/S	O/S

Bal. or Market Value: \$6800
IDAC Accident Rpt: _____ Consistent? : Yes or No
GIA / PR Seen: _____ Consistent? : Yes or No
Est. Repairs: 3 days Res.: Yes or No
Lum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____ Vehicle: IN / OUT
A1A52682

Veh No: FBN1676X Yr Regn: 27/07/18
Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
Truck / Trailer or
Make: Yamaha NMAX 155 c.c 155
Colour: white A/C: Insured / Std / NI / NA
Sp.Reading: 133463 T/Radio: Insured / Std / NI / NA
Eng/No: _____
C/No: MH35643/000007448
Gen. Cond: Good / Fair / Poor / Burnt
Steering: Inorder / Jammed / Leaked / Burnt or
Brake: Inorder / Jammed / Leaked / Burnt or
Modi: N/A / S/Rim / STD A/Rim or
Tyre Size: F: 110-70-13
R: 130-70-13
BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or Eurogrip
Front R/Bal. 4 mm Rear R/Bal. 4 mm
L/Bal. mm L/Bal. mm
D.O.A. 23/05/24 D.O.I. 13/6/24
Survey held at _____
Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or
MS Body
The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
27/6/24	Dep 1600 N/A \$4118 1/5 \$1250 in hand Raymond

Date/Time, File Pass to?

1)

Date/Time, File Return to?

2)

Report Format :

Lump Sum / I.B.I: (\$)

☐ : Preli. Report

☐ : Final Report

Days Of Repair:

Resurvey No. of Trip:

Add Fee: ☐ : Site Insp (\$)

☐ : Interview (\$)

☐ : Tech. Invs (\$)

☐ : Weekend (\$)

Survey Fee:

Transportation:

____ S + RS, ____ SI

) Photos

) Others

TOTAL



QUOTATION

Customer :

INDIA INTERNATIONAL INSURANCE P.L.
64 CECIL STREET
#04-00 & #06-00
IOB BUILDING
SINGAPORE 049711

NO. : 46747

DATE : 28/05/2024
CLAIM NO. : 12501
POLICY NO. : MC/01008824/02
FROM : RAYMOND

VEHICLE NO. : FBN1676X
MAKE/MODEL : YAM / NMAX155 ABS

*Not Authorised
13/6/24
d/s #1250
3 days
per ph...*

(Page 1 of 3)

S/N	Description	Action	Qty	Unit Price	Amount
1	BELLY PAN P/N: 58094 - (REPORTED BY MECHANIC)	<i>cut</i> REPLACE	1.00	\$37.00 ✓	37.00
2	BOARD FOOTREST LH P/N: 59588 - (REPORTED BY MECHANIC)	<i>cut</i> REPLACE	1.00	\$58.00 ✓	58.00
3	BOX FILTER AIR OUTER P/N: 58141 - (REPORTED BY MECHANIC)	<i>cut</i> REPLACE	1.00	\$19.00 ✓	19.00
4	BOX FILTER AIR OUTER FRONT P/N: 58164 - (REPORTED BY MECHANIC)	<i>17</i> REPLACE	1.00	\$12.00 ✗	12.00
5	BOX REAR (GIVI) B45NM P/N: 79580 - (REPORTED BY MECHANIC)	<i>cut</i> REPLACE	1.00	\$272.00 ✓	272.00
6	COVER CLUTCH OUTER P/N: 58147 - (REPORTED BY MECHANIC)	<i>cut</i> REPLACE	1.00	\$31.00 ✓	31.00
7	COVER CLUTCH OUTER DAMPER 1 P/N: 58111 - (REPORTED BY MECHANIC)	<i>cut</i> REPLACE	1.00	\$13.00 ✓	13.00
8	COVER CLUTCH OUTER DAMPER 2 P/N: 58172 - (REPORTED BY MECHANIC)	<i>nm</i> REPLACE	1.00	\$8.00 ✓	8.00
9	COVER CLUTCH OUTER DAMPER 3 P/N: 58107 - (REPORTED BY MECHANIC)	<i>nm</i> REPLACE	1.00	\$8.00 ✓	8.00

*46747 *



bizSAFE



S/N	Description	Action	Qty	Unit Price	Amount
10	COVER CLUTCH OUTER DAMPER 4 P/N: 58140 - (REPORTED BY MECHANIC)	REPLACE <i>neu</i>	1.00	\$13.00 ✓	13.00
11	COVER FRONT UPPER (WHITE) P/N: 59585 - (REPORTED BY MECHANIC)	REPLACE <i>cu</i>	1.00	\$40.00 ✓	40.00
12	COVER SIDE LH (GREY) P/N: 60877 - (REPORTED BY MECHANIC)	REPLACE <i>cu</i>	1.00	\$42.00 ✓	42.00
13	COVER SIDE LOWER LH (WHITE) P/N: 58097 - (REPORTED BY MECHANIC)	REPLACE <i>cu</i>	1.00	\$24.00 ✓	24.00
14	COVER SIDE REAR LH (WHITE) P/N: 58170 - (REPORTED BY MECHANIC)	REPLACE <i>cu</i>	1.00	\$33.00 ✓	33.00
15	COWLING FRONT LH (WHITE) P/N: 58179 - (REPORTED BY MECHANIC)	REPLACE <i>neu</i>	1.00	\$36.00 ✓	36.00
16	LABOUR P/N: 06766 - (REPORTED BY MECHANIC)	<i>X</i> REPLACE	5.00	\$85.00 <i>300</i>	425.00
17	LAMP SIGNAL FRONT LH P/N: 59587 - (REPORTED BY MECHANIC)	REPLACE <i>cu</i>	1.00	\$39.00 ✓	39.00
18	MIRROR LH P/N: 58099 - (REPORTED BY MECHANIC)	REPLACE <i>neu</i>	1.00	\$33.00 ✓	33.00
19	MUDGUARD FRONT (WHITE) P/N: 58087 - (REPORTED BY MECHANIC)	REPLACE <i>cu</i>	1.00	\$51.00 <i>X</i>	51.00
20	OBU TYPE B (12V) NEW P/N: 82490 - (REPORTED BY MECHANIC)	REPLACE <i>cu neu</i>	1.00	\$341.00 <i>X old type</i>	341.00
21	PANEL 1 (SILVER) LH P/N: 60905 - (REPORTED BY MECHANIC)	REPLACE <i>cu</i>	1.00	\$24.00 ✓	24.00
22	RIVET P/N: 56583 - (REPORTED BY MECHANIC)	REPLACE <i>neu</i>	7.00	\$3.00 ✓	21.00 ✓
23	SCREW (WINDSHIELD) P/N: 62053 - (REPORTED BY MECHANIC)	REPLACE <i>neu</i>	1.00	\$3.00 <i>1/c X</i>	3.00
24	SPARY LACQUER - (REPORTED BY MECHANIC)	<i>1.50</i> <i>X</i> REPLACE	1.00	\$0.00 <i>300</i>	0.00

*46747 *

bizSAFE₃

S/N	Description	Action	Qty	Unit Price	Amount
25	STICKER (CISCO DIAMOND GRADE) COWLING FRONT LH P/N: 79323 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$45.00	45.00
26	STICKER (CISCO DIAMOND GRADE) COWLING REAR LH P/N: 79321 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$40.00	40.00
27	STICKER (CISCO DIAMOND GRADE) MUDGUARD FRT P/N: 79325 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$48.00	48.00
28	STICKER (CISCO DIAMOND GRADE) SIDE BOTTOM COWL LH P/N: 79324 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$57.00	57.00
29	STICKER (CISCO) COVER CENTRE LH P/N: 58614 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$40.00	40.00
30	STICKER (CISCO) COWLING FRONT LH P/N: 58616 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$40.00	40.00
31	STICKER (CISCO) LINING COVER REAR RH P/N: 58613 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$17.00	17.00
32	STICKER (CISCO) MUDGUARD FRONT P/N: 58618 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$40.00	40.00

SUB TOTAL

\$1,910.00

GST @ 9 %

\$171.90

GRAND TOTAL (SGD)

\$2,081.90

50% deposit required before ordering of parts.

Validity: 30 days

For & on Behalf of

BAN HOCK HIN CO PTE LTD



RAYMOND

Acknowledge & Accepted By

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) for resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

*46747 *

bizSAFE₃

Blk 8 Defu South Street 1, #04-28, JTC Defu Industrial City, Singapore 533758 | Tel: +65 6281 6520 | www.bhh.com.sg
 Fax: (Main) + 65 6281 2830, (Spare Parts) + 65 6285 7530, (Insurance/Project) +65 6284 2969, (Accounts) + 65 6281 6759

CERT NO.: 2002-140383
 ISO 9001: 2015

p. 751
 102
 675.50
 327
 600
 1602.9
 201
 1282.