Note: This document has not been finalised. LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

To: AIG Asia Pacific Insurance Pte. Ltd. From: LKK Auto Consultants Pte Ltd

AIG Building, 78 Shenton Way

#09-16

Singapore 079120

51 Ubi Ave 1 #01-25

Paya Ubi Industrial Park

Singapore 408933

Attn: Hiew, Chasin Date: 10 Oct 2024

Preliminary Advice

 Vehicle No
 : SKJ5360U
 Accident Date
 : 09/07/2024

 Make
 : AUDI A5
 Policy No.
 : 7220045142

 Assignment Date
 : 11/07/2024
 Excess
 : \$\$1,400.00

Date of Inspection : 12/07/2024 Est. Duration of Repair : 4

Inspection At : PREMIUM AUTOMOBILES PTE LTD (UBI)

55 UBI ROAD 1 SINGAPORE 408699

Point of Impact / General Description of Damages

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	15,912.36 (estimate \$15,855.00 + Supplementary \$57.36)
Revised Amount	:S\$	4,455.04 (Inclusive of supplementary)
	*	, , , , , , , , , , , , , , , , , , , ,
Check Items (Estimated)	:S\$	0.00
Total	:S\$	4,455.04
Lump Sum Repair	:S\$	

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	114,000.00
COE / PARF Rebate	:S\$	96,265.00
Salvage Value	:S\$	
Margin for Repair	:S\$	17,735.00

Remarks

(X	()	The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
()	The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.

(X) Other comments: KINDLY APPROVE ON SUPPLEMENTARY.