

ASSIGNMENT

From: _____ Date: _____

Estimate: _____

OD / TP / TP RES / OD RES / EVA / INV / MV

To In Vehicle No: _____

at W/O _____

of _____

Insured: _____

Policy No: _____

Claims No: _____

Sum Insured _____ Excess: _____

(Client's Record)

Make of Vehicle: _____

(Policy Condition)

Remarks: Vehicle had commenced its repair at the time of inspection.

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE : ACCIDENT REPAIRS
WORKSHOP : UBI ROAD 1
CONTACT NO : 6366 2323
FAX NO : 6841 1183
REFERENCE : PA/OD/0543/2024/KS
DATE : 11-Jul-24
WIP : 22810

VEHICLE IN WORKSHOP. KINDLY ARRANGE FOR SURVEY ON 12/7/2024

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Motor Claims Dept

OWNER'S

55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE. SKJ 5360 U

S/N	NATURE OF JOBS	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE, CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHT, HORNS, OUTSIDE TEMPERATURE SENSOR, HEADLIGHT WASHER.	S/N \$ 360.00	X
2	TO REMOVE AND TRANSFER LHS HEADLIGHT CONTROL UNIT AND POWER MODULE	S/N \$ 400.00	250
3	TO DISMANTLE AND RENEW FRONT BUMPER, LHS FRONT FENDER, AND LHS HEADLIGHT. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	\$ 2,400.00	500
4	TO RESPRAY FRONT BUMPER AND LHS FRONT FENDER.	\$ 2,000.00	1100
5	TO CARRY OUT DIAGNOSTIC CHECK.	S/N \$ 292.00	✓
TOTAL LABOUR CHARGES		: \$ 5	

55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SKJ 5360 U

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
1	FRONT BUMPER <i>Repair</i>	1	\$ 3,254.00	+
2	FRONT BUMPER FIXING PARTS <i>new</i>	1	\$ 286.00	+
3	FRONT BUMPER SECURING STRIP - LH <i>2</i>	1	\$ 45.00	+
4	FRONT BUMPER CLOSING ELEMENT - LH	1	\$ 286.00	+
5	FRONT BUMPER AIR GUIDE GRILLE - LH			

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SKJ 5360 U

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
21	SIDE MEMBER COVER - LH LOWER FRONT <i>HN</i>	1	\$ 19.00	<i>X</i>
22	FRONT WHEEL HOUSING LINER - LH <i>HN</i>	1	\$ 219.00	<i>X</i>
23	WHEEL HOUSING LINER ATTACHMENT PARTS - LH <i>HN</i>	1	\$ 50.00	<i>X</i>
24	SUNDRIES <i>?</i>		\$ 500.00	<

55 UBI ROAD 1, SINGAPORE 408699
TEL : 6366 2323 FAX : 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME :

SURVEYED DATE :

AUTHORISED DATE :

EXCESS COST :

LIABILITY :

REMARKS :

Adrian Y
12/07/24

Not Authorized, 04 Days

PLEASE NOTE :

THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER LABOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF REPAIR, WE SHALL INFORM YOU ACCORDINGLY.
FOR INSPECTION OF VEHICLE,