

IP STRIDES  
AUTOMOTIVE  
44 ADV-L-1


SMRT Accident Vehicle Repair Estimates

SMRT Auto  
60 Woodlar  
FAX Numbe  
Estimator T  
Accident Re

Sompo

Date Gener  
User ID

Section A - Accident Details	
Registration Number	SHB5217D
Case Reference Number	TAX/07/24/2035
Registration Date	30/11/2020
Company Type	Strides Premier Taxi Pte Ltd
Make	TOYOTA
Model	PRIUS4FL
Name of Driver	LEE KWANG HANN
Type of Accident	Side Swipe
Accident Date and Time	10/7/2024 4:05 PM
Accident Reported Date and Time	11/7/2024 10:52 AM
Is Surveyor Required?	No
Survey by	
Vehicle is Towed Back?	No
Towed Back Date and Time	
Replacement Vehicle issued?	No
Job Card Number	24121809
Special Instruction to ARC,if any	TP/TOWED/LEFT FRONT PORTION
Prepared Date and Time	11/7/2024 1:05 PM
Chassis Number	
Mileage	
Work Shop	
Repair Completion Date and Time	

Section B - Summary of Repair Estimates		
Summary of Repair Estimates		
	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Cost	\$845.00	\$0.00
Total Spray Cost	\$976.00	\$0.00
Total Spare Part Cost	\$5,799.98	\$0.00
Total Other Cost	\$1,114.44	\$0.00
TOTAL COST	\$8,735.42	\$0.00
Lump Sum Total	\$8,750.00	\$0.00
Number of Repair Days	6.0	
Prepared / Adjusted By	Boon Chew Tay	
ARC / Surveyor Sign Off Date		
Signature		<input checked="" type="checkbox"/>
Remarks		

Section C - Quotation and Accident Invoice Details			
Quotation Number		Invoice Number	
Quotation Date		Invoice Date	
Invoice Amount		Prepared Date	



## SMRT Accident Vehicle Repair Estimates

- To resurvey before/after spray painting
- To display damaged part(s) before resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

## Section D - Details of Repair Estimates

SMRT Autor

60 Woodlanc

FAX Number

Estimator Te

Accident Rep

Date Genera

User ID

not authorized  
for  
1/17/24 @ 11am  
to be paid after 1/15/24  
3 days

## Part 1 - Labour Works

Job Scope	Quotation from AR	Adjusted by Surveyor, if applicab
TO REPAIR LH FRONT PORTION	\$845.00	200
<b>Total Labour</b>	<b>\$845.00</b>	<b>200</b>

## Part 2 - Spray Painting &amp; Panel Beating Related Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicab
TO RESPRAY FRONT BUMPER	\$378.00	200
TO RESPRAY FRONT FENDER LH	\$378.00	200
TO RESPRAY RIM	\$220.00	100
<b>Total Spray Painting &amp; Panel Beating</b>	<b>\$976.00</b>	

## Part 3 - Other Costs - Accident and Accident Repair Related Expense

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicab
TOWING CHARGE	\$56.00	347 ✓
TO CHECK WIRING AND SYSTEM FUNCTION	\$120.00	11X
TO APPLY RUST-PROOFING ON AFFECTED AREA	\$100.00	11X
TO DO WHEEL ALIGNMENT / TYRE BALANCING	\$120.00	60
TO REMOVE AND REFIT TYRE	\$120.00	11X
TO PROVIDE LABOUR & MATERIAL FOR ADVERTISEMENT STICKER (NET)	\$148.44	rec ✓
TO REMOVE AND REFIX UNDERCARRIAGE	\$350.00	11X
TO REPLACE SUNDRY PARTS	\$100.00	11X
<b>Total Other Costs</b>	<b>\$1,114.44</b>	

## Part 4 - Spare Parts / Material Usage

Part Number	Portion	Stock Number	Part Name	Quantity	List Price (\$)	Discount (%)	Final Price (\$)	Estimator Approved	Surveyor Ap
		52119-47980	COVER, FR BUMPER	1.00	\$565.60	25.00	\$424.20	Replace	DD ✓
		52116-47050	SUPPORT, FR BUMPER LH	1.00	\$86.20	25.00	\$64.65	Replace	CR ✓
	Low cover	52128-47910	COVER, FR BUMPER LH	1.00	\$32.70	25.00	\$24.53	Replace	MIS ✓
		53112-47310	GRILLE, RADIATOR	1.00	\$192.80	25.00	\$144.60	Replace	11X
		53101-47100	GRILLE SUB-ASSY	1.00	\$457.10	25.00	\$342.83	Replace	11X
		53111-47140	GRILLE, SUB-ASSY, 2	1.00	\$170.20	25.00	\$127.65	Replace	11X
		51451-12120	COVER ASSY, ENGINE	1.00	\$261.60	25.00	\$196.20	Replace	11X
		52161-16010	CLIPS PIECE, FRT BUMPER	10.00	\$4.80	25.00	\$36.00	Replace	rec ✓
		52535-50060	RETAINER, FR BUMPER, LH & RH	1.00	\$9.50	25.00	\$7.13	Replace	11X
		52421-47030	PAD, FRONT BUMPER (NO.1)	1.00	\$44.10	25.00	\$33.08	Replace	rec ✓
		52421-47040	PAD, FRONT BUMPER (NO.2)	1.00	\$38.90	25.00	\$29.17	Replace	rec ✓
		52713-47040	MOULDING, FRONT BUMPER SIDE, LH	1.00	\$103.70	25.00	\$77.78	Replace	SCN ✓
		52618-47130	ABSORBER, FR BUMPER LOWER	1.00	\$143.60	25.00	\$107.70	Replace	11X
		52611-47210	ABSORBER, FR BUMPER	1.00	\$86.60	25.00	\$64.95	Replace	11X
		81185-47890	UNIT, HEADLAMP, LH	1.00	\$2,852.40	25.00	\$2,139.30	Replace	11X
		81220-12240	LAMP ASSY, FOG, LH	1.00	\$256.50	25.00	\$192.38	Replace	11X
		51444-12080	COVER, ENGINE UNDER SIDE LH	1.00	\$86.20	25.00	\$64.65	Replace	11X
		51410-47021	COVER ASSY, ENGINE UNDER CENTER SET	1.00	\$511.20	25.00	\$383.40	Replace	11X



## SMRT Accident Vehicle Repair Estimates

SMRT Autor
60 Woodlanc
FAX Number
Estimator Te
Accident Rep

Date Genera

User ID

### Part 4 - Spare Parts / Material Usage

Part Number	Portion	Stock Number	Part Name	Quantity	List Price (\$)	Discount (%)	Final Price (\$)	Estimator Approved	Surveyor Ap
		53802-47100	FENDER SUB-ASSY, FR , LH	1.00	\$1,060.70	25.00	\$795.53	Replace	R X
		75374-47140	EMBLEM, SIDE PANEL (HYBRID)	1.00	\$59.10	25.00	\$44.33	Replace	11 X
		53876-47060	LINER, FR FENDER, LH	1.00	\$227.80	25.00	\$170.85	Replace	Tor X
		53828-47070	PROTECTOR, FR FENDER LH	1.00	\$101.80	25.00	\$76.35	Replace	11 X
		53852-47041	PAD, FR WHEEL LH	1.00	\$65.00	25.00	\$48.75	Replace	11 X
		42611-47450	WHEEL, DISC FRONT	1.00	\$2,036.30	25.00	\$1,527.23	Replace	R X
			TYRE	1.00	\$126.74	0.00	\$126.74	Replace	11 X
		43550-47020	HUB & BEARING ASSY, RH & LH	1.00	\$722.10	25.00	\$541.58	Replace	11 X
Total					\$10,303.24		\$7,791.56		


### Added Spare Parts / Material Usage After Surveyor Signed off

Part Number	Portion	Stock Number	Part Name	Quantity	List Price \$	Discount (%)	Final Price (\$)	ARC Check	Surveyor Cl
Total									

P-1147  
 252  
 860.25  
 less 202  
 688.20  
 200  
 764.44  
 1652.64

P-860.25  
 L-964.44  
 1824.69  
 202  
 1459.

Section A - Accident Details	
Registration Number	SHB5217D
Case Reference Number	TAX/07/24/2035
Registration Date	30/Nov/2020
Company Type	Strides Premier Taxi Pte Ltd
Make	TOYOTA
Model	PRIUS4FL
Name of Driver	LEE KWANG HANN
Type of Accident	Side Swipe
Accident Date and Time	10/Jul/2024 4:05 PM
Accident Reported Date and Time	11/Jul/2024 10:52 AM
Is Surveyor Required?	Yes
Survey by	
Vehicle is Towed Back?	No
Towed Back Date and Time	
Replacement Vehicle issued?	No
Job Card Number	24121809
Special Instruction to ARC, if any	TP/TOWED/LEFT FRONT PORTION
Prepared Date and Time	11/Jul/2024 1:05 PM
Chassis Number	
Mileage	
Work Shop	
Repair Completion Date and Time	

Section B - Summary of Repair Estimates		
Summary of Repair Estimates		
	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Cost	\$845.00	\$200.00
Total Spray Cost	\$976.00	\$500.00
Total Spare Part Cost	\$6,233.25	\$860.26
Total Other Cost	\$1,114.44	(\$110.26)
<b>TOTAL COST</b>	<b>\$9,168.69</b>	<b>\$1,450.00 (L/S)</b>
<b>Lump Sum Total</b>	<b>\$9,150.00</b>	<b>\$0.00</b>
Number of Repair Days	6.0	3.0
Prepared / Adjusted By	Boon Chew Tay	MARCUS CHUA (LKK) / Sompoo
ARC / Surveyor Sign Off Date	12/07/2024 4:10 PM	12/07/2024 2:17 PM
Signature		Marcus Chua
Remarks	REQ TOWING INVOICE REQ WHEEL ALIGNMENT REPORT L/S REPAIR / AFTER PAINT PHOTO, FOR CHECK ITEM and REPLACE ITEM PLEASE CALL SURVEYOR MARCUS CHUA (LKK) / HP: 9009 6608 / Email: marcuschua@lkkauto.com	

*Handwritten notes:*  
 $\frac{1}{1} \times \$1450 = 1450$   
 ✓ on 7/8/24