

Strides Premier Accident Vehicle Repair Estimates

Strides Premier Automotive Services Pte Ltd
60 Woodlands Industrial Park E4, Singapore 757705
FAX Number : 63685592
Estimator Telephone Number : 68662623
Accident Reporting Number : 68662672

Date Generated : 18/07/2024

User ID : PohSuan

Section A - Accident Details

Registration Number	SHB5217D
Case Reference Number	TAX/07/24/2035
Registration Date	30/Nov/2020
Company Type	Strides Premier Taxi Pte Ltd
Make	TOYOTA
Model	PRIUS4FL
Name of Driver	LEE KWANG HANN
Type of Accident	Side Swipe
Accident Date and Time	10/Jul/2024 4:05 PM
Accident Reported Date and Time	11/Jul/2024 10:52 AM
Is Surveyor Required?	Yes
Survey by	
Vehicle is Towed Back?	No
Towed Back Date and Time	
Replacement Vehicle issued?	No
Job Card Number	24121809
Special Instruction to ARC, if any	TP/TOWED/LEFT FRONT PORTION
Prepared Date and Time	11/Jul/2024 1:05 PM
Chassis Number	
Mileage	
Work Shop	
Repair Completion Date and Time	

Section B - Summary of Repair Estimates

Summary of Repair Estimates		
	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Cost	\$845.00	\$200.00
Total Spray Cost	\$976.00	\$500.00
Total Spare Part Cost	\$6,233.25	\$688.21
Total Other Cost	\$1,114.44	\$264.44
TOTAL COST	\$9,168.69	\$1,652.65
Lump Sum Total	\$9,150.00	\$1,650.00 (L/S)
Number of Repair Days	6.0	3.0
Prepared / Adjusted By	Boon Chew Tay	MARCUS CHUA (LKK) / Sompo
ARC / Surveyor Sign Off Date	12/07/2024 4:10 PM	12/07/2024 2:17 PM
Signature		
Remarks	REQ TOWING INVOICE REQ WHEEL ALIGNMENT REPORT L/S REPAIR / AFTER PAINT PHOTO , FOR CHECK ITEM and REPLACE ITEM PLEASE CALL SURVEYOR MARCUS CHUA (LKK) / HP : 9009 6608 / Email : marcuschua@kkauto.com	

Section C - Quotation and Accident Invoice Details			
Quotation Number	QN-2407-0222	Invoice Number	
Quotation Date	18.07.2024	Invoice Date	
Invoice Amount		Prepared Date	

Section D - Details of Repair Estimates		
Part 1 - Labour Works		
Job Scope	Quotation from AR	Adjusted by Surveyor, if applicable
TO REPAIR LH FRONT PORTION	\$845.00	\$200.00
Total Labour	\$845.00	\$200.00

Part 2 - Spray Painting & Panel Beating Related Works		
Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO RESPRAY FRONT BUMPER	\$378.00	\$200.00
TO RESPRAY FRONT FENDER LH	\$378.00	\$200.00
TO RESPRAY RIM	\$220.00	\$100.00
Total Spray Painting & Panel Beating	\$976.00	\$500.00

Part 3 - Other Costs - Accident and Accident Repair Related Expense		
Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TOWING CHARGE	\$56.00	\$56.00
TO CHECK WIRING AND SYSTEM FUNCTION	\$120.00	\$0.00
TO APPLY RUST-PROOFING ON AFFECTED AREA	\$100.00	\$0.00
TO DO WHEEL ALIGNMENT / TYRE BALANCING	\$120.00	\$60.00
TO REMOVE AND REFIT TYRE	\$120.00	\$0.00
TO PROVIDE LABOUR & MATERIAL FOR ADVERTISEMENT STICKER(NET)	\$148.44	\$148.44
TO REMOVE AND REFIX UNDERCARRIAGE	\$350.00	\$0.00
TO REPLACE SUNDRY PARTS	\$100.00	\$0.00
Total Other Costs	\$1,114.44	\$264.44

Part 4 - Spare Parts / Material Usage									
Part Number	Portion	Stock Number	Part Name	Quantity	List Price (\$)	Discount (%)	Final Price (\$)	Estimator Approved	Surveyor Approved
		52119-47980	COVER, FR BUMPER	1.00	\$565.60	25.00	\$424.20	Replace	Replace
		52116-47050	SUPPORT, FR BUMPER LH	1.00	\$86.20	25.00	\$64.65	Replace	Replace
		52128-47910	COVER, FR BUMPER LH	1.00	\$32.70	25.00	\$24.53	Replace	Replace
		53112-47310	GRILLE, RADIATOR	0.00	\$192.80	0.00	\$0.00	Replace	Not Given
		53101-47100	GRILLE SUB-ASSY	0.00	\$457.10	0.00	\$0.00	Replace	Not Given
		53111-47140	GRILLE, SUB -ASSY , 2	0.00	\$170.20	0.00	\$0.00	Replace	Not Given
		51451-12120	COVER ASSY, ENGINE	0.00	\$261.60	0.00	\$0.00	Replace	Not Given
		52161-16010	CLIPS PIECE, FRT BUMPER	10.00	\$4.80	25.00	\$36.00	Replace	Replace
		52535-50060	RETAINER, FR BUMPER, LH & RH	0.00	\$9.50	0.00	\$0.00	Replace	Not Given

Strides Premier Accident Vehicle Repair Estimates

Strides Premier Automotive Services Pte Ltd	
60 Woodlands Industrial Park E4, Singapore 757705	
FAX Number : 63685592	
Estimator Telephone Number : 68662623	
Accident Reporting Number : 68662672	

Date Generated : 18/07/2024

User ID : PohSuan

		52421-47030	PAD, FRONT BUMPER (NO.1)	1.00	\$44.10	25.00	\$33.08	Replace	Replace	√
		52421-47040	PAD, FRONT BUMPER (NO.2)	1.00	\$38.90	25.00	\$29.17	Replace	Replace	√
		52713-47040	MOULDING, FRONT BUMPER SIDE, LH	1.00	\$103.70	25.00	\$77.78	Replace	Replace	√
		52618-47130	ABSORBER, FR BUMPER LOWER	0.00	\$143.60	0.00	\$0.00	Replace	Not Given	X
		52611-47210	ABSORBER, FR BUMPER	0.00	\$86.60	0.00	\$0.00	Replace	Not Given	X
		81185-47890	UNIT , HEADLAMP , LH	0.00	\$2,852.40	0.00	\$0.00	Replace	Not Given	X
		81220-12240	LAMP ASSY, FOG, LH	0.00	\$256.50	0.00	\$0.00	Replace	Not Given	X
		51444-12080	COVER, ENGINE UNDER SIDE LH	0.00	\$86.20	0.00	\$0.00	Replace	Not Given	X
		51410-47021	COVER ASSY, ENGINE UNDER CENTER SET	0.00	\$511.20	0.00	\$0.00	Replace	Not Given	X
		53802-47100	FENDER SUB-ASSY, FR , LH	1.00	\$1,060.70	100.00	\$0.00	Replace	Repair	R
		75374-47140	EMBLEM, SIDE PANEL (HYBRID)	0.00	\$59.10	0.00	\$0.00	Replace	Not Given	X
		53876-47060	LINER, FR FENDER, LH	1.00	\$227.80	25.00	\$170.85	Replace	Replace	√
		53828-47070	PROTECTOR, FR FENDER LH	0.00	\$101.80	0.00	\$0.00	Replace	Not Given	X
		53852-47041	PAD, FR WHEEL LH	0.00	\$65.00	0.00	\$0.00	Replace	Not Given	X
		42611-47450	WHEEL, DISC FRONT	1.00	\$2,036.30	100.00	\$0.00	Replace	Repair	R
			TYRE	0.00	\$126.74	0.00	\$0.00	Replace	Not Given	X
		43550-47020	HUB & BEARING ASSY, RH & LH	0.00	\$722.10	0.00	\$0.00	Replace	Not Given	X
Total					\$10,303.24		\$860.26			

Added Spare Parts / Material Usage After Surveyor Signed off									
Part Number	Portion	Stock Number	Part Name	Quantity	List Price \$	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check
Total									

	860.26	
	-20%	
	688.21	L/S \$1,650/-
+	200.00	
+	764.44	
	1,652.65	