



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No.
19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

MS ALLIED WORLD ASSURANCE COMPANY LTD (SINGAPORE BRANCH) 60 ANSON ROAD #08-01 (8TH FLOOR) MAPLETREE ANSON SINGAPORE 079914	Ref: CS/AWA24070220/Anp3 Date: 14/10/2024 Code: AWA
---	---

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	YN 954C	Veh. Inspected	SNQ 8523A
Policy No.	BVFCB0013842302	Coverage	0
Claim No.	CSG24VFC2A00003/HLF	Excess	\$0.00
Assign From	STELLA GOH	Assign Date	12/07/2024

2. Vehicle Details

Make & Model	MERCEDES BENZ E200	C.C	1991
Engine No.	26492030471656	Year of Reg.	15/06/2022
Chassis No.	W1K2130802B035257	Colour	BLACK
Odometer	19463 KM	Steering	IN ORDER
Brakes	IN ORDER	General	GOOD
Modification(s)	RIMS: SPORTS RIM		

3. Conditions of Tyres

	Size	Make	Balance (mm)
R/H Front Tyre	245/45 R18	PIRELLI	6
L/H Front Tyre	245/45 R18	PIRELLI	6
R/H Rear Tyre	245/45 R18	PIRELLI	6
L/H Rear Tyre	245/45 R18	PIRELLI	6

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE FRONT AND REAR PORTION.

DAMAGES SEE DETAILS.

5. General Information

Accident Date	11/07/2024	Inspection Date	12/07/2024
Survey held at	RYDER AUTO PTE LTD 2 KAKI BUKIT AVE 2 #02-19/22 KAKI BUKIT AUTOHUB SINGAPORE 417921		

5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: 14 Working Days