

ESTIMATE OF REPAIR

Veh# : SNQ8523A

Model: MERCEDES BENZ

Accident Date : 11/7/2024

(31/10/2016 - 30/10/2026)

Location : AYE

3P: YN954C (ALLIED WORLD)

Hui Rong.

S/Nos.	Qty	Description	List \$	S/Nett \$	Nett \$
1	2 pcs	Front headlamp R/L <i>could</i>	9,408.00	✓ 7700	
2	1 pc	Front support panel top bracket <i>could</i>	292.70	✓	
3	1 pc	Front support panel (upper) <i>not needed</i>	972.40	✓	
4	1 pc	Front grille <i>could</i>	1,511.90	✓	
5	1 pc	Front grille upper bracket <i>needed</i>	345.60	✓	
6	1 pc	Front grill camera <i>could</i>	2,110.20	✓ 1420	
7	1 pc	Front radar sensor <i>new</i>	910.40	x	
8	1 pc	Front radar sensor bracket <i>could</i>	90.40	✓	
9	1 pc	Front air vent (upper) <i>needed</i>	1,240.60	✓ 720	
10	1 pc	Front air vent (lower)	749.30	✓	
11	1 pc	Front bumper <i>needed</i>	2,407.40	✓ 1775	
12	1 pc	Front bumper reinforcement <i>needed</i>	1,021.40	✓ 845	
13	1 pc	Front bumper reinforcement Rh <i>needed</i>	190.20	✓	
14	2 pcs	Front bumper side retainer R/L <i>could</i>	194.20	✓	
15	1 pc	Front bumper inner sponge <i>new</i>	234.00	x	
16	6 pcs	Front bumper parking sensor <i>new 2 pins</i>	1,860.00	x	620
17	6 pcs	Front bumper parking sensor 'O' ring <i>new 2 pins</i>	78.00	x	26
18	6 pcs	Front bumper parking sensor holder bracket <i>new</i>	180.00	x	150
19	1 pc	Front bumper center grille <i>needed</i>	171.60	✓	
20	2 pcs	Front bumper side fog lamp cover R/L <i>could</i>	272.80	✓	
21	1 pc	Front bumper tow hook cover <i>new</i>	64.00	x	
22	1 pc	Front bumper upper bracket <i>new</i>	149.50	x	
23	1 pc	Front bumper chrome middle <i>needed</i>	210.50	✓	
24	1 pc	Front bumper chrome Lh & Rh <i>could</i>	420.60	✓	
25	1 set	Front bumper rivet <i>new</i>		100.00	40
26	1 pc	Front bumper no. plate bracket garnish <i>needed</i>	170.30	✓	
27	1 pc	Front no. plate <i>could</i>		35.00	✓
28	1 pc	Front no. plate holder <i>new</i>		50.00	x

29	1 pc	Rear boot <i>Dented</i>	2,801.50	✓	
30	1 pc	Rear boot Logo <i>Me</i>	67.60	✓	
31	3 pcs	Rear boot Logo clip <i>Me</i>		16.50	✓
32	1 pc	Rear boot emblem E200 <i>3 sec</i>	117.45	✓	
33	1 pc	Rear boot emblem C&C		80.00	✓
34	1 pc	Rear boot emblem 9 G-TRONIC EMBLEM <i>Me</i>	165.00	✓	
35	1 pc	Rear boot chrome moulding <i>Dented</i>	298.70	✓	
36	1 pc	Rear boot chrome garnish <i>could</i>	258.70	✓	
37	1 pc	Rear boot mechanism lock <i>Rnd</i>	583.50	✓	
38	1 pc	Rear boot weatherstrip seal <i>Me</i>	252.00	+	
39	1 pc	Rear taillamp Rh <i>could</i>	959.00	739	
40	1 pc	Rear boot lid lamp Rh <i>cut</i>	401.50	✓	
41	2 pcs	Rear taillamp lower bracket R/L <i>Rlt could</i>	144.00	77.	
42	1 pc	Rear bumper <i>Dented</i>	2,164.50	2017	
43	1 pc	Rear bumper reinforcement <i>Dented</i>	1090.50	993	
44	1 pc	Rear bumper reinforcement insulator L/R <i>X60 Me</i>	150.80	+	
45	1 pc	Rear bumper side retainer Rh <i>Me</i>	150.00	+	
46	1 pc	Rear bumper retainer middle <i>could</i>	210.40	✓	
47	1 pc	Rear bumper lower lid garnish <i>Dented</i>	328.90	✓	
48	1 pc	Rear bumper lower lid garnish moulding chrome <i>could</i>	373.20	✓	
49	1 pc	Rear bumper lower lid garnish bracket <i>Me</i>	71.40	+	
50	1 pc	Rear bumper lower lid garnish bracket garnish <i>Me</i>	90.60	✓	
51	1 set	Rear bumper clip <i>Me</i>		50.00	✓
52	1 pc	Rear bumper tow hook cover <i>Dented</i>	62.00	✓	
53	4 pcs	Rear bumper reverse sensor <i>2 pieces dented</i>	1,360.00	680	
54	4 pcs	Rear bumper reverse sensor 'O' ring <i>2 pieces Me</i>	52.00	26.	
55	6 pcs	Rear bumper reverse sensor holder bracket <i>Me</i>	180.00	100	
56	1 pc	Rear bumper reverse sensor wireharness <i>Me</i>	468.00	+	
57	1 pc	Rear bumper inner frame bracket - Center <i>Me</i>	118.80	+	
58	1 set	Rear bumper rivet <i>Me</i>		100.00	to
59	1 pc	Rear bumper Rh chrome exhaust tip <i>Rnd</i>	440.60	✓	
60	1 pc	Rear bumper Rh reflector <i>could</i>	170.20	✓	

61	1 pc	Rear Rh fender <i>Buehard</i>	3,033.60 <i>2648</i>		
62	1 pc	Rear no. plate <i>744</i>		35.00	+
63	1 pc	Rear no. plate holder		50.00	+
64	2 pcs	Rear safety belt R/L <i>Aolimited</i>	1,571.00	<i>1410</i>	
65	2 pcs	Front safety belt R/L <i>Aolimited</i>	2,349.80	<i>1820</i>	
Sub Total:			45,741.25	516.50	0.00
<i>3536775 S.N: 261.50</i>			10%	0%	0%
<i>3183097</i>			After Less %:	41,167.13	516.50
0.00					
Labour					
1		To remove & refix accident damaged parts & realign accident affected area.	1,800.00	<i>1660</i>	
2		To spray paint on accident affected area.	1,600.00	<i>1200</i>	
3		To remove & refix air-con condenser & refilling gas.	150.00	<i>60</i>	
4		To remove & refix radiator, fan motor & other attachment parts.	80.00	<i>60</i>	
5		To remove & refix rear side covering, trim garnish & other attachment parts.	100.00	<i>60</i>	
6		To remove & refix front seat belt & rear seat belt.	150.00	<i>120</i>	
7		To check wiring & rewire parking sensor.	100.00	<i>50</i>	
8		To diagnosis & reset after work.	350.00	<i>200</i>	
9		To rust proof affected area.	120.00	<i>60</i>	
Sub Total:			4,450.00		
Total:			46,133.63		

Chan
Chan San Choon
Director
DipEng, AAE MIMI, MSAE(Aust)

Adrian G
L/S 12/07/24.
14 Days.



8778 1999
24 hr accident call



Total: 35502.47
L/S: 28.4K.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date: