

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933
TEL: 6256 3561 FAX: 6256 4315
Reg. No: 199607198R GST Reg. No.
19-9607198-R

Tax Invoice

MS FIRST CAPITAL INSURANCE LTD
16 RAFFLES QUAY
#42-01 HONG LEONG BUILDING

SINGAPORE 048581

INV No. : SAC2401346
INV Date : 12-11-2024

Reference CD/FCI24070222/Rma3q2
Code FCI2

PROFESSIONAL SERVICE FEE

Vehicle No. SNL 9561J
Insured Veh. SHD 6575C
Claim No. D24006095MFCT/CTPL/TPD2/KT
Policy No. D-24101861MFCT
Accident Date 10/07/2024
Inspection Date 29/07/2024

Description	Amount
Third Party Express Settlement	350.00
Sub-Total	350.00
GST (9%)	31.50
Grand Total	381.50

We shall be glad if you could forward the payment at your earliest convenience.

Cheque should be crossed and made payable to **'LKK Auto Consultants Pte Ltd'**

LKK Auto Consultants Pte Ltd

LKM



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No.
19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

MS MS FIRST CAPITAL INSURANCE LTD	Ref:	CD/FCI24070222/Rma3q2
16 RAFFLES QUAY	Date:	12/11/2024
#42-01 HONG LEONG BUILDING	Code:	FCI2
SINGAPORE 048581		

1. Policy Particulars :- DIRECT SETTLEMENT

Insured Veh.	SHD 6575C	Veh. Inspected	SNL 9561J
Policy No.	D-24101861MFCT	Coverage	0
Claim No.	D24006095MFCT/CTPL/TPD2/KT	Excess	\$0.00
Assign From	SERENE LER	Assign Date	11/07/2024

2. Vehicle Details

Make & Model	KIA SORENTO HYBRID 1.6A SX TECH PACK SR	C.C	1598
Engine No.	G4FTPH344739	Year of Reg.	18/08/2023
Chassis No.	KNARH81GMP5215929	Colour	RED
Odometer	25957 KM	Steering	IN ORDER
Brakes	IN ORDER	General	FAIR
Modification(s)	RIMS: SPORTS RIM		

3. Conditions of Tyres

	Size	Make	Balance (mm)
R/H Front Tyre	235/65 R17	CONTINENTAL	6
L/H Front Tyre	235/65 R17	CONTINENTAL	6
R/H Rear Tyre	235/65 R17	CONTINENTAL	6
L/H Rear Tyre	235/65 R17	CONTINENTAL	6

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE N/S FRONT PORTION.

DAMAGES SEE DETAILS.

5. General Information

Accident Date	10/07/2024	Inspection Date	29/07/2024
Survey held at	CYCLE & CARRIAGE KIA PTE LTD 209 PANDAN GARDENS SINGAPORE 609339		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: 4 Working Days



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933
TEL: 6256 3561 FAX: 6256 4315
Reg. No: 199607198R GST Reg. No.
19-9607198-R

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO SNL 9561J

Special Nett				
Qty	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)
1	SUNDRIES (SN)	NECESSARY	\$50.00	\$20.00
1	PANEL ASSY FRONT DOOR LH (SN)	BENT	\$1,411.00	\$1,411.00
1	PANEL ASSY FENDER LH (SN)	TO REPAIR SEE LABOUR	\$772.00	\$0.00
1	GARNISH ASSY FNDR SIDE LH (SN)	SCRATCHED	\$76.00	\$76.00
1	GARNISH ASSY -FRT DR SIDE LH (SN)	SCRATCHED	\$196.00	\$196.00
1	MOULDING ASSY -SIDE SILL ,LH (SN)	NOT NECESSARY	\$129.00	\$0.00
1	GARNISH ASSY -DR FRAME LH (SN)	NOT NECESSARY	\$48.00	\$0.00
1	MOULDING ASSY -FRT DR FRAME ,LH (SN)	NECESSARY	\$46.00	\$46.00
1	WHEEL ASSY ,ALUMINIUM (SN)	SCRATCHED	\$900.00	\$900.00
1	VALVE -TPMS (SN)	NECESSARY	\$159.00	\$159.00
			\$3,787.00	\$2,808.00
Labour				
	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)
	REPLACE FRT LH FENDER ,FRT LH DOOR & AFFECTED AREA.		\$1,920.00	\$1,280.00
	PAINT WORK ON FRT LH FENDER & FRT LH FENDER		\$1,650.00	\$1,100.00
	TRANSFER FRT LH DOOR ATTACHMENTS TO NEW PANEL		\$250.00	\$250.00
	APPLY SEALANT ON AFFECTED AREA		\$120.00	\$60.00
	PERFORM RUST PREVENTION		\$120.00	\$60.00
	CHECK WIRING & CHASSIS ELECTRICAL SYSTEM		\$150.00	\$120.00
	TO CARRY OUT DIAGNOSTIC CHECK ON ELECTRONIC CONTROL SYSTEM		\$380.00	\$380.00
	TRANSFER FRT LH RIM INCLUDING BALANCING		\$60.00	\$60.00
	TO CONDUCT COMPUTERIZE FULL WHEEL ALIGNMENT		\$250.00	\$250.00
			\$4,900.00	\$3,560.00
GRAND TOTAL			\$8,687.00	\$6,368.00
RECOMMENDED COST OF REPAIRS				\$6,368.00
Report Ref No: CD/FCI24070222/Rma3q2				



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933

TEL: 6256 3561 FAX: 6256 4315
Reg. No: 199607198R GST Reg. No.
19-9607198-R

MRB

MOHAMMED RASUL BIN MOHD YUNUS

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.



No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.





PHOTOGRAPHS FOR VEHICLE NO. : SNL 9561J




PHOTOGRAPHS FOR VEHICLE NO. : SNL 9561J



PHOTOGRAPHS FOR VEHICLE NO. : SNL 9561J



PHOTOGRAPHS FOR VEHICLE NO. : SNL 9561J



PHOTOGRAPHS FOR VEHICLE NO. : SNL 9561J





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No.
19-9607198-R

INSPECTION PHOTOS (Page 7 of 12)

PHOTOGRAPHS FOR VEHICLE NO. : SNL 9561J



PHOTOGRAPHS FOR VEHICLE NO. : SNL 9561J



PHOTOGRAPHS FOR VEHICLE NO. : SNL 9561J



PHOTOGRAPHS FOR VEHICLE NO. : SNL 9561J



PHOTOGRAPHS FOR VEHICLE NO. : SNL 9561J



PHOTOGRAPHS FOR VEHICLE NO. : SNL 9561J

