

N-51 AUTOMOTIVE PTE LTD

Kaki Bukit AutoHub
 2 Kaki Bukit Ave 2
 #01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
 Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
 E-Mail : sales@n51.com.sg
 Company Reg. No. : 200616038C
 GST Registration No. : 200616038C

TP111
 Daphne

CARSTOMERS PTE LTD
 89 KAKI BUKIT AVENUE 1 #03-00 SHUN
 LI INDUSTRIAL PARK
 SINGAPORE 417957

TAX INVOICE

Repair Code : CLM18303
 Date in : 11/07/2024
 Vehicle Num. : GBM333Y
 Model : BYD T3
 Chassis/Eng# : LC0CE4DB3M0011670/-

Contact : 96282100 94455088

Parts and Labour Assesment

Description of part	Qty	Unit Price	Amount
REAR BUMPER <i>disturbed</i>	1	2069.10	✓ 2,069.10 <i>1890</i>
REAR BUMPER CENTER LAMP <i>crack d</i>	1	469.00	✓ 469.00
REAR BUMPER CENTER LAMP COVER <i>missing</i>	1	259.00	✓ 259.00
REAR BUMPER REVERSE SENSOR <i>2 pieces damaged</i>	4	205.00	410 820.00
REAR BUMPER REVERSE SENSOR HOLDER <i>2 pieces damaged</i>	4	60.00	50 240.00
REAR BUMPER SIDE RETAINER L/R <i>crack d</i>	2	145.00	✓ 290.00
REAR END PANEL (INNER) <i>distorted</i>	1	1769.40	✓ 1,769.40 <i>1100</i>
REAR END PANEL (OUTER) <i>distorted</i>	1	1298.00	✓ 1,298.00 <i>905</i>
REAR END PANEL ANTENNA SENSOR <i>new</i>	1	295.00	✓ 295.00
REAR END PANEL INNER TOP GARNISH <i>disturbed</i>	1	326.40	✓ 326.40
REAR FLOOR PANEL <i>Repair</i>	1	4370.00	✓ 4,370.00
REAR TAILGATE <i>disturbed</i>	1	9687.00	✓ 9,687.00
REAR TAILGATE 'BYD' EMBLEM <i>new</i>	1	205.00	✓ 205.00
REAR TAILGATE 'T3' EMBLEM <i>new</i>	1	189.00	✓ 189.00
REAR TAILGATE HINGES L/R <i>new</i>	2	269.00	✓ 538.00
REAR TAILGATE INNER PULL HANDLE <i>crack d</i>	1	105.00	✓ 105.00
REAR TAILGATE INNER TRIM BOARD <i>crack d</i>	1	788.00	✓ 788.00
REAR TAILGATE LOCK COVER <i>crack d</i>	1	80.00	✓ 80.00

*** This is a computer-generated document which requires no signature.***

Kaki Bukit AutoHub
 2 Kaki Bukit Ave 2
 #01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
 Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
 E-Mail : sales@n51.com.sg
 Company Reg. No. : 200616038C
 GST Registration No. : 200616038C

CARSTOMERS PTE LTD
 89 KAKI BUKIT AVENUE 1 #03-00 SHUN
 LI INDUSTRIAL PARK
 SINGAPORE 417957

TAX INVOICE

Repair Code : CLM18303
 Date in : 11/07/2024
 Vehicle Num. : GBM333Y
 Model : BYD T3
 Chassis/Eng# : LC0CE4DB3M0011670/-

Contact : 96282100 94455088

REAR TAILGATE MECHANISM LOCK	<i>Repa</i>	1	480.00	<i>✓</i>	480.00
REAR TAILGATE NUMBER PLATE LAMP L/R	<i>re u</i>	2	115.00	<i>+</i>	230.00
REAR TAILGATE OUTER CHROME HANDLE	<i>re u</i>	1	699.00	<i>✓</i>	699.00 <i>520</i>
REAR TAILGATE WEATHER STRIP	<i>lt</i>	1	369.00	<i>✓</i>	369.00
REAR TAILLAMP L/R	<i>re u</i>	2	890.00	<i>✓</i>	1,780.00 <i>1510</i>
Subtotal before discount					27,355.90
Percentage discount 10%					2,735.59
Sub-total 1					24,620.31
REAR BUMPER CLIPS - SET	<i>re u</i>	1	80.00	<i>30</i>	80.00
REAR FLOOR PANEL TOP ALUMINIUM PLATE	<i>Best</i>	1	2800.00	<i>820</i>	2,800.00
REAR TAILGATE '6PAX' STICKER	<i>re u</i>	1	25.00	<i>15</i>	25.00
REAR TAILGATE '70KM' STICKER		1	25.00	<i>15</i>	25.00
REAR TAILGATE INNER TRIM BOARD CLIPS - SET	<i>re u</i>	1	50.00	<i>30</i>	50.00
REAR TAILGATE NUMBER PLATE	<i>re u</i>	1	25.00	<i>+</i>	25.00
REAR TAILGATE NUMBER PLATE HOLDER		1	50.00	<i>+</i>	50.00
REAR TAILGATE OUTER CHROME HANDLE CLIPS - SET	<i>re u</i>	1	50.00	<i>20</i>	50.00
REAR TAILGATE WINDSCREEN SEAL	<i>re u</i>	1	80.00	<i>40</i>	80.00
REAR TAILGATE WINDSCREEN SEALANT		1	80.00	<i>30</i>	80.00

*** This is a computer-generated document which requires no signature.***

Kaki Bukit AutoHub
 2 Kaki Bukit Ave 2
 #01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
 Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
 E-Mail : sales@n51.com.sg
 Company Reg. No. : 200616038C
 GST Registration No. : 200616038C

CARSTOMERS PTE LTD
 89 KAKI BUKIT AVENUE 1 #03-00 SHUN
 LI INDUSTRIAL PARK
 SINGAPORE 417957

Contact : 96282100 94455088

TAX INVOICE

Repair Code : CLM18303
 Date in : 11/07/2024
 Vehicle Num. : GBM333Y
 Model : BYD T3
 Chassis/Eng# : LC0CE4DB3M0011670/-

REAR TAILLAMP CLIPS L/R - SET	2	980	30.00	+	60.00
Subtotal before discount					3,325.00
Percentage discount 0%					0.00
Sub-total 2					3,325.00
Parts-total					27,945.31

LABOUR

To reset system after repair works				+	400.00
To remove, reinstall electrical wiring harness, check lighting, and rewire for parking sensor.				✓	80.00
To remove, reinstall tailgate windscreen				120	150.00
To remove, reinstall roof top trim upholstery, cushion seat, trim garnish, trim liner carpet. (to FR)				60	100.00
To re-spray painting on the change bodyparts, repair portion, and where consistent to the accident.		2600	800	✓	1,300.00
To provide labour, workmanship to change the above damaged bodyparts, repair, re-construct and re-align body structure, body alignments and damaged consistent to the accident.				1400	2,000.00
To apply anti-rust chemical on repaired and replaced panel.				80	140.00
To remove, reinstall tailgate mechanism and check for function				60	80.00
Labour Total					4,250.00
Parts & Labour Total					32,195.31

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be this is a computer-generated document which requires no signature.***

is subject to final approval from Insurance Company

Acknowledged by:
 Signature:
 Date:

Admin
 L/S 12/07/24
 08 hrs

total: 21249.16
 L/S: 17 KIC

17 KIC