


Section A - Accident Details

Registration Number	SHB1158S
Case Reference Number	TAX/07/24/2037
Registration Date	9/Sep/2021
Company Type	Strides Premier Taxi Pte Ltd
Make	MORRISGARAGES
Model	MG5
Name of Driver	LIEW CHEE KONG
Type of Accident	Head to Rear
Accident Date and Time	11/Jul/2024 3:30 PM
Accident Reported Date and Time	12/Jul/2024 9:57 AM
Is Surveyor Required?	Yes
Survey by	
Vehicle is Towed Back?	No
Towed Back Date and Time	
Replacement Vehicle issued?	No
Job Card Number	24121815
Special Instruction to ARC, if any	TP/REAR PORTION
Prepared Date and Time	12/Jul/2024 10:32 AM
Chassis Number	
Mileage	
Work Shop	
Repair Completion Date and Time	

Section B - Summary of Repair Estimates

Summary of Repair Estimates		
	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Cost	\$2,400.00	\$1,200.00
Total Spray Cost	\$1,744.00	\$850.00
Total Spare Part Cost	\$9,356.61	\$4,315.09
Total Other Cost	\$1,850.00	\$420.00
TOTAL COST	\$15,350.61	\$6,785.09 (P/P)
Lump Sum Total	\$0.00	\$0.00
Number of Repair Days	12.0	6.0
Prepared / Adjusted By	Boon Chew Tay	MARCUS CHUA (LKK) / Somp
ARC / Surveyor Sign Off Date	17/07/2024 2:21 PM	17/07/2024 11:00 AM
Signature		
Remarks	INITIAL = 8 DAYS WITH SUPP = 4 DAYS TOTAL = 12 DAYS	INITIAL = 4 DAYS / EXTEND = 2 DAYS SURVEYOR ONLY APPROVED \$35.00 FOR NUMBER PLATE AND FRAME P/P REPAIR / BEFORE PAINT PHOTO , FOR CHECK ITEM and REPLACE ITEM PLEASE CALL SURVEYOR MARCUS CHUA (LKK) / HP : 9009 6608 / Email : marcuschua@kkauto.com

Strides Premier Automotive Services Pte Ltd
60 Woodlands Industrial Park E4, Singapore 757705
FAX Number : 63685592
Estimator Telephone Number : 68662623
Accident Reporting Number : 68662672

Date Generated : 24/07/2024

User ID : PohSuan

Section C - Quotation and Accident Invoice Details			
Quotation Number	QN-2407-0273	Invoice Number	
Quotation Date	24.07.2024	Invoice Date	
Invoice Amount		Prepared Date	

Section D - Details of Repair Estimates		
Part 1 - Labour Works		
Job Scope	Quotation from AR	Adjusted by Surveyor, if applicable
TO REPLACE REAR END PANEL	\$600.00	\$400.00
TO REPAIR REAR PORTION	\$1,800.00	\$800.00
Total Labour	\$2,400.00	\$1,200.00

Part 2 - Spray Painting & Panel Beating Related Works		
Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO RESPRAY REAR PANEL	\$230.00	\$100.00
TO RESPRAY TAIL GATE	\$428.00	\$250.00
TO RESPRAY REAR FENDER LH	\$428.00	\$250.00
TO RESPRAY REAR BUMPER	\$428.00	\$250.00
TO RESPRAY REAR PANEL	\$230.00	\$0.00
Total Spray Painting & Panel Beating	\$1,744.00	\$850.00

Part 3 - Other Costs - Accident and Accident Repair Related Expense		
Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO APPLY RUST-PROOFING ON AFFECTED AREA	\$100.00	\$30.00
TO WASH AND VACUUM	\$60.00	\$0.00
TO CHECK WIRING AND SYSTEM FUNCTION	\$120.00	\$20.00
TO APPLY RUST-PROOFING ON AFFECTED AREA	\$200.00	\$30.00
TO PROVIDE LABOUR & MATERIAL FOR SOLAR FILM (NET)	\$350.00	\$0.00
TO TRANSFER REAR TAILGATE MECHANISM	\$120.00	\$60.00
TO TEST AND REFIX REVERSE SENSOR SYSTEM	\$120.00	\$30.00
TO REMOVE AND REFIX REAR WINDSCREEN	\$180.00	\$100.00
TO REPLACE SUNDRY PARTS	\$100.00	\$0.00
TO CHECK & RESET SYSTEM FUNCTION	\$350.00	\$150.00
ISOLATED OF (EV) (NET)	\$150.00	\$0.00
Total Other Costs	\$1,850.00	\$420.00

Part 4 - Spare Parts / Material Usage									
Part Number	Portion	Stock Number	Part Name	Quantity	List Price (\$)	Discount (%)	Final Price (\$)	Estimator Approved	Surveyor Approved
		10726676	LAMP ASM-RR FOG - LH	1.00	\$36.30	10.00	\$32.67	Replace	Replace
		10726677	LAMP ASM-RR FOG - RH	1.00	\$189.07	10.00	\$170.16	Replace	Replace
		10587412	LAMP ASM-TAIL(LID SI) - RH	0.00	\$407.68	0.00	\$0.00	Replace	Not Given

√
√
X

Strides Premier Accident Vehicle Repair Estimates

Strides Premier Automotive Services Pte Ltd
80 Woodlands Industrial Park E4, Singapore 757705
FAX Number : 63685592
Estimator Telephone Number : 68662623
Accident Reporting Number : 68662672

Date Generated : 24/07/2024

User ID : PohSuan

		10587411	LAMP ASM-TAIL(LID SI) - LH	0.00	\$407.68	0.00	\$0.00	Replace	Not Given	X
		10587410	LAMP ASM-TAIL(BODY SI) - RH	0.00	\$764.09	0.00	\$0.00	Replace	Not Given	X
		10587409	LAMP ASM-TAIL(BODY SI) - LH	0.00	\$764.09	0.00	\$0.00	Replace	Not Given	X
		10732857	CAMERA ASM-RR VIEW	0.00	\$237.74	0.00	\$0.00	Replace	Check	X
		10376550-WSD	SENSOR-RR PARK DIST CONT	0.00	\$65.00	0.00	\$0.00	Replace	Check	X
		10395721-SEPP	PANEL ASM-RR END	0.00	\$708.66	0.00	\$0.00	Replace	Check	X
		10327894	BAR ASM-RR BPR IMP	0.00	\$339.77	0.00	\$0.00	Replace	Check	X
		90003417	SCRIVET-RR BPR FASCIA	10.00	\$0.84	10.00	\$7.56	Replace	Replace	√
		10449047	BRACKET-RR BPR FASCIA LWR MTG - LH	0.00	\$12.80	0.00	\$0.00	Replace	Check	X
		10449056	BRACKET-RR BPR FASCIA LWR MTG - RH	0.00	\$12.80	0.00	\$0.00	Replace	Check	X
		10371790	BRACKET-PARK DIST CONT SEN(BRACKET-PARK DIST	1.00	\$12.90	10.00	\$11.61	Replace	Replace	√
		10371768	BRACKET-PARK DIST CONT SEN(BRACKET-PARK DIST	1.00	\$12.90	10.00	\$11.61	Replace	Replace	√
		10371766	BRACKET-PARK DIST CONT SEN(BRACKET-PARK DIST	1.00	\$13.20	10.00	\$11.88	Replace	Replace	√
		10326369	BRACKET-RR BPR FASCIA SI MTG - LH	0.00	\$46.08	0.00	\$0.00	Replace	Check	X
		10326371	BRACKET-RR BPR FASCIA SI MTG - RH	0.00	\$46.08	0.00	\$0.00	Replace	Check	X
		10465723	BRACKET ASM-RR BPR FASCIA SI-L	0.00	\$29.85	0.00	\$0.00	Replace	Check	X
		10465727	BRACKET ASM-RR BPR FASCIA SI-RH	0.00	\$29.85	0.00	\$0.00	Replace	Check	X
		10359002	FINISHER-RR BPR - LH	1.00	\$47.42	10.00	\$42.68	Replace	Replace	√
		10359003	FINISHER-RR BPR - RH	1.00	\$47.42	10.00	\$42.68	Replace	Replace	√
		10751490	FASCIA-RR BPR LWR	1.00	\$230.68	10.00	\$207.61	Replace	Replace	√
		10369261-SPRP	FASCIA-RR BPR	1.00	\$758.48	10.00	\$682.63	Replace	Replace	√
		10328380	MOTOR ASM-R/WDO WPR	0.00	\$208.52	0.00	\$0.00	Replace	Check	X
		10728270	MODULE ASM-WSW SYS	0.00	\$359.11	0.00	\$0.00	Replace	Check	X
			SEALANT W/SCREEN	2.00	\$37.00	0.00	\$74.00	Replace	Replace	√
		10964627	WINDOW ASM-RR	0.00	\$323.44	0.00	\$0.00	Replace	Check	X
			STICKER DECAL 65558888	1.00	\$21.60	0.00	\$21.60	Replace	Replace	√
			STRIDES LOGO	1.00	\$7.80	0.00	\$7.80	Replace	Replace	√
			NUMBER PLATE	1.00	\$35.00	0.00	\$35.00	Replace	Replace	√
		10562676	PLATE ASM-RR LIC PLT	0.00	\$96.40	0.00	\$0.00	Replace	Check	X
		10321485	WEATHERSTRIP-L/GATE	0.00	\$73.53	0.00	\$0.00	Replace	Check	X
		10896035	EMBLEM ASM-L/GATE (SW EV)	1.00	\$33.90	10.00	\$30.51	Replace	Replace	√
		10885560	EMBLEM ASM-L/GATE (MG5 SW)	1.00	\$21.84	10.00	\$19.66	Replace	Replace	√
		10935050	EMBLEM ASM-RR LIC PLT (MG)	1.00	\$62.92	10.00	\$56.63	Replace	Replace	√
		10328219-SEPP	TAIL GATE ASM-LIFT	1.00	\$1,928.26	10.00	\$1,735.43	Replace	Replace	√
		10103179	HINGE ASM-L/GATE - LH	0.00	\$30.89	0.00	\$0.00	Replace	Not Given	X
		10103178	HINGE ASM-L/GATE - RH	0.00	\$30.89	0.00	\$0.00	Replace	Not Given	X
		10444797	STRUT ASM-L/GATE - LH	0.00	\$52.52	0.00	\$0.00	Replace	Not Given	X
		10444798	STRUT ASM-L/GATE -RH	0.00	\$52.52	0.00	\$0.00	Replace	Not Given	X
		10294677	STRIKER ASM-L/GATE LAT	0.00	\$17.16	0.00	\$0.00	Replace	Check	X
		10606578	COVER-L/GATE LAT	0.00	\$6.86	0.00	\$0.00	Replace	Check	X
		10314527	LATCH ASM-L/GATE	0.00	\$139.36	0.00	\$0.00	Replace	Check	X

Strides Premier Accident Vehicle Repair Estimates

Strides Premier Automotive Services Pte Ltd
60 Woodlands Industrial Park E4, Singapore 757705
FAX Number : 63685592
Estimator Telephone Number : 68662623
Accident Reporting Number : 68662672

Date Generated : 24/07/2024

User ID : PohSuan

		10022051	SWITCH-L/GATE OPEN	0.00	\$30.68	0.00	\$0.00	Replace	Check	X
		10521906	PANEL ASM-L/GATE LWR TR	0.00	\$167.34	0.00	\$0.00	Replace	Check	X
		10431554	PANEL-L/GATE UPR TR	0.00	\$10.30	0.00	\$0.00	Replace	Check	X
			NUMBER PLATE FRAME	1.00	\$25.00	0.00	\$25.00	Replace	Replace	√
Total					\$8,994.22		\$3,226.72			

Added Spare Parts / Material Usage After Surveyor Signed off									
Part Number	Portion	Stock Number	Part Name	Quantity	List Price \$	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check
		10562676	PLATE ASM-RR LIC PLT	1.00	\$96.40	10.00	\$86.76	Replace	Replace
		10012107	LAMP ASM-RR LIC PLT	2.00	\$32.24	10.00	\$58.03	Replace	Replace
		10327894	BAR ASM-RR BPR IMP	1.00	\$339.77	10.00	\$305.79	Replace	Replace
		10395721-SEPP	PANEL ASM-RR END	1.00	\$708.66	10.00	\$637.79	Replace	Replace
Total					1,177.07		1,088.37		

4,315.09
+ 1200.00
+ 1270.00

6,785.09