






**PHOTOGRAPHS FOR VEHICLE NO. : SGA 5333T**



**PHOTOGRAPHS FOR VEHICLE NO. : SGA 5333T**



**PHOTOGRAPHS FOR VEHICLE NO. : SGA 5333T**



**PHOTOGRAPHS FOR VEHICLE NO. : SGA 5333T**




**PHOTOGRAPHS FOR VEHICLE NO. : SGA 5333T**



**PHOTOGRAPHS FOR VEHICLE NO. : SGA 5333T**



**PHOTOGRAPHS FOR VEHICLE NO. : SGA 5333T**




**PHOTOGRAPHS FOR VEHICLE NO. : SGA 5333T**



**PHOTOGRAPHS FOR VEHICLE NO. : SGA 5333T**



**PHOTOGRAPHS FOR VEHICLE NO. : SGA 5333T**



**PHOTOGRAPHS FOR VEHICLE NO. : SGA 5333T**



**PHOTOGRAPHS FOR VEHICLE NO. : SGA 5333T**



**PHOTOGRAPHS FOR VEHICLE NO. : SGA 5333T**




**PHOTOGRAPHS FOR VEHICLE NO. : SGA 5333T**



**PHOTOGRAPHS FOR VEHICLE NO. : SGA 5333T**



**PHOTOGRAPHS FOR VEHICLE NO. : SGA 5333T**



**PHOTOGRAPHS FOR VEHICLE NO. : SGA 5333T**



**PHOTOGRAPHS FOR VEHICLE NO. : SGA 5333T**




**PHOTOGRAPHS FOR VEHICLE NO. : SGA 533T**



**PHOTOGRAPHS FOR VEHICLE NO. : SGA 5333T**



**PHOTOGRAPHS FOR VEHICLE NO. : SGA 5333T**



**PHOTOGRAPHS FOR VEHICLE NO. : SGA 5333T**




**PHOTOGRAPHS FOR VEHICLE NO. : SGA 5333T**



**PHOTOGRAPHS FOR VEHICLE NO. : SGA 5333T**



**PHOTOGRAPHS FOR VEHICLE NO. : SGA 533T**



**PHOTOGRAPHS FOR VEHICLE NO. : SGA 5333T**



**PHOTOGRAPHS FOR VEHICLE NO. : SGA 5333T**



**PHOTOGRAPHS FOR VEHICLE NO. : SGA 5333T**



**PHOTOGRAPHS FOR VEHICLE NO. : SGA 533T**



**PHOTOGRAPHS FOR VEHICLE NO. : SGA 5333T**



**PHOTOGRAPHS FOR VEHICLE NO. : SGA 5333T**



**PHOTOGRAPHS FOR VEHICLE NO. : SGA 5333T**



**PHOTOGRAPHS FOR VEHICLE NO. : SGA 5333T**



**PHOTOGRAPHS FOR VEHICLE NO. : SGA 5333T**



**PHOTOGRAPHS FOR VEHICLE NO. : SGA 5333T**



**PHOTOGRAPHS FOR VEHICLE NO. : SGA 5333T**




**PHOTOGRAPHS FOR VEHICLE NO. : SGA 5333T**



**PHOTOGRAPHS FOR VEHICLE NO. : SGA 5333T**




**PHOTOGRAPHS FOR VEHICLE NO. : SGA 5333T**



**PHOTOGRAPHS FOR VEHICLE NO. : SGA 5333T**





**PHOTOGRAPHS FOR VEHICLE NO. : SGA 533T**




**PHOTOGRAPHS FOR VEHICLE NO. : SGA 5333T**



**PHOTOGRAPHS FOR VEHICLE NO. : SGA 5333T**



**PHOTOGRAPHS FOR VEHICLE NO. : SGA 5333T**



**PHOTOGRAPHS FOR VEHICLE NO. : SGA 5333T**



**PHOTOGRAPHS FOR VEHICLE NO. : SGA 533T**



**PHOTOGRAPHS FOR VEHICLE NO. : SGA 5333T**



**PHOTOGRAPHS FOR VEHICLE NO. : SGA 533T**



**PHOTOGRAPHS FOR VEHICLE NO. : SGA 5333T**





## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,  
Singapore 408933  
TEL: 6256 3561 FAX: 6256 4315  
Reg. No: 199607198R GST Reg. No.  
19-9607198-R

REINSPECTION PHOTOS (Page 50 of 54)

### PHOTOGRAPHS FOR VEHICLE NO. : SGA 5333T



**PHOTOGRAPHS FOR VEHICLE NO. : SGA 5333T**



**PHOTOGRAPHS FOR VEHICLE NO. : SGA 5333T**



**PHOTOGRAPHS FOR VEHICLE NO. : SGA 5333T**



**PHOTOGRAPHS FOR VEHICLE NO. : SGA 5333T**

