

ONE GARAGE PTE LTD

8 KAKI BUKIT AVENUE 4 #03-33 PREMIER@KAKI BUKIT
SINGAPORE 415875
TEL: 96311088

TO	: NTUC	DATE	: 16/7/2024
VEHICLE NO	: SNE6769J (2020)		
VEHICLE MODEL	: MERCEDES BENZ A200		Veron
CHASSIS NO	: W1K1771872J185342		

CLAIM DETAILS: PARTS

	ITEMS	QTY	UNIT PRICE	TOTAL
1	FRONT BUMPER <i>Ric</i>	1	\$ 1,341.00	\$ 1,341.00
2	FRONT BUMPER SIDE HOLDER <i>Clipped new</i>	2	\$ 96.00	\$ 192.00
TOTAL PRICE:				\$ 1,533.00
LESS 10%				\$ 153.30
SUB TOTAL PRICE:				\$ 1,379.70

SPECIAL NETT ITEMS

	ITEMS	QTY	UNIT PRICE	TOTAL
1	FRONT BUMPER CLIPS (SET) <i>New</i>	1	\$ 50.00	\$ 50.00
2	FRONT BUMPER LOWER GARNISH <i>Chipped</i>	1	\$ 1,000.00	\$ 1,000.00
TOTAL :				\$ 1,050.00

LABOUR

	JOB	PRICE	ADJUSTED COST	APPROVED
1	PANEL BEATING, REMOVE AND REFIT PARTS	\$ 400.00	<i>200</i>	
2	SPRAY PAINTING TO AFFECTED AREA	\$ 400.00	<i>200</i>	
3	WIRING CHECK	\$ 50.00	<i>X</i>	
4	TO REMOVE FRONT BUMPER SENSOR	\$ 100.00	<i>X</i>	
TOTAL:		\$ 950.00		

ESTIMATE REPORT

TOTAL PARTS COST: \$ 2,429.70

TOTAL LABOUR COST: \$ 950.00

TOTAL REPAIR COST: \$ 3,379.70

total: 1050
L/S: 800
02 Pags

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: