8/16/24, 5:15 PM Adjuster Report

# LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

### VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/MSG24070228/UVP3E2

**Date:** 16/08/2024

**REFERENCE** 

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd. Policy No: 30003109458

Claimant Vehicle FZ2530R Insured Vehicle No: SMK6971X

No: FZZSSUR INSURED VEHICLE NO . SIMROS/ TA

Date of Loss: 03/07/2024 Nature of Claim: TP Claim No: 365970

**DESCRIPTION & IDENTIFICATION OF VEHICLE** 

Reg No: FZ2530R

Make & Model: SUZUKI DRZ, 398cc 400SM (M) Engine No: K419141861

Reg. Date: 24/05/2005 (Man. Year: 2005) Chassis No: JS1B8111200101503

Colour: Black Odometer: 0 km

Engine Capacity: 398 cc Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

**CONDITION OF TYRES** 

Front Tyre Size: 120/70-17 Rear Tyre Size: 160/60-17
Front Left Side: Pirelli 5 mm Rear Left Side: Pirelli 5 mm
Front Right Side: 0 mm Rear Right Side: 0 mm

The above values represent the remaining tyre treads depth

| COST OF CLAIMS      | Repairer's | Adjuster's | Difference | Diff % |
|---------------------|------------|------------|------------|--------|
| Parts               | 0.00       | 0.00       | 0.00       |        |
| Miscellaneous Items | 0.00       | 0.00       | 0.00       |        |
| Labour              | 0.00       | 0.00       | 0.00       |        |
| Paintwork Labour    | 0.00       | 0.00       | 0.00       |        |
| Towing              | 0.00       | 0.00       | 0.00       |        |
| Nett Amount (S\$)   | 0.00       | 0.00       | 0.00       |        |

INSPECTION

Date of Assignment: 08/08/2024

Lightning Bike Pte Ltd (HQ)

Date Inspected: 14/08/2024 Inspected At: 257A Jalan Besar

257A Jalan Besar Singapore 208931

Estimated Period of Repair: 0.0 days

Adjuster: MARCUS CHUA Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

#### TOTAL LOSS ASPECT

MARKET VALUE: \$3,000.00 (EST)

LTA REBATE : \$ 418.00 NET VALUE : \$2,582.00 8/16/24, 5:15 PM Adjuster Report

### REPAIR DETAILS

Reference

Part Source: (Last Synchronised: 16 Aug 2024)

Parts: N/A SUZUKI DRZ 398cc 400SM (M) (Model not available in database)

Labour: Repairer's (Price-denominated Standard List)

**Print Code:** (Unsubmitted, no print-code for FZ2530R)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the

END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk \*.

### **Recommended Parts**

There are no new parts selected.

Report was unsubmitted during this print-out.

8/16/24, 5:15 PM Adjuster Report

# Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >