


HD Perfect Autowork Pte Ltd

Company Reg No: 202136904Z

8 Kaki Bukit Ave 4, #08-09 Premier@Kaki Bukit
Singapore 415875

Tel : 6341 6789 Fax: 6341 6778

E-mail: hdperfectautowork@gmail.com



HD PERFECT
AUTOWORK PTE LTD

DATE : 10.07.2024

TO : **AIG** MOTOR CLAIMS DEPTS
VEHICLE NO : **SJW8422Z**
MODEL : **TOYOTA VIOS**
DATE OF ACCIDENT : 09.07.2024
TIME OF ACCIDENT : 18:10 HOURS

WE APPEND HEREUNDER THE ESTIMATED COST OF REPAIRS TO BE CARRIED OUT TO THE ABOVE VEHICLE.

CLAIM DETAIL : PARTS

S/N	DESCRIPTION	QTY	UNIT LIST PRICE	TOTAL LIST PRICE
1	BOOT LID <i>Distorted</i>	1	\$ 575.00	\$ 575.00
2	BOOT LID LOGO <i>2</i>	1	\$ 70.00	\$ 70.00
3	BOOT LID EMBLEM 'VIOS' <i>new</i>	1	\$ 65.00	\$ 65.00
4	BOOT LID EMBLEM 'E'	1	\$ 55.00	\$ 55.00
5	BOOT LID OUTER MOULDING <i>new</i>	1	\$ 190.00	\$ 190.00
6	BOOT LID NUMBER PLATE LAMP <i>new</i>	2	\$ 42.00	\$ 84.00
7	BOOT LID TOP LOCK <i>new</i>	1	\$ 155.00	\$ 155.00
8	BOOT LID LOWER LOCK <i>new</i>	1	\$ 25.00	\$ 25.00
9	BOOT LID KEY LOCK <i>new</i>	1	\$ 225.00	\$ 225.00
10	BOOT LID WEATHER STRIP <i>lit</i>	1	\$ 205.00	\$ 205.00
11	BOOT LID HINGE <i>new</i>	2	\$ 70.00	\$ 140.00
12	REAR BUMPER <i>Distorted</i>	1	\$ 495.00	\$ 495.00
13	REAR BUMPER REFLECTOR <i>RH cracked</i>	2	\$ 105.00	\$ 210.00
14	REAR BUMPER BRACKET <i>new</i>	2	\$ 89.00	\$ 178.00
15	REAR BUMPER SIDE RETAINER (FRONT) <i>2HP</i>	2	\$ 105.00	\$ 210.00
16	REAR BUMPER SIDE RETAINER (REAR) <i>1HP</i>	2	\$ 55.00	\$ 110.00
17	TAIL LAMP <i>RH cracked</i>	2	\$ 345.00	\$ 690.00
18	REAR FENDER INNER COWLING <i>new</i>	2	\$ 175.00	\$ 350.00
19	REAR FENDER INNER TRIM <i>new</i>	2	\$ 295.00	\$ 590.00
20	REAR CHASSIS MEMBER RH <i>Repis</i>	1	\$ 694.30	\$ 694.30
21	REAR END PANEL <i>Distorted</i>	1	\$ 439.00	\$ 439.00

TO : AIG MOTOR CLAIMS DEPTS
 VEHICLE NO : SJW8422Z
 MODEL : TOYOTA VIOS
 DATE OF ACCIDENT : 09.07.2024
 TIME OF ACCIDENT : 18:10 HOURS

22	REAR END PANEL TOP GARNISH <i>Delid</i>	1	\$	230.00	\$	230.00	✓
23	REAR FLOOR PANEL TOP BOARD <i>new</i>	1	\$	175.00	\$	175.00	✓
24	REAR FLOOR PANEL TOP SPONGE (SIDE) <i>new</i>	2	\$	275.00	\$	550.00	275
25	REAR EXHAUST MOUNTING <i>new</i>	4	\$	45.00	\$	180.00	+
26	REAR EXHAUST GASKET (SET) <i>new</i>	1	\$	60.00	\$	60.00	+
27	REAR EXHAUST INSULATOR <i>new</i>	1	\$	89.00	\$	89.00	+
28	REAR EXHAUST PIPE WITH BOX <i>new</i>	1	\$	690.00	\$	690.00	+

TOTAL PRICE \$ 7,729.30
 LESS 25% \$ 1,932.33
 SUB TOTAL PRICE \$ 5,796.98

S/N	DESCRIPTION	QTY	UNIT S/NETT	TOTAL S/NETT
1	REAR NUMBER PLATE <i>new</i>	1	\$ 50.00	\$ 50.00
2	REAR BUMPER CLIPS (SET) <i>new</i>	1	\$ 50.00	\$ 50.00
3	BOOT LID OUTER MOULDING CLIP (SET) <i>new</i>	1	\$ 30.00	\$ 30.00
4	REAR FENDER SEALANT <i>new</i>	2	\$ 150.00	\$ 300.00
5	REAR FENDER INNER COWLING CLIPS (SET) <i>new</i>	1	\$ 80.00	\$ 80.00
6	REAR FENDER INNER TRIM CLIPS (SET) <i>new</i>	1	\$ 80.00	\$ 80.00
7	TAIL LAMP CLIPS (SET) <i>new</i>	1	\$ 30.00	\$ 30.00
8	REAR END PANEL TOP GARNISH CLIPS (SET) <i>new</i>	1	\$ 30.00	\$ 30.00
9	REAR END PANEL INSULATION SEAL <i>new</i>	1	\$ 150.00	\$ 150.00
10	REAR EXHAUST CHROME PIPE (SPECIAL TYPE) <i>Delid</i>	1	\$ 250.00	\$ 250.00
11	REVERSE CAMERA <i>new</i>	1	\$ 450.00	\$ 450.00
12	REVERSE SENSOR <i>Delid</i>	1	\$ 220.00	\$ 220.00

TOTAL \$ 1,720.00

CLAIM DETAILS: LABOUR AND SPRAY PAINTING

S/N	JOB DESCRIPTION	PRICE	ADJUSTED COST
1	TO PANEL BEAT, WELD, CUT, KNOCK, GRAZE, ADJUST, REPLACE NEW PARTS	\$ 1,800.00	700
2	TO PUTTY, SPRAY PAINT, POLISH, WAX ADJACENT PANELS	\$ 1,600.00	600
3	TUFF COAT	\$ 250.00	60

TO : **AIG** MOTOR CLAIMS DEPTS
 VEHICLE NO : **SJW8422Z**
 MODEL : **TOYOTA VIOS**
 DATE OF ACCIDENT : 09.07.2024
 TIME OF ACCIDENT : 18:10 HOURS

4	WIRING/ BULB CHECKING	\$ 80.00	30
5	REMOVE AND REFIX CUSHION SEAT/ UPHOLSTRY AND ROOF LINNING TO FACILITATE REPAIR	\$ 200.00	60
6	REMOVE AND REFIX REVERSE SENSOR AND DISTANCE SETTING	\$ 80.00	50
7	REMOVE AND REFIX REVERSE CAMERA AND DISTANCE SETTING	\$ 80.00	50
8	REMOVE AND REFIX REAR EXHAUST	\$ 180.00	X
9	TRANSFER BOOT LID MECHANISM	\$ 80.00	60
10	TO CONDUCT WATER LEAKAGE TEST	\$ 80.00	X
11	REAR CHASSIS MEMBER ALIGNMENT	\$ 250.00	X
12	TO CHECK DIAGNOSTICS OF VEHICLE MANAGEMENT/CONTROL UNITS, RESET MEMORIES TO SPECIFICATION ETC.	\$ 180.00	X

TOTAL \$ 4,860.00

ESTIMATE REPORT

TOTAL PARTS COST : \$ 7,516.98
 TOTAL LABOUR COST : \$ 4,860.00
 TOTAL REPAIR COST : \$ 12,376.98

Adrian G
2/s 11/07/24.
0629p

NB: THIS IS ONLY AN ESTIMATE AND SHOULD ADDITIONAL WORK BE FOUND NECESSARY TO BE CARRIED OUT IN THE COURSE OF REPAIRS, EXTRA MATERIALS AND LABOUR COST WILL BE CHARGED ACCORDINGLY WHICH HOWEVER, YOU WILL BE INFORMED PRIOR TO ACTION TAKEN.

PARTS PRICES ARE SUBJECT TO CHANGES.

YOURS FAITHFULLY,

IRENE

SERVICE ADVISOR
 IRENE
 HP : 8297 9787

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: