



205 Braddell Road S(579701)

ACCIDENT REPAIR ESTIMATES

Our Ref:

Type of Claim : TP(MSFC)Vehicle No. : SNE4096EMake & Model : TOYOTA NOAHYear of Manufacture : 2021Chassis No. : ZWR800523639Engine No. : 2ZR2P15329Ins Company : III

Policy No. : _____

Excess : _____

Date of Accident : 7/7/2024

Time of Accident : _____

Suggested Days of Repair : _____

In-house Vehicle Assessor**Repair Estimates**Case Owner : KELVIN

Signature : _____

Parts (a) Cost / List Price Items \$ 865.00Plus/Less 25% \$ 216.25Total of Cost / List \$ 648.75

(b) Nett Price Items _____

Less _____

Total of Nett Item _____

(c) Special Nett Items \$ -Total Parts Cost (Appendix A) \$ 648.75Labour (Appendix B) \$ 750.00Total Repair Cost \$ 1,398.75**Operation**

KELVIN SU

TEL: 9786 4236

E: kelvinsukwen@cdge.com.sg

SUN PIN

TEL: 9728 8916

E: oisunpin@cdge.com.sg

*NOT authorized
Recovery B4 pricing*

The above total will be subjected to 9% G.S.T.

Name of Surveyor : KennethCompany : CLICSurvey conducted on : 15/7/24 at _____**Remarks By Surveyor**(a) The repair of this vehicle is not authorized / is not authorized until further notice.(b) Recommended Days of Repair : 02 day(s)(c) Resurvey : Required / Not Required

(d) Excess : \$ _____

(e) Signature of surveyor : De Date: 15/7/24

Spark Car Care

ComfortDelGro Engineering Pte Ltd
205 Braddell Road S (579701)
Tel: 63837168 / 63837466 Fax: 62815767

Spare Parts

Vehicle No : SNE4096E Case Owner : KELVIN

Make & Model : TOYOTA NOAH Year Manufacture : 2021

Chassis No : ZWR800523639 Engine No : 2ZR2P15329

Sales Order : _____ Supplier : _____

Order By : KELVIN Type of Claim : TP(MSFC)

S/No	DESCRIPTION	QTY	Cost Price	List Price	S/N	Disposition By Surveyor
1	REAR BUMPER	1	<i>810</i>	\$ 810.00		<input checked="" type="checkbox"/>
2	REAR BUMPER CLIPS	10	<i>55</i>	\$ 55.00	<i>SN</i>	<input checked="" type="checkbox"/>
3						
4						
5						
6						
7						
8						
9						
10						
11						
12						
13						
14						
15						
16						
17						
18						
19						
20						
21						
22						
23						
24						
25						
26						
27						
28						
29						
30						

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "without prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature: _____

Date: _____

Note: If any of the quoted parts are recommended to be repaired, then an additional labour charge will be charged accordingly under supplementary.

ComfortDelGro Engineering Pte Ltd
205 Braddell Road S (579701)
Tel: 63837168 / 63837466 Fax: 62815767

Vehicle No.	: <u>SNE4096E</u>	Case Owner	: <u>KELVIN</u>
Make & Model	: <u>TOYOTA NOAH</u>	Year of Manufacture	: <u>2021</u>

Note: The above estimate of repair is based on visual assessment of the external affected areas. Any additional damages observed during the course of repair will be quote accordingly as a supplementary.