

205 Braddell Road S(579701)

ACCIDENT REPAIR ESTIMATES

Our Ref:	
Type of Claim (TP(MSFC)	Vehicle No. SNE4096E
Transition of the state of the	Make & Model TOYOTA NOAH
	Year of Manufacture 2 2021
	Chassis No. ZWR800523639
Ins Company III	Engine No. 2ZR2P15329
Excess	Policy No.
Date of Accident	Time of Accident
Suggested Days of Repair :	In-house Vehicle Assessor
Repair Estimates	Case Owner KELVIN
	Signature :
Parts (a) Cost / List Price Items \$865.00	
Plus/Less25% \$ 216.25	
Total of Cost / List \$ 648.75	Operation
(b) Nett Price Items	KELVIN SU TEL: 9786 4236
Less	E: kelvinsukwen@cdge.com.sg
Total of Nett Item	SUN PIN TEL: 9728 8916
	E: oisunpin@cdge.com.sg
(-)	
Total Parts Cost (Appendix A) \$ 648.75	
Labour (Appendix B) \$ 750.00	
Total Repair Cost \$ 1,398.75	
The above total will be subjected to 9% G.S.T.	
1	
	atat
- Larvey confedered on	
Remarks By Surveyor	
(a) The repair of this vehicle is authorized / is not at	uthorized until further notice.
(b) Recommended Days of Repair	day(s)
(c) Resurvey : Required / N	lot Required
(d) Excess :\$	
(a) Signature of surveyor	Date:

VACCIDENT REPAIR ESTIMATES/F3

Spark Car Care

ComfortDelGro Engineering Pte Ltd

205 Braddell Road S (579701) Tel: 63837168 / 63837466 Fax:62815767

Spare Parts

Vehicle No	SNE4096E	Case Owner :	KELVIN
Make & Model	: TOYOTA NOAH	Year Manufacture :	2021
Chassis No	ZWR800523639	Engine No :	2ZR2P15329
Sales Order		Supplier :	·
Order By	: KELVIN	Type of Claim:	TP(MSFC)

		_				D
S/No	DESCRIPTION	QTY	Cost Price	List Price	S/N	Disposition By Surveyor
1	REAR BUMPER	1		\$ 810.00		
	REAR BUMPER CLIPS	10		\$ 55.00		
3						
4						
5						
6						
7						
8						
9						
10						
11						
12						
13						
14						
15						
16						
17						
18						
19						
20						
21						
22						
23						
24						
25				4		
26						
27						
28						
29						
30						

Note: If any of the quoted parts are recommended to be repaired, then an additional labour charge will be charged accordingly under supplementary.

Spark Car Care

ComfortDelGro Engineering Pte Ltd

205 Braddell Road S (579701) Tel: 63837168 / 63837466 Fax: 62815767

Labour

Vehicle No.	:	SNE4096E	Case Owner		KELVIN
Make & Model	:	TOYOTA NOAH	Year of Manufacture	:	2021

S/No	Labour Description		simated Price	Adjusted Price
	TO KNOCK & STRAIGHTEN ON ACCIDENT AREA, TO REMOVE &	\$	250.00	
	REFIT DAMAGE PARTS	_		
2	TO PUTTY,RESPRAY ON REAR BUMPER,REAR TAILGATE,	\$	500.00	
_	AFFECTED AREA			
		-		
		_		

Note: The above estimate of repair is based on visual assessment of the external affected areas. Any additional damages observed during the course of repair will be quote accordingly as a supplementary.