


SMRT Accident Vehicle Repair Estimates

SMRT Automotive Services Pte Ltd
60 Woodlands Industrial Park E4, Singapore 757705
FAX Number : 63685592
Estimator Telephone Number : 68662623
Accident Reporting Number : 68662672

Date Generated : 15/07/2024

User ID : munsan

Section A - Accident Details	
Registration Number	SHB5931A
Case Reference Number	TAX/07/24/2042
Registration Date	12/12/19
Company Type	Strides Premier Taxi Pte Ltd
Make	TOYOTA
Model	PRIUS4FL
Name of Driver	NG CHENG SEE
Type of Accident	Head to Rear
Accident Date and Time	12/7/24 9:40 PM
Accident Reported Date and Time	13/7/24 9:34 AM
Is Surveyor Required?	No
Survey by	
Vehicle is Towed Back?	No
Towed Back Date and Time	
Replacement Vehicle issued?	No
Job Card Number	24121827
Special Instruction to ARC,if any	TP/FRONT PORTION
Prepared Date and Time	15/7/24 9:25 AM
Chassis Number	
Mileage	
Work Shop	
Repair Completion Date and Time	

Section B - Summary of Repair Estimates		
Summary of Repair Estimates		
	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Cost	\$676.00	\$0.00
Total Spray Cost	\$976.00	\$0.00
Total Spare Part Cost	\$6,018.21	\$0.00
Total Other Cost	\$380.00	\$0.00
TOTAL COST	\$8,050.21	\$0.00
Lump Sum Total	\$8,050.00	\$0.00
Number of Repair Days	5.0	
Prepared / Adjusted By	Boon Chew Tay	
ARC / Surveyor Sign Off Date	15/07/2024 9:38 AM	
Signature		<div><div>✖</div><div>Steve (LKK) 15/07/24, 4.30pm Without Prejudice</div></div>
Remarks		<div>L/S Resurvey After Spray 2 days</div>

Section C - Quotation and Accident Invoice Details			
Quotation Number		Invoice Number	
Quotation Date		Invoice Date	
Invoice Amount		Prepared Date	

LKK Auto Consultants hence notify the Repairer of the following:

• To resurvey before/after spray painting

• To display damaged part(s) during resurvey

• Parts prices are subject to confirmation

• Third party survey is on a "Without Prejudice" basis

• No illegal modification(s) is allowed

• Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

SMRT Accident Vehicle Repair Estimates

SMRT Automotive Services Pte Ltd
60 Woodlands Industrial Park E4, Singapore 757705
FAX Number : 63685592
Estimator Telephone Number : 68662623
Accident Reporting Number : 68662672

Date Generated : 15/07/2024

User ID : munsan

Section D - Details of Repair Estimates									
Part 1 - Labour Works									
Job Scope			Quotation from AR				Adjusted by Surveyor, if applicable		
TO REPAIR FRONT PORTION			\$676.00				200		
Total Labour			\$676.00						
Part 2 - Spray Painting & Panel Beating Related Works									
Job Scope			Quotation from ARC				Adjusted by Surveyor, if applicable		
TO RESPRAY FRONT BUMPER			\$378.00				200		
TO RESPRAY FRONT HOOD			\$378.00				x		
TO RESPRAY FRONT SUPPORT PANEL			\$220.00				x		
Total Spray Painting & Panel Beating			\$976.00						
Part 3 - Other Costs - Accident and Accident Repair Related Expense									
Job Scope			Quotation from ARC				Adjusted by Surveyor, if applicable		
TO WASH AND VACUUM			\$60.00				x      nn		
TO CHECK WIRING AND SYSTEM FUNCTION			\$120.00				30    nec		
TO APPLY RUST-PROOFING ON AFFECTED AREA			\$100.00				x      nn		
TO REPLACE SUNDRY PARTS			\$100.00				x      nn		
Total Other Costs			\$380.00						
Part 4 - Spare Parts / Material Usage									
Part Number	Portion	Stock Number	Part Name	Quantity	List Price (\$)	Discount (%)	Final Price (\$)	Estimator Approved	Surveyor Approved
		52119-47980	COVER, FR BUMPER	1.00	\$565.60	25.00	\$424.20	Replace	x R
		52115-47050	SUPPORT, FR BUMPER RH	1.00	\$86.20	25.00	\$64.65	Replace	x nn
		52116-47050	SUPPORT, FR BUMPER LH	1.00	\$86.20	25.00	\$64.65	Replace	x nn
		52114-47270	BRACKET, FR BUMPER	1.00	\$119.90	25.00	\$89.93	Replace	/ BR
			NUMBER PLATE FRAME	1.00	\$25.00	0.00	\$25.00	Replace	/ BR
			NUMBER PLATE	1.00	\$35.00	0.00	\$35.00	Replace	/ BR
		53112-47310	GRILLE, RADIATOR	1.00	\$192.80	25.00	\$144.60	Replace	x nn
		53101-47100	GRILLE SUB-ASSY	1.00	\$457.10	25.00	\$342.83	Replace	x nn
		75310-33050	EMBLEM ASSY FRONT	1.00	\$114.30	25.00	\$85.73	Replace	/ BR
		53111-47140	GRILLE, SUB -ASSY , 2	1.00	\$170.20	25.00	\$127.65	Replace	x nn
		52161-16010	CLIPS PIECE, FRT BUMPER	10.00	\$4.80	25.00	\$36.00	Replace	x nn
		52712-47040	MOULDING, FRONT BUMPER SIDE, RH	1.00	\$103.70	25.00	\$77.78	Replace	x nn
		52713-47040	MOULDING, FRONT BUMPER SIDE, LH	1.00	\$103.70	25.00	\$77.78	Replace	x nn
		52618-47130	ABSORBER, FR BUMPER LOWER	1.00	\$143.60	25.00	\$107.70	Replace	x nn
		52611-47210	ABSORBER, FR BUMPER	1.00	\$86.60	25.00	\$64.95	Replace	x nn
		52021-47110	REINFORCEMENT FRONT UPPER	1.00	\$773.90	25.00	\$580.43	Replace	x nn
		81185-47890	UNIT , HEADLAMP , LH	1.00	\$2,852.40	25.00	\$2,139.30	Replace	x nn
		81145-47890	UNIT , HEADLAMP , RH	1.00	\$2,852.40	25.00	\$2,139.30	Replace	x nn
		53301-47110	HOOD SUB-ASSY	1.00	\$1,066.30	25.00	\$799.72	Replace	x nn
		53410-47130	HINGE ASSY, HOOD, RH	1.00	\$63.70	25.00	\$47.78	Replace	x nn
		53420-47130	HINGE ASSY, HOOD, LH	1.00	\$63.70	25.00	\$47.78	Replace	x nn
		53205-47900	SUPPORT S/A UPPER,	1.00	\$408.50	25.00	\$306.38	Replace	x nn
Total					\$10,375.60		\$7,829.14		
Added Spare Parts / Material Usage After Surveyor Signed off									

SMRT Accident Vehicle Repair Estimates

SMRT Automotive Services Pte Ltd
60 Woodlands Industrial Park E4, Singapore 757705
FAX Number : 63685592
Estimator Telephone Number : 68662623
Accident Reporting Number : 68662672

Date Generated : 15/07/2024

User ID : munsan

Part Number	Portion	Stock Number	Part Name	Quantity	List Price \$	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check
Total									