



# QUOTATION

CODE: L0002  
CUSTOMER: LONPAC INSURANCE BHD  
ADDRESS: 300 BEACH ROAD  
#17-04/07 THE CONCOURSE  
SINGAPORE 199555

PAGE NO.: 1  
DOCUMENT NO.: 1229  
DOCUMENT DATE: 11/06/2024  
POS ID: MU  
PRINTED BY: Lee Yao Sheng  
SERVICE ADV:  
CSP/OP CODE: Lee Yao Sheng  
DEPT: 1  
WIP NO.: 14300  
REF. NO.:  
DATE IN: 18/12/2023  
EXT. WTY: 0  
MILEAGE:

CONTACT NO.: 6250 7388 *sterechen@lkkauto.com*  
MODEL: MAZDA3 1.5L SDN DELUXE BLACK L  
CHASSIS NO.: JM6BN22A8K0265147  
ENGINE NO.: P520566283  
REG NO.: SLL4040C *Stev (LKK)*  
REGN DATE: 19/12/2018 *20/6/24 12.11pm*

## DESCRIPTION:

| Item         | Description                                                      | Qty. | Unit Price | Stk/Status | Gross amount | GST Code   |
|--------------|------------------------------------------------------------------|------|------------|------------|--------------|------------|
|              |                                                                  |      | SGD        |            | SGD          |            |
| NOTES        | LONPAC TP CLAIM                                                  |      |            |            | 0.00         | O          |
| SUB          | TO REMOVE & REPLACE REAR BUMPER. AND ALL ACCIDENT AFFECTED AREA. |      |            | 792        | 1,584.00     | S          |
| SUB          | TO RESPRAY REAR BUMPER & REINFORCEMENT.                          |      |            | 756        | 2,835.00     | S          |
| SUB          | TO TRANSFER REVERSE SENSORS.                                     |      |            | 180        | 330.00       | S          |
| SUB          | TO CHECK ELECTRICAL SYSTEM FOR PROPER FUNCTIONING.               |      |            | 180        | 250.00       | S          |
| SUB          | TO REPROGRAMME AFTER THE ACCIDENT REPAIR WORKS.                  |      |            | 180        | 300.00       | S          |
| SUB          | SUNDRIES.                                                        |      |            |            |              |            |
| BFYD-50-221  | REAR BUMPER BM/BN W/SENSOR                                       | 1.00 | 1,143.51   | *NO STOCK  | 20           | 50.00 S    |
| B45A-56-146A | FASTENER                                                         | 4.00 | 2.36       | STOCK      |              | 1,143.51 S |
| BBM4-50-355  | RIVET                                                            | 4.00 | 3.71       | STOCK      |              | 9.44 S     |
| BHN1-50-0Z1A | GROMMET, SCREW                                                   | 4.00 | 2.36       | *NO STOCK  |              | 14.84 S    |
| BCKA-50-EM1  | TAPE, PROTECTOR                                                  | 3.00 | 7.42       | *NO STOCK  |              | 9.44 S     |
| B45A-50-260  | REINFORMENT REAR BM                                              | 1.00 | 576.77     | STOCK      |              | 22.26 S    |
| BHN1-51-153  | GASKET(R), RR.COMB. BM/BN                                        | 1.00 | 26.47      | STOCK      |              | 576.77 S   |
| BHN1-51-163  | GASKET(L), RR.COMB. BM/BN                                        | 1.00 | 26.47      | STOCK      |              | 26.47 S    |

|           | GST Code | Rate  | Service/Goods | GST    |
|-----------|----------|-------|---------------|--------|
| Parts     | O        | -     |               | -      |
| Surcharge | S        | 9.00% | 7,178.20      | 646.04 |
| Labour    |          |       |               |        |
| Menus     |          |       |               |        |

\*This is only an estimate from our visual inspection and should there be more damages found during the process of works you will then be informed for your approval before proceeding with the repairs.

\*Take note that should you decide not to proceed with the repairs "a service quotation fee" with a minimum of \$180.00 will be applied and it will varies depending on the time unit that was taken for the checking and diagnosis of your vehicle.

|                 | Before GST | GST    | Total    |
|-----------------|------------|--------|----------|
| Gross           | 7,178.20   | 646.04 | 7,824.24 |
| Less: Deposit** | 0.00       | 0.00   | 0.00     |
| Amount Due      | 7,178.20   | 646.04 | 7,824.24 |

\*\*Deposit tax invoice No.:

CASH / NETS / AMEX / VISA / MASTER / CHEQUE  
No.

Date:

Customer signature



Corporate Head Office : Trans Eurokars Pte Ltd, 11 Kung Chong Road Singapore 155  
Tel: 6363 3003, Fax: 63693003, BRN.199103859N, GST

**zoom-zoom**

Showrooms & Service Centres :

5 Ubi Close Singapore 408605  
Sales Tel: 6395 8888 Service Tel: 6395 8899  
Sales Fax: 68461700 Service Fax: 6744 9402

23 Leng Kee Road Singapore 15909  
Sales Tel: 6603 6118 Service Tel: 6  
Sales Fax: 6476 7073 Service Fax:

**LKK Auto Consultants** hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: