

ASS. REC. BY:

PARTY

CD/CT124070237/Dua³

ASSIGNMENT

COR 04/12/2027

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value:

IDAC Accident Report

Consistent?: Yes or No

GIA / PR Seen:

Consistent?: Yes or No

Est. Repair:

68 days

Res.: Yes or No

Lump Sum:

20 %

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date:

Person Contacted:

Veh No:

STC 83808G

Yr Regn:

05/12/2019

Type: M/Car / M/Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Toyota Prius

C.C. 1798

Colour:

Blue

A/C: Insured / Std / NI / NA

Sp. Reading

T/Radio: Insured / Std / NI / NA

Eng/No:

22RLTA2302313

C/No:

JTDKB3FU303089043

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

195/65 219

R:

11

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Westlake

Front

Rear

R/Bal.

5

mm

R/Bal.

5

mm

L/Bal.

5

mm

L/Bal.

5

mm

D.O.A.

14/07/2024

D.O.I.

16/07/2024

Survey held at

Highpost

Layang

Des. of Damages: Frt / Rear / O/S / N/S / W/C / Rooftop or

Rear

The W/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

China Taping PC7496B

04/11/24 Taping 215 57501- with 6 days of my

Date/Time, File Pass to?



Prel. Report

1



Final Report

Date/Time, File Return to?

2

Report Format:

Lump Sum / L.B.I. (\$

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

S-RS-SI

Photos

Others

TOTAL

Add Fee:



Site Insp (\$



Interview (\$



Tech. Invs (\$



Weekend (\$

12634

11773B

BIFROST AUTO PTE LTD

REPAIR ESTIMATE

DATE: 15-Jul-24

INSURANCE: China Taping

MODEL: TOYOTA PRIUS G5

VEHICLE NO.: SHC 3808 G

DESCRIPTION	QTY	LIST PRICE	AMOUNT
REAR TRUNK LID COVER <i>St</i>	1	\$ 1,577.24	\$1,577.24
REAR TRUNK LID LOCK <i>Dm</i>	1	\$ 641.06	\$641.06
REAR TRUNK LID LOCK COVER <i>HH</i>	1	\$ 129.80	\$129.80
REAR TRUNK LID LOCK SWITCH <i>HH</i>	1	\$ 468.90	\$468.90
REAR TRUNK LID COVER TRIM BOARD <i>HH</i>	1	\$ 303.10	\$303.10
REAR TRUNK LID RUBBER <i>original</i>	1	\$ 511.28	\$511.28
REAR TRUNK LID LAMP G5 <i>HH</i>	1	\$ 891.52	\$891.52
REAR TRUNK LID GLASS (BLACK COLOR) <i>HH</i>	1	\$ 2,197.58	\$2,197.58
BOARD ASSY, BACK DOOR TRIM <i>HH 1054.71</i>	1	\$ 356.16	\$356.16
GARNISH SUB-ASSY, BACK DOOR, OUTSIDE <i>cut/crank</i>	1	\$ 1,845.58	\$1,845.58
REAR TRUNK LID LOGO (PRIUS) <i>Hec</i>	1	\$ 85.12	\$85.12
REAR TRUNK LID LOGO (HYBRID) <i>Hec</i>	1	\$ 73.36	\$73.36
REAR TRUNK LID LOGO (TOYOTA STAR) <i>Hec</i>	1	\$ 74.06	\$74.06
THIRD BRAKE LIGHT <i>HH</i>	1	\$ 552.58	\$552.58
REAR TRUNK LID STRIKER <i>HH</i>	1	\$ 138.18	\$138.18
REAR TRUNK LID HINGE (LH/RH) <i>HH</i>	2	\$ 265.30	\$530.60
REAR TRUNK LID ABSORBER (LH/RH) <i>HH</i>	2	\$ 402.50	\$805.00
REAR TRUNK LID ABSORBER BRACKET (LH/RH) <i>HH</i>	2	\$ 179.06	\$358.12
REAR TRUNK LID STOPPER (LH/RH) <i>HH</i>	2	\$ 118.72	\$237.44
SPOILERSUB-ASSY, REAR <i>HH</i>	1	\$ 1,335.18	\$1,335.18
REAR BUMPER <i>broken</i>	1	\$ 642.04	\$642.04
REAR BUMPER RE-INFORCEMENT <i>Reinforced</i>	1	\$ 446.32	\$446.32
REAR BUMPER UNDER COVER <i>HH</i>	1	\$ 773.64	\$773.64
REAR BUMPER SIDE RETAINER <i>HH</i>	2	\$ 157.78	\$315.56

REAR BUMPER UNDER CENTRE COVER <i>damaged</i>	1	\$ 773.64	\$773.64	✓
REAR BUMPER TOWING COVER <i>minorly damaged</i>	1	\$ 115.78	\$115.78	✓
REAR BUMPER CLIPS <i>HL</i>	1	\$ 30.80	\$30.80	✓
REAR BUMPER SIDE CLIP <i>HL</i>	2	\$ 35.00	\$70.00	X
REAR BUMPER UPPER STOPPER <i>HL</i>	2	\$ 106.96	\$213.92	X
ARM SUB-ASSY, REAR BUMPER, RH <i>HL</i>	1	\$ 195.44	\$195.44	X
REAR BUMPER UNDER SIDE COVER (RH) <i>HL</i>	1	\$ 324.80	\$324.80	X
RETAINER, REAR BUMPER, SIDE, RH <i>HL</i>	1	\$ 132.72	\$132.72	X
RETAINER, REAR BUMPER, UPPER SIDE (LH/RH) <i>HL</i>	2	\$ 42.98	\$85.96	X
RETAINER, REAR BUMPER, SIDE, LH <i>HL</i>	1	\$ 132.72	\$132.72	X
REAR BUMPER UNDER SIDE COVER (LH) <i>HL</i>	1	\$ 324.80	\$324.80	X
ARM SUB-ASSY, REAR BUMPER, LH <i>HL</i>	1	\$ 195.44	\$195.44	X
REAR BUMPER LOWER COVER GARNISH G5 <i>broken</i>	1	\$ 963.63	\$963.63	✓
TAIL LAMP ASSY (UPPER) G5 <i>HL</i>	2	\$ 942.90	\$1,885.80	X
TAIL LAMP ASSY (LOWER) G5 <i>HL</i>	2	\$ 860.58	\$1,721.16	X
TAIL LAMP QUARTER PANEL <i>HL</i>	2	\$ 302.40	\$604.80	X
REAR END PANEL GARNISH COVER <i>HL</i>	1	\$ 138.90	\$138.90	X
TAIL LAMP SIDE COVER <i>HL</i>	2	\$ 358.40	\$716.80	X
REAR END PANEL <i>HL</i>	1	\$ 842.94	\$842.94	X
REAR END PANEL GARNISH <i>HL</i>	1	\$ 294.80	\$294.80	X
REAR SPARE TYRE PANEL <i>HL</i>	1	\$ 960.80	\$960.80	X
REAR SPARE TYRE CUSHION (FLR BOARD CENTRE) <i>HL</i>	1	\$ 668.90	\$668.90	X
REAR FIBER TOOL BOX TRIM <i>HL</i>	1	\$ 557.20	\$557.20	X
SPARE TYRE LOCK NUT <i>HL</i>	1	\$ 123.76	\$123.76	X
REAR EXHAUST PIPE RH <i>HL</i>	1	\$ 1,628.76	\$1,628.76	X
REAR EXHAUST PIPE HANGER <i>HL</i>	1	\$ 56.98	\$56.98	X
REAR EXHAUST PIPE INSULATOR <i>HL</i>	1	\$ 440.44	\$440.44	X
REAR WINDSCREEN GLASS W/ MOULDING <i>HL</i>	1	\$ 2,489.62	\$2,489.62	X
REAR WINDSCREEN SEALANT <i>HL</i>	1	\$ 64.40	\$64.40	✓
SUB TOTAL <i>7,053.44</i>			\$32,045.13	
LESS 20% <i>25%</i> <i>5,290.08</i>			\$6,409.03	
DISCOUNTED TOTAL			\$25,636.10	

REAR TRUNK LOWER W/S MOULDING <i>HH</i>	SN	1	\$180.00	\$180.00	X
REAR LOWER W/S SEALANT <i>HH</i>	SN	1	\$46.00	\$46.00	✓
REAR NO. PLATE WITH TRIM COVER <i>HH</i>	SN	1	\$ 140.00	\$140.00	X
REAR TRUNK LID APPS STICKER <i>HH</i>	SN	1	\$ 56.00	\$56.00	✓
REAR TRUNK LID COMFORT & TEL NO. STICKER <i>HH</i>	SN	1	\$ 84.00	\$84.00	✓
REAR BUMPER REVERSE SENSOR <i>840 Dan</i>	SN	1	\$ 189.98	\$189.98	X ✓
REAR BUMPER RUBBER MAT <i>HH</i>	SN	1	\$ 70.00	\$70.00	✓ 50/-
SUB TOTAL				\$765.98	
Labour Charge					
Panel Beating		1	\$ 2,000.00	\$2,000.00	600/-
Spray Painting Charge		1	\$ 1,600.00	\$1,600.00	700/-
Wiring Charge		1	\$ 100.00	\$100.00	HH
Tuff Kote		1	\$ 100.00	\$100.00	20/-
Towing Charge		1	\$ 80.00	\$80.00	HH
Remove/Refix Cushion & Upholstery Rear		1	\$ 150.00	\$150.00	80/-
Remove/Refix Rear Windscreen Glass		2	\$ 120.00	\$240.00	80/-
Remove/Refix Exhaust Pipe		1	\$ 80.00	\$80.00	HH
Diagnostic & Resetting To Erase Fault Code		1	\$ 550.00	\$550.00	HH
TOTAL LABOUR				\$4,900.00	
ESTIMATE TOTAL				\$31,302.08	
prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.					

16/07/2024 @ 1030w

7,196.06

N/A Andrew

4/s 5,750

2/5mm

6 days

1 ym

LKK Auto

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer