



ZOOM AUTOWERKS PTE LTD

130 Bedok Reservoir Road

#08-1339 Singapore 470130

Tel: 9450 7920

* zoomautowerks@gmail.com

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

29 July 2024

REG NO. : SKU 8804 D
MAKE/MODEL : PEUGEOT 3008

Acknowledged by Repairer
Signature:
Date:

ESTIMATED REPAIR COST FOR THE VEHICLE MENTIONED ABOVE

QTY	DESCRIPTION	AMT(\$)
<u>LIST ITEMS</u>		
1	Rear bumper side H cur/Toon	\$ 420 888.31 ✓
1	Rear bumper cur/Toon	\$ 1,379.79 ✓
1	Rear bumper reflector H one	\$ 118.00 ✓
2	Rear bumper side retainers 11	\$ 301.08 X
2	Rear bumper PDC sensors 11	\$ 630.00 X
1	Rear fender -LH 11	\$ 1,085.00 X
1	Rear fender inner shield 11	\$ 182.00 X
1	Rear fender wheel arch garnish 11 cur/Toon	\$ 380 488.74 ✓
1	Rear wheel hub with bearing 11	\$ 533.96 X
1	Rear shock absorber 11	\$ 499.75 X
		\$ 6,106.63
	Less 10%	\$ 610.66
		\$ 5,495.97

<u>SPECIAL NETT ITEMS</u>		
1	Rear bumper clip (1 set) 111	\$ 80.00 30
1	Rear fender inner shield clip (1 set) 11	\$ 60.00 X
1	Rear tyre 11	\$ 400.00 X
1	Rear wheel rim - LH 11	\$ 1,250.00 X
		\$ 1,790.00

S/N	LABOUR CHARGES	
1	To remove, replaced damaged lamps and check up rear wiring.	\$ 80.00 20
2	To remove and refit rear undercarriage.	\$ 11 250.00 X
3	To conduct wheel alignment.	\$ 11 180.00 X
4	Panel beating.	\$ 1,200.00 550
5	To re-spray painting on the affected areas.	\$ 1,100.00 340
		\$ 2,810.00

GRAND TOTAL :

\$ 10,095.97

Not Authorized
for
repair
15/7/24
1/5 \$2400/
the phd. After rep.
4 days

1- 2297.79
102
2068.01
30
410
2008.01
2406.