



55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE : ACCIDENT REPAIRS
WORKSHOP : UBI ROAD 1
CONTACT NO : 6366 2323
FAX NO : 6841 1183
REFERENCE : PA/OD/0549/2024/KS
DATE : 15-Jul-24
WIP : 23284

VEHICLE NOT IN WORKSHOP. KINDLY ARRANGE FOR SURVEY ON 18/7/2024

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Motor Claims Dept

OWNER'S NAME : MR CHOW WAI THONG
ADDRESS : BLK 80 PUNGGOL CENTRAL PARC CENTROS
#02-01
SINGAPORE 828762
TELEPHONE : HP +65 90492373
TYPE OF CLAIM : OWN DAMAGE CLAIM
POLICY NO : 7210150861-01
VEHICLE NO : **SNE 898 J**
MODEL CODE : Q3 SPORTBACK 1.4 TFSI
MODEL YEAR : 16/12/2021
ENGINE NO : CZD C54183
CHASSIS NO : WAUZZZF3N1038709
MILEAGE : KM
DATE IN : -
ESTIMATED BY : JOHNNY BOO / ALLAN WU
ACCIDENT DATE : 13-Jul-24
PLACE OF ACCIDENT : JLN EUNOS, SINGAPORE
TOWARDS EAST COAST DIRECTION

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE. SNE 898 J

S/N	NATURE OF JOBS	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE, CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHT, HORNS, OUTSIDE TEMPERATURE SENSOR, HEADLIGHT WASHER AND FRONT PARKING AID.	S/N \$ 480.00	✓
2	TO REMOVE AND TRANSFER LHS HEADLIGHT CONTROL UNIT AND POWER MODULE.	S/N \$ 400.00	250
3	TO REMOVE AND REINSTALL LHS FRONT DOOR PANEL TRIM. TO REMOVE AND INSTALL LHS WING MIRROR ASSY TO FACILITATE RESPRAY OF RHS FRONT DOOR.	S/N \$ 280.00	✓
4	TO DISMANTLE AND RENEW FRONT BUMPER, LHS FRONT FENDER, BONNET AND LHS HEADLIGHT. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	\$ 3,600.00	1000
5	TO RESPRAY FRONT BUMPER, FRONT BUMPER SPOILER, LHS FRONT FENDER, BONNET, LHS FRONT DOOR, BOTH FRONT WHEEL ARCH TRIMS, LHS FRONT DOOR LOWER COVER AND LHS WING MIRROR COVER.	\$ 5,700.00	3600
6	TO SUPPLY AND RE-APPLY STONE GUARD FILM FOR HEADLIGHT.	S/N TBC	35
7	TO CARRY OUT DIAGNOSTIC CHECK	S/N \$ 292.00	✓
TOTAL LABOUR CHARGES		: \$ 10,752.00	



55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SNE 898 J.

S/N	PARTS DESCRIPTION	QTY	DAMAGED PARTS & PRICES		REMARKS
			S/NETT		
1	FRONT BUMPER <i>Delud</i>	1	\$	1,784.00	✓
2	FRONT BUMPER FIXING PARTS <i>ren</i>	1	\$	463.00	+
3	FRONT BUMPER CLOSING ELEMENT - LH <i>not ren</i>	1	\$	74.00	+
4	FRONT BUMPER TRIM - MANHATTAN GREY <i>Delud ren</i>	1	\$	443.00	+
5	FRONT BUMPER TRIM - CENTER <i>ren</i>	1	\$	272.00	+
6	FRONT PARKING AID SENSOR SUPPORT - LH <i>ren</i>	1	\$	32.00	+
7	FRONT BUMPER CLOSING ELEMENT <i>ren</i>	1	\$	238.00	+
8	FRONT BUMPER SPOILER <i>Delud</i>	1	\$	956.00	✓
9	FRONT BUMPER LOWER BRACKET - LH <i>ren</i>	1	\$	27.00	+
10	FRONT BUMPER AIR GUIDE GRILLE - LH <i>at</i>	1	\$	192.00	✓
11	FRONT BUMPER TRIM - LH (MANHATTAN GREY) <i>at</i>	1	\$	204.00	✓
12	FRONT PARKING AID SENSOR SUPPORT - LH <i>ren</i>	1	\$	32.00	+
13	FRONT PARKING AID SENSOR <i>ren</i>	1	\$	286.00	+
14	FRONT PARKING AID SENSOR SEAL RING	4	\$	11.00	+
15	RADIATOR GRILLE <i>at ne</i>	1	\$	2,367.00	+
16	RADIATOR GRILLE STRIKER PLATE <i>ren</i>	1	\$	303.00	+
17	RADIATOR GRILLE COVER	1	\$	303.00	+
18	LED HEADLIGHT - LH <i>Carb</i>	1	\$	6,696.00	✓
19	LED HEADLIGHT SPACER - LH <i>ren</i>	1	\$	50.00	+
20	LED HEADLIGHT POWER MODULE <i>at ne</i>	1	\$	904.00	+
SUB TOTAL SPARE PARTS		:	\$	15,637.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SNR 8427 P

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
21	LED HEADLIGHT MOUNTING - LH <i>new</i>	1	\$ 147.00	+
22	LIFT CYLINDER - LH	1	\$ 244.00	+
23	LIFT CYLINDER HOSE - LH	1	\$ 102.00	+
24	FRONT FENDER - LH <i>Broken</i>	1	\$ 1,537.00	✓
25	FRONT FENDER ATTACHMENT PARTS - LH <i>new</i>	1	\$ 74.00	x
26	FRONT FENDER BRACE - LH ?	1	\$ 127.00	?
27	FRONT FENDER BRACKET - LH ?	1	\$ 58.00	?
28	FRONT FENDER CLOSING ELEMENT - LH ?	1	\$ 42.00	?
29	FRONT FENDER DAMPER - LH UPPER <i>new</i>	1	\$ 40.00	x
30	FRONT FENDER SEAL - LH <i>new</i>	1	\$ 45.00	x
31	FRONT WHEEL HOUSING LINER - LH	1	\$ 289.00	+
32	FRONT WHEEL HOUSING LINER ATTACHMENT - LH <i>new</i>	1	\$ 111.00	+
33	FRONT WHEEL ARCH COVER - LH / RH <i>new</i>	2	\$ 1,278.00	✓
34	BONNET	1	\$ 3,746.00	+
35	BONNET ATTACHMENT PARTS	1	\$ 321.00	+
36	BONNET STRIKER - LH / RH	2	\$ 260.00	+
37	BONNET HINGE - LH / RH	2	\$ 210.00	+
38	BONNET IMPACT PROTECTION - CENTER	1	\$ 36.00	+
39	BONNET LID LOCK	1	\$ 246.00	+
40	WING MIRROR MOUNT - LH <i>new</i>	1	\$ 2,560.00	x
SUB TOTAL SPARE PARTS			\$ 27,110.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.



55 UBI ROAD 1, SINGAPORE 408699
TEL : 6366 2323 FAX : 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SNR 8427 P

			DAMAGED PARTS & PRICES		
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS	
41	WING MIRROR GLASS - LH <i>John M n</i>	1	\$ 1,038.00	+	
42	WING MIRROR CAP - LH <i>John Regis</i>	1	\$ 269.00	+	
43	FRONT DOOR COVER - LH <i>Regis</i>	1	\$ 438.00	+	
44	SUNDRIES <i>xt ?</i>	1	\$ 500.00	?	
45	FRONT NO PLATE <i>Nad n</i>	S/N	\$ 60.00	+	
TOTAL SPARE PARTS		:	\$ 45,052.00		
TOTAL LABOUR CHARGES		:	\$ 10,752.00		
GRAND TOTAL		:	\$ 55,804.00		

ALL CHARGES ARE NOT INCLUSIVE OF GST
LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.



55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME :
SURVEYED DATE :
AUTHORISED DATE :
EXCESS COST :
LIABILITY :
REMARKS :

Adrian Ling
18/07/24

Not Authorised, 05 Days.

PLEASE NOTE :

THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER LABOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF REPAIR, WE SHALL INFORM YOU ACCORDINGLY.
FOR INSPECTION OF VEHICLE, PLEASE REFER TO MS. NORAH KHAI AT TEL: 6768 9828 / 6768 9911 FOR APPOINTMENT.

YOURS FAITHFULLY,
PREMIUM AUTOMOBILES PTE LTD

JOHNNY BOO
BODY REPAIR MANAGER

ALLAN WU
CLAIMS CONSULTANT

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: