

Cheng Hoe Motor Pte Ltd

Blk 1019, Yishun Industrial Park A #01-374/382, Singapore 768761
TEL: 67556142 (YIS) FAX: 67557719 (YIS) Email: chmotor@singnet.com.sg
GST:201001158E RCB NO:201001158E

SNK1422K
TP/India

M/S : INDIA INT'L INSURANCE PTE LTD
64 CECIL STREET
#04/#05 IOB BUILDING
SINGAPORE 049711

TEL: 63476100

ATTN: Motor Claim Department

FAX: 62247743

Not Notwithstanding

WS Ref: TP/INDIA

Claim Type: Third Party

Accident Date: 15/07/2024

TP Veh Reg No: SNE7329P

Assessment B4 paint

8 days

Estimate No: ES2400585/YISHUN

Date: 16 Jul 2024

Policy No: 5134672704-01

Veh Reg No: SNK1422K

Make/Model: HONDA ODYSSEY
E:HEV ABSOLUTE

Chassis No: RC41309190

Engine No: LFA2149190

Reg. Date: 22/03/2023

5848.40

Estimate Repair Cost to Vehicle No :SNK1422K

Description	U/Price	Quantity	List Price S\$	Amount S\$
List Price				
1 REAR TAILGATE	1,328.60	1 PC	1,328.60	✓
2 TAILGATE EMBLEM 'ODYSSEY'	49.70	1 PC	49.70	✓
3 TAILGATE EMBLEM 'ABSOLUTE'	68.50	1 PC	68.50	✓
4 TAILGATE EMBLEM 'E:HEV'	70.50	1 PC	70.50	✓
5 TAILGATE INNER RUBBER	145.80	1 PC	145.80	✓
6 TAILGATE INNER LOCK	210.90	1 PC	210.90	✓
7 REAR BUMPER	1,270.50	1 PC	1,270.50	✓
8 REAR BUMPER CLIP	3.90	6 PC	23.40	✓
9 REAR WINDSCREEN GLASS MOULDING	140.30	1 PC	140.30	✓
10 REAR END PANEL OUTER	604.70	1 PC	604.70	✓
11 REAR END PANEL INNER TOP GARNISH	188.60	1 PC	188.60	✓
12 REAR SMART KEY SENSOR	88.70	1 PC	88.70	✓
13 REAR BUZZER SENSOR	85.00	1 PC	85.00	✓
14 REAR CENTRE REVERSE SENSOR	295.00	2 PC	590.00	✓
15 REAR REVERSE SENSOR WIRE HARNESS	1,401.00	1 SET	1,401.00	✓
16 REAR RH FENDER INNER GARNISH	649.80	1 PC	649.80	✓
17 REAR SPARE TYRE COMPARTMENT	791.20	1 PC	791.20	✓
			7,707.20	
		Less 20%	1,541.44	6,165.76
Special Net				
18 REAR WINDSCREEN GLASS SEALANT	40.00	1 PC	40.00	✓
19 REAR COMPARTMENT COATING	80.00	2 PC	160.00	80.00
			200.00	200.00
Labour				
20 REMOVE AND REFIX REAR WINDSCREEN GLASS	100.00	1 LA	100.00	✓
21 REMOVE & REFIX REAR BUMPER ASSY, TAILGATE & ATTACHMENTS, REAR LOCK ASSY, REFLECTORS, TOP SPOILER; TO RENEW REAR END PANEL, REAR SPARE TYRE COMPARTMENT; KNOCKING & REPAIR REAR RH CHASSIS & REALIGN THE SAME	1,200.00	1 LA	1,200.00	1000.00
22 REMOVE & REFIX SEAT, CARPET, GARNISH ETC	80.00	1 LA	80.00	✓
23 PUTTY & RESPRAY ON REAR SPARE TYRE COMPARTMENT, REAR END PANEL, REAR BUMPER, TAILGATE, REAR RH FENDER & ALL AFFECTED AREAS	1,200.00	1 LA	1,200.00	1000.00

Cheng Hoe Motor Pte Ltd

Blk 1019, Yishun Industrial Park A #01-374/382, Singapore 768761
TEL: 67556142 (YIS) FAX: 67557719 (YIS) Email: chmotor@singnet.com.sg
GST:201001158E RCB NO:201001158E

M/S : INDIA INT'L INSURANCE PTE LTD

64 CECIL STREET
#04/#05 IOB BUILDING
SINGAPORE 049711

TEL: 63476100

FAX: 62247743

ATTN: Motor Claim Department

WS Ref: TP/INDIA

Claim Type: Third Party

Accident Date: 15/07/2024

TP Veh Reg No: SNE7329P

Estimate No: ES2400585/YISHUN

Date: 16 Jul 2024

Policy No: 5134672704-01

Veh Reg No: SNK1422K

Make/Model: HONDA ODYSSEY
E:HEV ABSOLUTE

Chassis No: RC41309190

Engine No: LFA2149190

Reg. Date: 22/03/2023

Estimate Repair Cost to Vehicle No :SNK1422K

Description	U/Price	Quantity	List Price	Amount
			<u>S\$</u>	<u>S\$</u>
24 REMOVE & REFIX SMART KEY SENSOR,BUZZER SENSOR,REVERSE CAMERA & REVERSE SENSOR & RESET SYSTEM	100.00	1 LA	100.00	801
25 RUSTPROOFING	60.00	1 LA	60.00	✓
			2,740.00	2,740.00
			Total	S\$ 9,105.76
			Add GST @ 9%	819.52
			Total Amount Payable	<u>S\$ 9,925.28</u>

For Cheng Hoe Motor Pte Ltd

AUTHORISED SIGNATURE

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: