

Cheng Hoe Motor Pte Ltd

Blk 1019, Yishun Industrial Park A #01-374/382, Singapore 768761
TEL: 67556142 (YIS) FAX: 67557719 (YIS) Email: chmotor@singnet.com.sg
GST:201001158E RCB NO:201001158E

M/S : INDIA INT'L INSURANCE PTE LTD
64 CECIL STREET
#04/#05 IOB BUILDING
SINGAPORE 049711

TEL: 63476100 FAX: 62247743
ATTN: Motor Claim Department

WS Ref: TP/INDIA
Claim Type: Third Party
Accident Date: 15/07/2024
TP Veh Reg No: SNE7329P

Estimate No: ES2400585
Date: 16 Jul 2024
Policy No: 5134672704-01
Veh Reg No: SNK1422K
Make/Model: HONDA ODYSSEY
E:HEV ABSOLUTE
Chassis No: RC41309190
Engine No: LFA2149190
Reg. Date: 22/03/2023

Estimate Repair Cost to Vehicle No :SNK1422K

PAGE:1/2

Description	U/Price	Quantity	List Price S\$	Amount S\$
List Price				
1 REAR TAILGATE	1,328.60	1 PC	1,328.60	
2 TAILGATE EMBLEM 'ODYSSEY'	49.70	1 PC	49.70	
3 TAILGATE EMBLEM 'ABSOLUTE'	68.50	1 PC	68.50	
4 TAILGATE EMBLEM 'E:HEV'	70.50	1 PC	70.50	
5 TAILGATE INNER RUBBER	145.80	1 PC	145.80	
6 TAILGATE INNER LOCK	210.90	1 PC	210.90	
7 REAR BUMPER	1,270.50	1 PC	1,270.50	
8 REAR BUMPER CLIP	3.90	6 PC	23.40	
9 REAR WINDSCREEN GLASS MOULDING	140.30	1 PC	140.30	
10 REAR END PANEL OUTER	604.70	1 PC	604.70	
11 REAR END PANEL INNER TOP GARNISH	188.60	1 PC	188.60	
12 REAR SMART KEY SENSOR	88.70	1 PC	88.70	
13 REAR BUZZER SENSOR	85.00	1 PC	85.00	
14 REAR CENTRE REVERSE SENSOR	295.00	2 PC	590.00	
15 REAR REVERSE SENSOR WIRE HARNESS	1,401.00	1 SET	1,401.00	
16 REAR RH FENDER INNER GARNISH	649.80	1 PC	649.80	
17 REAR SPARE TYRE COMPARTMENT	791.20	1 PC	791.20	
			7,707.20	
		Less 20%	1,541.44	6,165.76
Special Net				
18 REAR WINDSCREEN GLASS SEALANT	40.00	1 PC	40.00	
19 REAR COMPARTMENT COATING	80.00	2 PC	160.00	
			200.00	200.00
Labour				
20 REMOVE AND REFIX REAR WINDSCREEN GLASS	100.00	1 LA	100.00	
21 REMOVE & REFIX REAR BUMPER ASSY, TAILGATE & ATTACHMENTS, REAR LOCK ASSY, REFLECTORS, TOP SPOILER; TO RENEW REAR END PANEL, REAR SPARE TYRE COMPARTMENT; KNOCKING & REPAIR REAR RH CHASSIS & REALIGN THE SAME	1,200.00	1 LA	1,200.00	
22 REMOVE & REFIX SEAT, CARPET, GARNISH ETC	80.00	1 LA	80.00	
23 PUTTY & RESPRAY ON REAR SPARE TYRE COMPARTMENT, REAR END PANEL, REAR BUMPER, TAILGATE, REAR RH FENDER & ALL AFFECTED AREAS	1,200.00	1 LA	1,200.00	

Cheng Hoe Motor Pte Ltd

Blk 1019, Yishun Industrial Park A #01-374/382, Singapore 768761
TEL: 67556142 (YIS) FAX: 67557719 (YIS) Email: chmotor@singnet.com.sg
GST:201001158E RCB NO:201001158E

M/S : INDIA INT'L INSURANCE PTE LTD

64 CECIL STREET

ES2400585/YISHUN

#04/#05 IOB BUILDING

SINGAPORE 049711

TEL: 63476100

FAX: 62247743

ATTN: Motor Claim Department

Estimate No: ES2400585

Date: 16 Jul 2024

Policy No: 5134672704-01

Veh Reg No: **SNK1422K**

Make/Model: HONDA ODYSSEY
E:HEV ABSOLUTE

WS Ref: TP/INDIA

Claim Type: Third Party

Accident Date: 15/07/2024

TP Veh Reg No: SNE7329P

Chassis No: RC41309190

Engine No: LFA2149190

Reg. Date: 22/03/2023

Estimate Repair Cost to Vehicle No :SNK1422K

PAGE:2/2

Description	U/Price	Quantity	List Price	Amount
			<u>S\$</u>	<u>S\$</u>
24 REMOVE & REFIX SMART KEY SENSOR,BUZZER SENSOR,REVERSE CAMERA & REVERSE SENSOR & RESET SYSTEM	100.00	1 LA	100.00	
25 RUSTPROOFING	60.00	1 LA	60.00	
			2,740.00	2,740.00
			Total	S\$ 9,105.76
			Add GST @ 9%	819.52
			Total Amount Payable	S\$ 9,925.28

For Cheng Hoe Motor Pte Ltd

AUTHORISED SIGNATURE