

Performance Motors

BMW Dealer



Supplementary

Estimate No. : b1 70384
Date Estimated : 03/07/2024
Prepared By : Tee Hong Da

Page No. :

- ESTIMATE REPAIR FOR -

Chan Suat Kheng
95 Grange Road
#07-09

- ACCOUNT - 303
MS First Capital Insurance Limited
6 Raffles Quay
#21-00
Singapore 048580

Singapore 249616

REGN. NO.	CHASSI S NO.	REGN. DATE	MODEL	M LEAGE
SNP2328S	WBA20FF0108D36874	19/01/2024	318i Sedan	29

DESCRIPTION	ORIGINAL PRICE	DISC. %	NETT
* To replace front RH door and attachments, rear RH door and attachments, front RH fender, RH side frame seal include making good the rear RH fender and carrying out other necessary repairs caused by the accident	2,975.00		2,975.00 /
* To respray front RH door, rear RH door, front RH fender and rear RH fender	3,540.00		3,540.00 /
* To carry out body cavity preservation (x3) (Per panel)	354.00		354.00 /
** To check electrical wiring system and lightings at the RH section for proper function	177.00		177.00 /
* To replace winshield cleaning container include checking the pump assembly for proper function	295.00		295.00 /
* To replace wheel rim include balancing (x2)	188.00		188.00 /

DESCRIPTION	UNIT PRICE	QTY	DISC. %	NETT
# PLUG IN RETAINER <i>re</i>	2.45	4.00	0.00	9.80
# CLIP COVER FOR COLUMN B <i>re</i>	1.00	8.00	0.00	8.00
# RH SIDE FRAME SEAL <i>re</i>	100.55	1.00	0.00	100.55
# ADJUSTABLE BLIND RIVET <i>re</i>	3.20	3.00	0.00	9.60
# WINDSHIELD CLEANING CONTAINER <i>de</i>	160.10	1.00	0.00	160.10

SUPPLEMENTARY ITEMS

Total Labour : 7,529.00
Total Parts : 288.05
Total Labour & Parts (before GST) : 7,817.05

Performance Motors Limited.
Sime Darby Performance Centre, 303 Alexandra Road

Tel: 1800-2255-269
Co Reg No. 197401559W

A Sime Darby Motors Company