



Final Report

Estimate No. : **b1 70384**
Date Estimated : **03/07/2024**
Prepared By : **Tee Hong Da**

Page No. :

- ESTIMATE REPAIR FOR -

Chan Suat Kheng
95 Grange Road
#07-09

Singapore 249616

- ACCOUNT - 303

MS First Capital Insurance Limited
6 Raffles Quay
#21-00
Singapore 048580

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	M LEAGE
SNP2328S	WBA20FF0108D36874	19/01/2024	318i Sedan	29

DESCRIPTION	ORIGINAL PRICE	DISC. %	NETT	
* To replace front RH door and attachments, rear RH door and attachments, front RH fender, RH side frame seal include making good the rear RH fender and carrying out other necessary repairs caused by the accident	2,975.00		2,975.00	
* To respray front RH door, rear RH door, front RH fender and rear RH fender	3,540.00		3,540.00	
To transfer lock mechanism from old to new door include conducting checks on new door power window system for proper function (x2)	1,062.00		1,062.00	
* To carry out body cavity preservation (x3) (Per panel)	354.00		354.00	
** To check electrical wiring system and lightings at the RH section for proper function	177.00		177.00	
* To replace winshield cleaning container include checking the pump assembly for proper function	295.00		295.00	
* To replace wheel rim include balancing (x2)	188.00		188.00	
Sundries	150.00		150.00	
DESCRIPTION	UNIT PRICE	QTY	DISC. %	NETT
# PLUG IN RETAINER	2.45	4.00	0.00	9.80

Performance Motors Limited.

Sime Darby Performance Centre, 303 Alexandra Road

Tel: 1800-2255-269

Co Reg No. 197401559W





Final Report

ALLOY RIM 7.5JX18 V SPK 780	1,141.60	1.00	0.00	1,141.60
ALLOY RIM 7.5JX18 V SPK 780	1,141.60	1.00	0.00	1,141.60
FRT RH SIDE PANEL	887.15	1.00	0.00	887.15
FRT RH DOOR	1,462.10	1.00	0.00	1,462.10
REAR RH DOOR	1,462.10	1.00	0.00	1,462.10
# CLIP COVER FOR COLUMN B	1.00	8.00	0.00	8.00
# RH SIDE FRAME SEAL	100.55	1.00	0.00	100.55
# ADJUSTABLE BLIND RIVET	3.20	3.00	0.00	9.60
(S/L) DOOR WEATHERSTRIP	167.35	2.00	0.00	334.70
# WINDSHIELD CLEANING CONTAINER	160.10	1.00	0.00	160.10

SUPPLEMENTARY ITEMS

Total Labour :	8,741.00
Total Parts :	6,717.30
Total Labour & Parts (before GST) :	15,458.30
Deduction for Excess :	
Total Repair Costs less Excess:	15,458.30
GST @9%:	1,391.25
Grand Total :	16,849.55

Performance Motors Limited.

Sime Darby Performance Centre, 303 Alexandra Road

Tel: 1800-2255-269

Co Reg No. 197401559W

