

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

To: China Taiping Insurance (Singapore) Pte. Ltd.
3 Anson Road
#16-00 Springleaf Tower
Singapore 079909

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Tan Kah Leong

Date: 11 Jul 2023

Preliminary Advice

Vehicle No	: GBL7433B	Accident Date	: 22/07/2022
Make	: TOYOTA HIACE	Policy No.	: DMCVSNW00033502200
Assignment Date	: 15/11/2022	Excess	: S\$2,000.00
Date of Inspection	: 16/11/2022	Est. Duration of Repair	: 28
Inspection At	: DING AUTO PTE LTD		

Point of Impact / General Description of Damages

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	57,985.34 (Inclusive of Supplementary \$2,112.
Revised Amount	:S\$	28,040.34
Check Items (Estimated)	:S\$	24,915.00
Total	:S\$	52,955.34

Lump Sum Repair	:S\$
-----------------	------

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	97,000.00
COE / PARF Rebate	:S\$	35,200.00
Salvage Value	:S\$	
Margin for Repair	:S\$	61,800.00

Remarks

(X) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.

() The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.

(X) Other comments : Kindly approve on Supplementary.

Please note that the preliminary advise amount (Revised & Check items) stated are subject to consistency check, part prices and labour cost.