

ASSIGNMENT

Front: _____ Date: _____
 Estin: _____
 OD / TP RES / OD RES / EVA / INV / MV
 To in Vehicle No: _____
 at W/O _____
 of _____
 Insured: _____
 Policy No: _____
 Claims No: _____
 Sum Insured: _____ Excess: _____
 (Client's Record)
 Make of Veh: _____
 (Policy Condition)

N/S	O/S

Remarks: The veh had commenced its repair at the time of inspection.

Bal. or Market Value: _____
 IDAC Accident Report: _____ Consistent?: Yes or No
 GIA / PR Seen: _____ Consistent?: Yes or No
 Est. Repair: _____ days Res.: Yes or No
 Lum Sum: _____ % 3 Val.: Yes or No
 CA / REV / REP. / 24 HRS
 Date: _____ Person Contacted: _____
 Vehicle: IN / OUT

Veh No: SGX73E Yr Regn: 2007, July
 Type: M. Car M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
 Truck / Trailer or
 Make: Mitsuoaka Galue C.D. 2495
 Colour: Gold A/C: Insured / Std / NI / NA
 Sp. Reading: 184182 T/Radio: Insured / Std / NI / NA
 Eng/No: _____
 C/No: Y50153254
 Gen. Cond: Good Fair / Poor / Burnt
 Steering: In order / Jammed / Leaked / Burnt or
 Brake: In order / Jammed / Leaked / Burnt or
 Modi: Nil / S/Rim / STD A/Rim or
 Tyre Size: F: 225/55R17
 R: 225/55R17

BS / DUN / EXNOVA / GY / FS / IZA / MIG / OHTSU / PIR / SUMI /
 TOYO / YOKO or Continental

Front: _____ Rear: _____
 R/Bal. 06 mm R/Bal. 06 mm
 L/Bal. 06 mm L/Bal. 06 mm
 D.O.A. _____ D.O.I. 15/07/24
 Survey held at KT Garage
 Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	<u>TP Budget Direct.</u>
	<u>COE Expiry: 16/07/24.</u>
	<u>Estimate given during: Yes (✓)</u>
	<u>1st Survey: No (✓)</u>
	<u>MV: 26K (Depreciation @ 8.5K x 3yr)</u>
	<u>PV: 15.7K</u>
	<u>Nett: 10.3K</u>

Date/Time, File Pass to?

☐ : Preli. Report
☐ : Final Report

Days Of Repair: _____

Resurvey No. of Trip: _____

Survey Fee: _____

Transportation: _____

S + RS: _____

Photos: _____

Others: _____

Add Fee: ☐ : Site Insp (\$ _____)

☐ : Interview (\$ _____)

☐ : Tech. Inve (\$ _____)

Report Format: _____

Report Date / Time / Location: _____



KT GARAGE PTE LTD UEN: 201906115R

Auto Bay@ Kaki Bukit Entrance A

BLK 1 Kaki Bukit Ave 6 #01-04 Singapore 417883

ORIGINAL

Date :

Total Pages :

TO: Whom it may concern

Our Customer : Limm Han Tee

Vehicle No : **SGX73E**

Model : Mitsuoka Galue

Manufacture Year : 2006

Date of Accident : 12/7/2024

Total Estimate Repair Days :

No.	Item Descriptions	Qty	Unit Price	Amount	Remarks From Surveyor
A.	Spare Parts				
1	Rear Bumper <i>Painted</i>	1	\$2,705.63	\$2,705.63	✓
2	Rear Bumper Clips <i>new</i>	10	\$3.00	\$30.00	✓
3	Rear Bumper Cover Centre Garnish <i>Painted</i>	1			+
4	Rear Bumper - GaluE Emblem <i>new</i>	1			✓
5	Rear Bumper Cover Centre <i>Painted</i>	1	\$1,060.56	\$1,060.56	✓
6	Rear Bumper Cover RH Corner <i>new</i>	1	\$1,041.41	\$1,041.41	✓
7	Rear bumper Cover LH Corner <i>Painted</i>	1	\$1,041.41	\$1,041.41	✓
8	Rear Bumper Side Retainer <i>new</i>	2	\$216.00	\$432.00	+
9	RH & LH Taillamp <i>2H ended</i>	2	\$904.56	\$1,809.12	904.56
10	RH & LH Taillamp Outer Chrome <i>new</i>	2			+
11	RH & LH Taillamp Lower <i>ended</i>	2			✓
12	Reverse Lamp <i>ended</i>	1	\$704.48	\$704.48	✓
13	Reverse Lamp Holder <i>ended</i>	1	\$186.00	\$186.00	✓
14	Rear Bootlid <i>new</i>	1			+
15	Rear Bootlid Garnish <i>Painted</i>	1			✓
16	Rear Bootlid Garnish Emblem <i>new</i>	1			✓
17	Rear Bootlid Finisher Assy <i>new</i>	1			+
18	Reverse lamp holder <i>Repaired</i>	1			+
19	End panel <i>Painted</i>	1	\$895.20	\$895.20	✓
20	End panel weatherstrip <i>new</i>	1	\$336.00	\$336.00	✓
21	End panel top garnish <i>Painted</i>	1	\$198.00	\$198.00	✓
22	End panel catch <i>new</i>	1	\$150.00	\$150.00	+
23	Keyless sensor <i>ended</i>	1	\$117.60	\$117.60	✓
24	Rear boot lock <i>new</i>	1	\$297.60	\$297.60	+
	Sub Total			\$11,005.01	
	Less 20%			\$2,201.00	
	Sub Total 1			\$8,804.01	
B	Special Nett				
1	Rear Numper Plate With Holder <i>new</i>	1	\$80.00	\$80.00	+
2	Parking Sensor <i>ended</i>	1	\$588.00	\$588.00	200
	Sub Total 2			\$588.00	
C	Labour				
1	To panel beat, knock and straighten damaged panel and re-align the same			\$1,500.00	800
2	To rust proof the affected areas			\$120.00	60
3	To check all necessary lighting & wiring			\$80.00	30



KT GARAGE PTE LTD UEN: 201906115R

Auto Bay@ Kaki Bukit Entrance A

BLK 1 Kaki Bukit Ave 6 #01-04 Singapore 417883

4	To install parking sensor	\$120.00	50
5	To spray paint the affected areas	\$1,200.00	700
	Total Labour	\$3,020.00	
	Total Repair Cost	\$12,412.01	
	* The above quoted are exclusive of GST.		

Yours faithfully,

Kai
f KT Garage Pte Ltd

Surveyor's Details	
Name	
Contact	
Survey Date	
Recommender	Authorize / Not Authorize
Before Paint	Yes / No
Signature	

Adnan

L/S 15/07/24.

No of days : 06 Days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: