

ASS. REC. BY:

REF:

CC3/AIG22012898/Ac

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. 1800053121-03Claims No. 3109893272SGSum Insured: _____ Excess: \$500f

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 5 days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: SFN8484P Yr Regn: 2018, May

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Audi Q7 C.C. 1984Colour: Green A/C: Insured / Std / NI / NASp. Reading: 91677 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: WAUZ224M SJ D031220Gen. Cond: Good / Fair / Poor / BurntSteering: Inorder / Jammed / Leaked / Burnt orBrake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 255/55R19R: 255/55R19BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front _____ Rear _____

R/Bal. 26 mm R/Bal. 06 mmL/Bal. 26 mm L/Bal. 06 mmD.O.A. _____ D.O.I. 23/12/22Survey held at PremiumDes. of Damages: Front / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	<u>OD AIG.</u>
<u>11/7/23</u>	<u>Finalised final sig @18,416.16 ; 5 days with Mr Boo. (Red. 18,379.84, 50%)</u>
	<u>MV: 175K</u>
	<u>PV: 79.81C</u>
	<u>Nett: 95.2K</u>

Date/Time, File Pass to?



: Preli. Report

Days Of Repair: 5

1)



: Final Report

Resurvey No. of Trip: _____

Date/Time, File Return to?

2)

Add Fee:



: Site Insp (\$



: Interview (\$



: Tech. Insp (\$

Survey Fee:

Transportation:

: (R) \$

: P/R

: P/R

Report Format:

OD

18,416.16

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type: Singapore NRIC
Owner ID: 126G

Vehicle Details

Vehicle No.: SFN8484P
Vehicle to be Exported: No
Intended Deregistration Date: 27 Dec 2022
Vehicle Make: AUDI
Vehicle Model: Q7 2.0 TFSI QU (252 BHP)
Primary Colour: Blue
Manufacturing Year: 2017
Engine No.: CYR059010
Chassis No.: WAUZZZ4M5JD031220
Maximum Power Output: 185.0 kW (248 bhp)
Open Market Value: \$59,262.00
Original Registration Date: 16 May 2018
First Registration Date: 16 May 2018
Transfer Count: 0
Actual ARF Paid: \$78,672.00

Intended PARF Rebate Details


PARF Eligibility: Yes
PARF Eligibility Expiry Date: 15 May 2028
PARF Rebate Amount: \$59,004.00

Intended COE Rebate Details

COE Expiry Date: 15 May 2028
COE Category: B - Car above 1600cc or 97kW (130bhp)
COE Period(Years): 10
QP Paid: \$38,501.00
COE Rebate Amount: \$20,721.00
Total Rebate Amount: \$79,725.00

The information contained herein is correct as at 27 Dec 2022

OK



Post an Advertisement
Sell it yourself! Advertise it at just
\$68 until it's SOLD!

Post an Ad Advertiser Login Ways of Selling

original stock condition supra



very low mileage agent sold,
now to balance its condition, car
in showroom.
Ole Supercars



Sort by results/page

4 vehicles



audi q7

Any Category

Advanced Search



Search

	Make	Model	Price	Depreciation	Reg Date	Eng Cap	Mileage	Veh Type	Status
Search Selection	audi q7		Any	Any	2018	Any	Any	Any	Available
	Audi Q7 2.0A TFSI Quattro Tip 7-Seater		\$176,800	\$25,870 /yr	19-Apr-2018	1,984 cc	32,400 km	SUV	Available
Lowest Depreciation 25.7k Nego. Low Mileage 32,400km. A Well Maintained Luxury 7 Seater SUV In Tip Top Condition, Awaits You To Test Drive And Feel It For Yourself! Prestigious, Performance, And High Levels Of Comfort, Spaciousness, And Luxury Interior. Well Maintaine...									
Roadlink Auto Pte Ltd									
Posted: 21-Dec-2022									
	Audi Q7 2.0A TFSI Quattro Tip 7-Seater		\$176,800	\$24,730 /yr	18-Jul-2018	1,984 cc	57,465 km	SUV	Available
1 owner, agent maintained with 5 years warranty, Well Maintained By Previous Owner! Full Loan With High Trade In Available. Price Negotiable. Call Now Or Visit Our Showroom Today.									
Posted: 25-Dec-2022									
	Audi Q7 2.0A TFSI Quattro Tip 7-Seater		\$188,888	\$26,870 /yr	12-Sep-2018	1,984 cc	56,255 km	SUV	Available
Brokers Welcome - Partner with CARRO today and get access to the largest inventory in Singapore. Contact us to find out more!									
Carro									
Posted: 02-Dec-2022									
	Audi Q7 2.0A TFSI Quattro Panoramic Roof		\$192,500	\$27,100 /yr	12-Oct-2018	1,984 cc	93,000 km	SUV	Available
Full loan available! Bank or in house loan is available. We provide the lowest interest rate. Loan and high trade in are available. Ex bankruptcy or bad credit can apply. Meet our friendly consultant for a non obligation advice.									
Posted: 27-Dec-2022									

Save this search criteria, to get email alerts whenever a match is found.

Make Model Price Depreciation Reg Date Eng Cap Mileage Veh Type Status

For old advertisements, view **Expired ads**

results/page

Buy / Rent Cars

New Cars For Sale

Used Cars For Sale

Cars For Rent

Sell Your Car

Post an Ad

Sell by Bidding

Sell by Consignment

Aftermarket

Workshop Directory

Aftermarket Products

Articles

Car Reviews

Car Advice

Car News

Car Features

General

About Us

Contact Us

Careers

Site Map

Resource

COE [Compare](#)

Car Insurance

Used Car Warranty

Follow Sgcarmart.com

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE : ACCIDENT REPAIRS
WORKSHOP : UBI ROAD 1
CONTACT NO : 6366 2323
FAX NO : 6841 1183
REFERENCE : PA/OD/1138/2022/EQ
DATE : 20-Dec-22
WIP : 55503

VEHICLE NOT IN WORKSHOP. KINDLY ARRANGE FOR SURVEY ON 23/12/2022

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Motor Claims Dept

Tel: 6880 4602 - Fax: 6880 4838

OWNER'S NAME : MR CHNG HOCK HUAT
ADDRESS : 30 BARKER ROAD
SINGAPORE 309906

TELEPHONE : HP +65 90908866
TYPE OF CLAIM : OWN DAMAGE CLAIM
POLICY NO : 1800053121-03
VEHICLE NO : **SFN 8484 P**
MODEL CODE : AUDI Q7 2.0 TFSI
MODEL YEAR : 16/5/2018
ENGINE NO : CYR 059010
CHASSIS NO : WAUZZZ4M5JD031220
MILEAGE : -
DATE IN : -
ESTIMATED BY : JOHNNY BOO / ALLAN WU
ACCIDENT DATE : 16-Dec-22
PLACE OF ACCIDENT : DUNEARN RD TURN TO BUKIT TIMAH

55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SFN 8484 P

S/N	NATURE OF JOBS	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE, CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR, HEADLIGHT WASHER ASSY AND FRONT PARKING AID. S/N \$	480.00 ✓	
2	TO REMOVE AND TRANSFER LHS HEADLIGHT'S CONTROL UNIT AND POWER MODULE. S/N \$	450.00 300	
3	TO REMOVE AND REINSTALL LHS FRONT DOOR PANEL TRIM. TO REMOVE AND REINSTALL LHS WING MIRROR ASSY TO FACILITATE RESPRAY OF LHS FRONT DOOR. S/N \$	280.00 11 ✓	
4	TO DISMANTLE AND RENEW FRONT BUMPER, LHS FRONT FENDER AND LHS HEADLIGHT. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED. \$	2,700.00 1200	
5	TO RESPRAY FRONT BUMPER, LHS FRONT FENDER AND LHS FRONT DOOR. \$	3,500.00 1800	
6	TO RENEW LHS FRONT RIM. TO CARRY OUT PRE/POST WHEEL ALIGNMENT. S/N \$	520.00 X	
7	TO CARRY OUT DIAGNOSTIC CHECK. S/N \$	192.00 ✓	
TOTAL LABOUR CHARGES		: \$ 8,122.00	

Car-in

5/1/23

wp: 55503

PREMIUM AUTOMOBILES

55 UBI ROAD 1, SINGAPORE 408699

TEL: 6366 2323 FAX: 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG



AZG - Adrian

- 5 days

Xin Yu.

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SFN 8484 P

DAMAGED PARTS & PRICES

S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
1	FRONT BUMPER <i>Del d</i>	1	\$ 2,896.00 ✓	2,316.80
2	FRONT BUMPER FIXING PARTS <i>HL</i>	1	\$ 468.00 ✗	
3	FRONT BUMPER TOW EYE COVER <i>HL</i>	1	\$ 44.00 +	
4	FRONT BUMPER AIR GUIDE - LH <i>HL HL</i>	1	\$ 75.00 ? ✗	
5	FRONT BUMPER END CAP - LH <i>HL</i>	1	\$ 40.00 ✓	<i>86.8</i> 29.84
6	FRONT BUMPER CLOSING ELEMENT - UPPER CENTRE <i>HL HL</i>	1	\$ 309.00 ✗	
7	FRONT BUMPER GRILLE - LOWER CENTRE <i>HL HL</i>	1	\$ 230.00 +	
8	FRONT BUMPER UNDERRUN BAR <i>HL HL</i>	1	\$ 899.00 +	
9	FRONT BUMPER CLOSING ELEMENT - LOWER CENTRE <i>HL HL</i>	1	\$ 235.00 ✗	<i>86.8</i> 187.60
10	FRONT BUMPER SPOILER - LH <i>Del d</i>	1	\$ 154.00 -	123.20
11	FRONT BUMPER SPOILER MUD GUARD - LH OUTER <i>HL HL</i>	1	\$ 49.00 ? ✗	
12	RADIATOR GRILLE <i>HL HL</i>	1	\$ 2,741.00 +	
13	FRONT BUMPER AIR GUIDE GRILLE - LH <i>HL HL</i>	1	\$ 332.00 -	265.60
14	FRONT BUMPER FOG LAMP COVER PLATE - LH <i>HL HL</i>	1	\$ 38.00 +	
15	FRONT BUMPER SPOILER - LH INNER <i>HL HL</i>	1	\$ 65.00 +	
16	FRONT BUMPER GUIDE SECTION - LH <i>HL HL</i>	1	\$ 50.00 ✓	<i>86.8</i> 39.52
17	FRONT FENDER - LH <i>HL HL</i>	1	\$ 1,819.00 -	1,455.20
18	FRONT FENDER ATTACHMENT PARTS <i>HL HL</i>	1	\$ 123.00 ✗	
19	FRONT FENDER BRACE <i>HL HL</i>	1	\$ 171.00 ✓	<i>86.8</i> 136.80
20	FRONT FENDER BRACKET - LH <i>HL HL</i>	1	\$ 72.00 ? ✗	
SUB TOTAL SPARE PARTS			\$ 10,810.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.

Adrian Ling
Resurveyed
86.8

PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SFN 8484 P

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
21	FRONT WHEEL HOUSING LINER <i>torn</i>	1 \$	260.00 ✓	<i>S.S.</i> 208.00
22	FRONT WHEEL HOUSING LINER - LH REAR <i>3 new</i>	1 \$	260.00 +	
23	HEADLIGHT MOUNTING - LH ?	1 \$	132.00 >	105.20
24	HEADLIGHT - LH <i>crack</i>	1 \$	10,660.00 ✓	8,528.00
25	HEADLIGHT HOSE - LH <i>new</i>	1 \$	45.00 +	
26	HEADLIGHT FAN ?	1 \$	428.00 ? X	
27	HEADLIGHT CONTROL UNIT - LH ?	1 \$	840.00 ? X	
28	HEADLIGHT POWER MODULE ?	1 \$	842.00 ? X	
29	LIFT CYLINDER - LH <i>crack 2</i>	1 \$	217.00 ✓	<i>S.S.</i> 173.60
30	LIFT CYLINDER HOSE <i>new</i>	1 \$	113.00 +	
31	FRONT WHEEL COVER - LH / RH <i>LH Delid, RIT</i>	2 \$	696.00 ✓	556.80
32	FRONT PARKING AID SENSOR - INNER / OUTER <i>new</i>	2 \$	531.00 +	
33	FRONT PARKING AID SEAL RING <i>new</i>	4 \$	10.00 X	
34	FRONT ALUMINIUM RIM - LH <i>new</i>	1 \$	2,266.00 +	
35	FRONT ALUMINIUM RIM RUBBER VALVE <i>new</i>	1 \$	4.00 ✓	
36	FRONT NO PLATE <i>new</i>	S/N \$	60.00 +	
37	SUNDRIES <i>new</i>	\$	500.00 ?	38.00
TOTAL SPARE PARTS		:	\$ 28,674.00	
TOTAL LABOUR CHARGES		:	\$ 8,122.00	
GRAND TOTAL		:	\$ 36,796.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST
 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.



55 UBI ROAD 1, SINGAPORE 408699
TEL : 6366 2323 FAX : 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME : *Adrian Lim*
SURVEYED DATE : *23/12/22*
AUTHORISED DATE :
EXCESS COST :
LIABILITY :
REMARKS : *Not Authorised, 05 days*

PLEASE NOTE : THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER LABOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF REPAIR, WE SHALL INFORM YOU ACCORDINGLY. FOR INSPECTION OF VEHICLE, PLEASE REFER TO MS. NORAH KHAI AT TEL: 6768 9828 / 6768 9911 FOR APPOINTMENT.

YOURS FAITHFULLY,
PREMIUM AUTOMOBILES PTE LTD

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

JOHNNY BOO
BODY REPAIR MANAGER

ALLAN WU
CLAIMS CONSULTANT

55 UBI ROAD 1, SINGAPORE 408699
TEL : 6366 2323 FAX : 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE : ACCIDENT REPAIRS
WORKSHOP : UBI ROAD 1
CONTACT NO : 6366 2323
FAX NO : 6841 1183
REFERENCE : PA/OD/1138/2022/EQ
DATE : 20-Dec-22
WIP : 55503

VEHICLE NOT IN WORKSHOP. KINDLY ARRANGE FOR SURVEY ON 23/12/2022

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way
#07-16 AIG Building
Singapore 079120

Attn: Motor Claims Dept

Tel: 6880 4602 - Fax: 6880 4838

*Hi Adrian
7d days exclude 1 Sunday
Johnny Boo 6 Mar 23*

OWNER'S NAME : MR CHNG HOCK HUAT
ADDRESS : 30 BARKER ROAD
SINGAPORE 309906

TELEPHONE : HP +65 90908866
TYPE OF CLAIM : OWN DAMAGE CLAIM
POLICY NO : 1800053121-03
VEHICLE NO : **SFN 8484 P**
MODEL CODE : AUDI Q7 2.0 TFSI
MODEL YEAR : 16-05-18
ENGINE NO : CYR 059010
CHASSIS NO : WAUZZZ4M5JD031220
MILEAGE : -
DATE IN : -
ESTIMATED BY : JOHNNY BOO / ALLAN WU
ACCIDENT DATE : 16-Dec-22
PLACE OF ACCIDENT : DUNEARN RD TURN TO BUKIT TIMAH

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SFN 8484 P

S/N	NATURE OF JOBS	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE, CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR, HEADLIGHT WASHER ASSY AND FRONT PARKING AID. S/N \$	480.00 \$	480.00
2	TO REMOVE AND TRANSFER LHS HEADLIGHT'S CONTROL UNIT AND POWER MODULE. S/N \$	450.00 \$	300.00
3	TO REMOVE AND REINSTALL LHS FRONT DOOR PANEL TRIM. TO REMOVE AND REINSTALL LHS WING MIRROR ASSY TO FACILITATE RESPRAY OF LHS FRONT DOOR. S/N \$	280.00 \$	280.00
4	TO DISMANTLE AND RENEW FRONT BUMPER, LHS FRONT FENDER AND LHS HEADLIGHT. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED. \$	2,700.00 \$	1,200.00
5	TO RESPRAY FRONT BUMPER, LHS FRONT FENDER AND LHS FRONT DOOR. \$	3,500.00 \$	1,800.00
6	TO RENEW LHS FRONT RIM. TO CARRY OUT PRE/POST WHEEL ALIGNMENT. S/N \$	520.00	
7	TO CARRY OUT DIAGNOSTIC CHECK. S/N \$	192.00 \$	192.00
TOTAL LABOUR CHARGES		: \$ 8,122.00	\$ 4,252.00

55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SFN 8484 P

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
1	FRONT BUMPER	1 \$	2,896.00 \$	2,316.80
2	FRONT BUMPER FIXING PARTS	1 \$	468.00	
3	FRONT BUMPER TOW EYE COVER	1 \$	44.00	
4	FRONT BUMPER AIR GUIDE - LH	1 \$	75.00	
5	FRONT BUMPER END CAP - LH	1 \$	40.00 \$	29.84
6	FRONT BUMPER CLOSING ELEMENT - UPPER CENTRE	1 \$	309.00	
7	FRONT BUMPER GRILLE - LOWER CENTRE	1 \$	230.00	
8	FRONT BUMPER UNDERRUN BAR	1 \$	899.00	
9	FRONT BUMPER CLOSING ELEMENT - LOWER CENTRE	1 \$	235.00 \$	187.60
10	FRONT BUMPER SPOILER - LH	1 \$	154.00 \$	123.20
11	FRONT BUMPER SPOILER MUD GUARD - LH OUTER	1 \$	49.00	
12	RADIATOR GRILLE	1 \$	2,741.00	
13	FRONT BUMPER AIR GUIDE GRILLE - LH	1 \$	332.00 \$	265.60
14	FRONT BUMPER FOG LAMP COVER PLATE - LH	1 \$	38.00	
15	FRONT BUMPER SPOILER - LH INNER	1 \$	65.00	
16	FRONT BUMPER GUIDE SECTION - LH	1 \$	50.00 \$	39.52
17	FRONT FENDER - LH	1 \$	1,819.00 \$	1,455.20
18	FRONT FENDER ATTACHMENT PARTS	1 \$	123.00	
19	FRONT FENDER BRACE	1 \$	171.00 \$	136.80
20	FRONT FENDER BRACKET - LH	1 \$	72.00	
SUB TOTAL SPARE PARTS		:	\$ 10,810.00	\$ 4,554.56

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SFN 8484 P

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
	<i>c/f</i>			\$ 4,554.56
21	FRONT WHEEL HOUSING LINER	1 \$	260.00 \$	208.00
22	FRONT WHEEL HOUSING LINER - LH REAR	1 \$	260.00	
23	HEADLIGHT MOUNTING - LH	1 \$	132.00 \$	105.20
24	HEADLIGHT - LH	1 \$	10,660.00 \$	8,528.00
25	HEADLIGHT HOSE - LH	1 \$	45.00	
26	HEADLIGHT FAN	1 \$	428.00	
27	HEADLIGHT CONTROL UNIT - LH	1 \$	840.00	
28	HEADLIGHT POWER MODULE	1 \$	842.00	
29	LIFT CYLINDER - LH	1 \$	217.00 \$	173.60
30	LIFT CYLINDER HOSE	1 \$	113.00	
31	FRONT WHEEL COVER - LH / RH	2 \$	696.00 \$	556.80
32	FRONT PARKING AID SENSOR - INNER / OUTER	2 \$	531.00	
33	FRONT PARKING AID SEAL RING	4 \$	10.00	
34	FRONT ALUMINIUM RIM - LH	1 \$	2,266.00	
35	FRONT ALUMINIUM RIM RUBBER VALVE	1 \$	4.00	
36	FRONT NO PLATE	S/N \$	60.00	
37	SUNDRIES	\$	500.00 \$	38.00
TOTAL SPARE PARTS		: \$	28,674.00 \$	14,164.16
TOTAL LABOUR CHARGES		: \$	8,122.00 \$	4,252.00
GRAND TOTAL		: \$	36,796.00 \$	18,416.16

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED

SPARE PARTS ARE SPECIAL NETT.

bi-01/02/23

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME :
SURVEYED DATE :
AUTHORISED DATE :
EXCESS COST :
LIABILITY :
REMARKS :

PLEASE NOTE

THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER LABOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF REPAIR, WE SHALL INFORM YOU ACCORDINGLY.
FOR INSPECTION OF VEHICLE, PLEASE REFER TO MS. NORAH KHAI AT TEL: 6768 9828 / 6768 9911 FOR APPOINTMENT.

YOURS FAITHFULLY,
PREMIUM AUTOMOBILES PTE LTD

JOHNNY BOO
BODY REPAIR MANAGER

ALLAN WU
CLAIMS CONSULTANT