

SPEEDWERKZ PRIVATE LIMITED

1 KAKI BUKIT AVENUE 6 #01-73, AUTOBAY, SINGAPORE 417883

Tel: 96195936 / info@speedwerkz.biz

VEHICLE NUMBER: GBL1786Y

MAKE & MODEL: CITROEN BERLINGO

Not Authorized
Rm
Moras
16/7/24

d/s \$10,500
taken. All 11 per.
9 days.

BONNET		R	\$1,385.10	X
HEADLAMP L/R X2	705.00	W/SAH o/s holder one	\$3,646.34	12C
HEADLAMP PANEL RH	188.00	Dis	\$366.10	—
FRONT BUMPER		703.00	\$980.90	—
FRONT BUMPER BOTTOM (BLACK)		746.00	\$1,012.50	—
FRONT BUMPER UNDERCOVER		266.00	\$311.50	—
FRONT BUMPER SIDE RETAINER L/R X2	60	W/SAH o/s cre	\$266.20	12C
FRONT BUMPER FOG LAMP RH		17	\$273.80	X
FRONT BUMPER FOG LAMP COVER RH		17	\$98.00	X
FRONT RADIATOR GRILLE ASSY		17	\$488.60	X
SUPPORT PANEL		17	\$988.80	X
CONDENSER		17	\$1,210.20	X
front inter cooler		1100.00	\$1,518.90	—
FRONT FENDER RH		966.00	\$966.90	—
FRONT FENDER SPLASH SHIELD RH		180.00	\$294.00	—
FRONT FENDER BRACKET RH		324	\$189.20	—
FRONT FENDER INNER PANEL RH		R	\$1,154.00	X
FRONT FENDER SIGNAL LAMP		17	\$106.00	X
FRONT air duct		255.00	\$356.10	—
FRONT RIM RH		324	\$891.40	180 s/w
FRONT RIM CAP RH		282.00	\$315.30	—
FRONT WHEEL BEARING & HUB RH		320.00	\$426.10	—
FRONT KNUCKLE ARM RH		450.00	\$524.20	—
FRONT SHOCK ABSORBER RH		276.00	\$869.40	—
FRONT LOWER ARM RH		721	\$478.50	—
FRONT LOWER ARM RH BALL JOINT RH		150.00	\$523.40	—
FRONT DRIVESHAFT RH		17	\$1,684.10	X
FRONT TIE ROD L/R X2		17	\$376.80	X
FRONT STEERING RACK		17	\$2,156.80	X
FRONT STABILIZER LINK L/R X2		112.00	\$496.40	12C
FRONT STABILIZER BAR		552.00	\$623.30	—
FRONT ABS SENSOR RH brake pipe RH		160.00	\$285.80	—
FRONT SUBFRAME crossmember		1407.00	\$1,966.30	—
FRONT DOOR PILLAR RH		R	\$1,496.20	X
FRONT DOOR ASSY RH		1803.00	\$1,866.70	—
FRONT DOOR RH HINGES X2		17	\$268.40	X
FRONT DOOR CHECKER RH		17	\$155.00	X
FRONT DOOR OUTER PROTECTOR RH		320.00	\$458.80	—
FRONT DOOR WINDOW MOULDING RH		17	\$251.70	X
FRONT DOOR POWER WINDOW REGULATOR RH		17	\$516.00	X
FRONT DOOR POWER WINDOW MOTOR RH		17	\$648.00	X
FRONT DOOR WEATHERSTRIP RH		17	\$384.80	X

FRONT DOOR SIDE MIRROR RH
FRONT DOOR INNER LOCK RH
FRONT DOOR TRIMBOARD RH
FRONT WINDSCREEN MOULDING

11 \$1,015.30X
11 \$486.50X
11 \$535.60X
12 \$361.00X
\$35,674.94

107

150f FRONT BUMPER CLIPS
BONNET INSULATOR CLIPS
RADIATOR GRILLE CLIPSS
150f FRONT FENDER SPLASH SHIELD RH CLIPS
FRONT FENDER INNER PANEL RH SEALANT
FRONT DOOR PILLAR RH SEALANT
FRONT WINDSCREEN SEALANT
FRONT WINDSCREEN SPONGE
FRONT DOOR TRIMBOARD RH CLIPS
FRONT TYRE RH
BRAKE FLUID
COOLANT

11 \$60.00 30 SIN
11 \$60.00X
11 \$20.00X
11 \$80.00 30 SIN
11 \$80.00X
11 \$80.00X
11 \$100.00X
11 \$80.00X
11 \$80.00X
50 \$300.00X
11 \$60.00X
11 \$80.00X
\$1,080.00

TO CHECK FRONT WIRING AND HEADLAMP LEVELING
TO REMOVE AND REPLACE AIRCON CONDENSER, RECHARGE A/C GAS

TO REMOVE AND REPLACE RADIATOR, CONDUCT WATER PRESSURE TEST
TO REPLACE FRONT WINDSCREEN
TO REMOVE AND REPLACE FRONT UNDERCARRIAGE PARTS
TO CONDUCT WHEEL ALIGNMENT X2
TO REPLACE FRONT TYRE RH AND BALANCING
TO PROVIDE LABOUR, WORKMANSHIP TO CHANGE THE ABOVE
DAMAGED BODYPARTS, REPAIR, RE-CONSTRUCT AND RE-ALIGN BODY STRUCTURE, BODY ALIGNMENTS AND DAMAGED CONSISTENT TO THE ACCIDENT.
TO SPRAY PAINT ON AFFECTED PANELS
TO REMOVE AND REPLACE FRONT DOOR RH FITTINGS
RUST PROOFING
TO COMPUTER DIAGNOSE, CALIBRATE AND RESET SYSTEM

\$80.00 30
11 \$160.00X
11 \$120.00X
11 \$150.00X
\$600.00 350
\$240.00 60
11 \$120.00X
\$2,000.00 900
\$2,000.00 900
\$80.00 50
\$150.00 60
\$300.00 50
\$6,000.00

Total

\$42,754.94

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

2- 11668.70
107

P- 10501.83

S.N- 240

L- 2400

1314183
202

10513