



ComfortDelGro Engineering

205 Braddell Road S(579701)

ACCIDENT REPAIR ESTIMATES

Our Ref:

Type of Claim : TP(CT)Ins Company : III

Excess : _____

Date of Accident : 10/7/2024

Suggested Days of Repair : _____

Repair Estimates

Parts (a) Cost / List Price Items	\$ 19,239.00
Plus/Less 25%	\$ 4,809.75
Total of Cost / List	\$ 14,429.25
(b) Nett Price Items	_____
Less	_____
Total of Nett Item	_____
(c) Special Nett Items	\$ 796.00
Total Parts Cost (Appendix A)	\$ 15,225.25
Labour (Appendix B)	\$ 2,730.00
Total Repair Cost	\$ 17,955.25

The above total will be subjected to 9% G.S.T.

Vehicle No. : SMY6064R
 Make & Model : TOYOTA NOAH
 Year of Manufacture : 2020
 Chassis No. : ZWR800439098
 Engine No. : 2ZR0F41904
 Policy No. : _____
 Time of Accident : _____
 In-house Vehicle Assessor : _____
 Case Owner : KELVIN
 Signature : _____

Operation

KELVIN SU
 TEL: 9786 4236
 E: kelvinsukwen@cdge.com.sg

SUN PIN
 TEL: 9728 8916
 E: oisunpin@cdge.com.sg

Not Authorized
Runway B4 pain
11 Sep @ 8800h

Name of Surveyor : Kenneth
 Company : CKK
 Survey conducted on : 18/7/24 at _____

Remarks By Surveyor(a) The repair of this vehicle is authorized / is not authorized until further notice.(b) Recommended Days of Repair : 07 day(s)(c) Resurvey : Required / Not Required(d) Excess : \$ _____ De

(e) Signature of surveyor : _____

Date: 18/7/24

Spark Car Care

ComfortDelGro Engineering Pte Ltd

205 Braddell Road S (579701)

Tel: 63837168 / 63837466 Fax:62815767

Spare Parts

Vehicle No : SMY6064R

Case Owner : KELVIN

Make & Model : TOYOTA NOAH

Year Manufacture : 2020

Chassis No : ZWR800439098

Engine No : 2ZR0F41904

Sales Order : _____

Supplier : _____

Order By : KELVIN

Type of Claim : TP(CT)

S/No	DESCRIPTION	QTY	Cost Price	List Price	S/N	Disposition By Surveyor
1	REAR TAILGATE <i>1812.70</i>	1	<i>R</i>	\$ 2,705.00		<i>✓</i>
2	REAR TAILGATE WEATHERSTRIP <i>375.40</i>	1	<i>Di/1/Pd</i>	\$ 505.00		<i>✓</i>
3	REAR TAILGATE LOCK	1	<i>R</i>	\$ 635.00		<i>X</i>
4	REAR TAILGATE HINGE-RH	1	<i>R</i>	\$ 176.00		<i>X</i>
5	REAR TAILGATE HINGE-LH	1	<i>R</i>	\$ 176.00		<i>X</i>
6	TAILGATE EMBLEM"HYBRID"	1	<i>R</i>	\$ 65.00		<i>✓</i>
7	TAILGATE OUTER GARNISH <i>767.40</i>	1	<i>CM</i>	\$ 1,155.00		<i>✓</i>
8	TAILGATE CLOSE HANDLE	1	<i>R</i>	\$ 25.00		<i>✓</i>
9	TAILGATE NO. PLATE LAMP	2	<i>R</i>	\$ 176.00		<i>X</i>
10	TAILGATE INNER TRIM BOARD	1	<i>R</i>	\$ 635.00		<i>✓</i>
11	TRIM BOARD CLIPS	10		<i>R</i> \$ 30.00		<i>✓</i>
12	REAR BUMPER	1	<i>R</i>	\$ 810.00		<i>✓</i>
13	REAR BUMPER CLIPS	10		<i>R</i> \$ 30.00		<i>✓</i>
14	RHR BUMPER RETAINER	1	<i>Di/1</i>	\$ 120.00		<i>✓</i>
15	LHR BUMPER RETAINER	1	<i>Di/1</i>	\$ 120.00		<i>✓</i>
16	REAR BUMPER TOW COVER	1	<i>R</i>	\$ 40.00		<i>X</i>
17	REAR BUMPER REFLECTOR -RH	1	<i>R</i>	\$ 65.00		<i>X</i>
18	REAR BUMPER REFLECTOR -LH	1	<i>R</i>	\$ 65.00		<i>X</i>
19	RHR CORNER PANEL	1	<i>R</i>	\$ 235.00		<i>X</i>
20	RHR CORNER PANEL BRACKET	1	<i>R</i>	\$ 150.00		<i>X</i>
21	LHR CORNER PANEL	1	<i>CM</i>	\$ 235.00		<i>✓</i>
22	LHR CORNER PANEL BRACKET	1	<i>R</i>	\$ 150.00		<i>X</i>
23	RHR TAILLAMP <i>685.10</i>	1	<i>R</i>	\$ 2,038.00		<i>✓</i>
24	LHR TAILLAMP <i>685.10</i>	1	<i>Di/1/R/CM</i>	\$ 2,038.00		<i>✓</i>
25	REAR END PANEL <i>735.70</i>	1	<i>R</i>	\$ 1,100.00		<i>✓</i>
26	END PANEL TRIM BOARD	1	<i>R</i>	\$ 210.00		<i>✓</i>
27	SPARE TYRE COMPARTMENT	1	<i>R</i>	\$ 550.00		<i>X</i>
28	LUGGAGE BOARD DECK <i>691</i>	1	<i>CM</i>	\$ 1,500.00		<i>✓</i>
29	RHR FENDER INNER TRIM BOARD	1	<i>R</i>	\$ 795.00		<i>✓</i>
30	LHR FENDER INNER TRIM BOARD	1	<i>R</i>	\$ 795.00		<i>✓</i>

Note: If any of the quoted parts are recommended to be repaired, then an additional labour charge will be charged accordingly under supplementary.

Spark Car Care

ComfortDelGro Engineering Pte Ltd
205 Braddell Road S (579701)
Tel: 63837168 / 63837466 Fax: 62815767

Spare PartsVehicle No : SMY6064RCase Owner : KELVINMake & Model : TOYOTA NOAHYear Manufacture : 2020Chassis No : ZWR800439098Engine No : 2ZR0F41904Sales Order : 0Supplier : 0Order By : KELVINType of Claim : TP(CT)

S/No	Part Description	QTY	Cost Price	List Price	S/N	Disposition By Surveyor
31	REVERSE SENSOR	1		<i>Nil</i>	\$ 280.00	<i>2020</i>
32	REAR WINDSCREEN <i>1488-10</i>	1	<i>Shattered</i>	\$ 1,850.00		<i>✓</i>
33	REAR W/S MOULDING	2	<i>Nil</i>	\$ 120.00		<i>✓</i>
34	SEALANT	1		<i>Nil</i>	\$ 40.00	<i>✓</i>
35	REAR NO. PLATE	1		<i>Nil</i>	\$ 40.00	<i>X</i>
36	PHV DECAL	1		<i>Nil</i>	\$ 50.00	<i>2020</i>
37	SOLAR FILM	1		<i>Nil</i>	\$ 300.00	<i>1520</i>
38	INNER SEAL	1		<i>Nil</i>	\$ 26.00	<i>✓</i>
39						
40						
41						
42						
43						
44						
45						
46						
47						
48						
49						
50						
51						
52						
53						
54						
55						
56						
57						
58						
59						
60						

KK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Note: If any of the quoted parts are recommended to be repaired, then an additional labour charge will be charged accordingly under supplementary.

Tel: 63837168 / 63837466 Fax: 62815767

Note: The above estimate of repair is based on visual assessment of the external affected areas. Any additional damages observed during the course of repair will be quote accordingly as a supplementary.