

ASS. REC. BY:

REF:

09/C1224070250/Kap3

C

Kenneth

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / QD RES / EVA / INV / MY

To inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value:

155K

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

07

days

Res.: Yes or No

Lum Sum:

2018.7

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Date / Time

Action / Instruction

16/9 21 Rm @ 8800. Car used to 9155.75, 51%

Date/Time, File Pass to?

18/9 10:15

Date/Time, File Return to?

2)

☐

: Prell. Report

☐

: Final Report

Days Of Repair:

2

Resurvey No. of Trip:

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech Invs (\$

☐

: Weekend (\$

Survey Fee:

Transportation:

S - RS. SI

: Pairs

: Others

TOTAL

Report Format :

E2 Claims - TP

Lump Sum / I.B.H. (\$

8800



ComfortDelGro Engineering

205 Braddell Road S(579701)

ACCIDENT REPAIR ESTIMATES

Our Ref:

Type of Claim : TP(CT)Vehicle No. : SMY6064RMake & Model : TOYOTA NOAHYear of Manufacture : 2020Chassis No. : ZWR800439098Ins Company : IIIEngine No. : 2ZR0F41904

Excess : _____

Policy No. : _____

Date of Accident : 10/7/2024

Time of Accident : _____

Suggested Days of Repair : _____

In-house Vehicle Assessor

Repair EstimatesCase Owner : KELVIN

Signature : _____

Parts (a) Cost / List Price Items \$ 19,239.00Plus/Less 25% \$ 4,809.75Total of Cost / List \$ 14,429.25

(b) Nett Price Items _____

Less _____

Total of Nett Item _____

(c) Special Nett Items \$ 796.00Total Parts Cost (Appendix A) \$ 15,225.25Labour (Appendix B) \$ 2,730.00Total Repair Cost \$ 17,955.25**Operation**

KELVIN SU

TEL: 9786 4236

E: kelvinsukwen@cdge.com.sg

SUN PIN

TEL: 9728 8916

E: oisunpin@cdge.com.sg

Not Authorized
Resurvey B4 pain
L1 Imp @ 8800h

The above total will be subjected to 9% G.S.T.

Name of Surveyor : Kennerh
 Company : CKK
 Survey conducted on : 10/7/24 at _____

Remarks By Surveyor(a) The repair of this vehicle is ~~authorized~~ / is not authorized until further notice.(b) Recommended Days of Repair : 07 day(s)(c) Resurvey : Required / ~~Not Required~~

(d) Excess : \$ _____

(e) Signature of surveyor : De Date: 10/7/24

Spark Car Care

ComfortDelGro Engineering Pte Ltd

205 Braddell Road S (579701)

Tel: 63837168 / 63837466 Fax:62815767

Spare Parts

Vehicle No : SMY6064R Case Owner : KELVIN

Make & Model : TOYOTA NOAH Year Manufacture : 2020

Chassis No : ZWR800439098 Engine No : 2ZR0F41904

Sales Order : _____ Supplier : _____

Order By : KELVIN Type of Claim : TP(CT)

S/No	DESCRIPTION	QTY	Cost Price	List Price	S/N	Disposition By Surveyor
1	REAR TAILGATE <i>1812.70</i>	1	<i>R</i>	\$ 2,705.00		<i>✓</i>
2	REAR TAILGATE WEATHERSTRIP <i>375.10</i>	1	<i>Dis / Au</i>	\$ 505.00		<i>✓</i>
3	REAR TAILGATE LOCK	1	<i>R</i>	\$ 635.00		<i>X</i>
4	REAR TAILGATE HINGE-RH	1	<i>R</i>	\$ 176.00		<i>X</i>
5	REAR TAILGATE HINGE-LH	1	<i>R</i>	\$ 176.00		<i>X</i>
6	TAILGATE EMBLEM "HYBRID"	1	<i>Ne</i>	\$ 65.00		<i>✓</i>
7	TAILGATE OUTER GARNISH <i>767.40</i>	1	<i>CM</i>	\$ 1,155.00		<i>✓</i>
8	TAILGATE CLOSE HANDLE	1	<i>Ne</i>	\$ 25.00		<i>✓</i>
9	TAILGATE NO. PLATE LAMP	2	<i>3m</i>	\$ 176.00		<i>X</i>
10	TAILGATE INNER TRIM BOARD	1	<i>Bu</i>	\$ 635.00		<i>✓</i>
11	TRIM BOARD CLIPS	10		<i>Ne</i> \$ 30.00		<i>✓</i>
12	REAR BUMPER	1	<i>R</i>	\$ 810.00		<i>✓</i>
13	REAR BUMPER CLIPS	10		<i>Ne</i> \$ 30.00		<i>✓</i>
14	RHR BUMPER RETAINER	1	<i>Dis</i>	\$ 120.00		<i>✓</i>
15	LHR BUMPER RETAINER	1	<i>Dis</i>	\$ 120.00		<i>✓</i>
16	REAR BUMPER TOW COVER	1	<i>Sm</i>	\$ 40.00		<i>X</i>
17	REAR BUMPER REFLECTOR -RH	1	<i>Sm</i>	\$ 65.00		<i>X</i>
18	REAR BUMPER REFLECTOR -LH	1	<i>Sm</i>	\$ 65.00		<i>X</i>
19	RHR CORNER PANEL	1	<i>R</i>	\$ 235.00		<i>X</i>
20	RHR CORNER PANEL BRACKET	1	<i>R</i>	\$ 150.00		<i>X</i>
21	LHR CORNER PANEL	1	<i>CM</i>	\$ 235.00		<i>✓</i>
22	LHR CORNER PANEL BRACKET	1	<i>R</i>	\$ 150.00		<i>X</i>
23	RHR TAILLAMP <i>685.10</i>	1	Cut <i>Ne</i>	\$ 2,038.00		<i>✓</i>
24	LHR TAILLAMP <i>685.10</i>	1	<i>Dis / mg CM</i>	\$ 2,038.00		<i>✓</i>
25	REAR END PANEL <i>735.70</i>	1	<i>Bt</i>	\$ 1,100.00		<i>✓</i>
26	END PANEL TRIM BOARD	1	<i>Ne</i>	\$ 210.00		<i>✓</i>
27	SPARE TYRE COMPARTMENT	1	<i>R</i>	\$ 550.00		<i>X</i>
28	LUGGAGE BOARD DECK <i>691</i>	1	<i>CM</i>	\$ 1,500.00		<i>✓</i>
29	RHR FENDER INNER TRIM BOARD	1	<i>Bu</i>	\$ 795.00		<i>✓</i>
30	LHR FENDER INNER TRIM BOARD	1	<i>Bu</i>	\$ 795.00		<i>✓</i>

Note: If any of the quoted parts are recommended to be repaired, then an additional labour charge will be charged accordingly under supplementary.

Spark Car Care
ComfortDelGro Engineering Pte Ltd
 205 Braddell Road S (579701)
 Tel: 63837168 / 63837466 Fax:62815767

Spare Parts

Vehicle No : SMY6064R Case Owner : KELVIN

Make & Model : TOYOTA NOAH Year Manufacture : 2020

Chassis No : ZWR800439098 Engine No : 2ZR0F41904

Sales Order : 0 Supplier : 0

Order By : KELVIN Type of Claim : TP(CT)

S/No	Part Description	QTY	Cost Price	List Price	S/N	Disposition By Surveyor
31	REVERSE SENSOR	1		<i>Nil</i>	\$ 280.00	<i>2020</i>
32	REAR WINDSCREEN <i>1488-10</i>	1	<i>Shatter</i>	\$ 1,850.00		<i>✓</i>
33	REAR W/S MOULDING	2	<i>Nil</i>	\$ 120.00		<i>✓</i>
34	SEALANT	1		<i>Nil</i>	\$ 40.00	<i>✓</i>
35	REAR NO.PLATE	1		<i>Nil</i>	\$ 40.00	<i>X</i>
36	PHV DECAL	1		<i>Nil</i>	\$ 50.00	<i>2020</i>
37	SOLAR FILM	1		<i>Nil</i>	\$ 300.00	<i>1520</i>
38	INNER SEAL	1		<i>Nil</i>	\$ 26.00	<i>✓</i>
39						
40						
41						
42						
43						
44						
45						
46						
47						
48						
49						
50						
51						
52						
53						
54						
55						
56						
57						
58						
59						
60						

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Note: If any of the quoted parts are recommended to be repaired, then an additional labour charge will be charged accordingly under supplementary.

Tel: 63837168 / 63837466 Fax: 62815767

Note: The above estimate of repair is based on visual assessment of the external affected areas. Any additional damages observed during the course of repair will be quote accordingly as a supplementary.