

YSK AUTO

1 KAKI BUKIT AVENUE 6
#01-71 AUTOBAY SINGAPORE 417883

TO	: CHINA TAIPING	DATE	14/8/2024
VEHICLE NO	: PC8250L (2019)		
VEHICLE MODEL	: HIGER KLQ6118K		
CHASSIS NO	: LKLR1GSJ7JA728211		

CLAIM DETAILS: PARTS

	ITEMS	QTY	UNIT PRICE	TOTAL
1	FRONT SIDE MIRROR ASSY <i>Damaged</i>	1	\$ 3,800.00	\$ 3,800.00
TOTAL PRICE:				\$ 3,800.00
L SS 10%				\$ 380.00
SUB TOTAL PRICE:				\$ 3,420.00

LABOUR

	JOB	PRICE	ADJUSTED COST	APPROVED
1	PANEL BEATING, REMOVE AND REFIT PARTS	\$ 400.00	<i>200</i>	
2	SPRAY PAINTING TO AFFECTED AREA	\$ 400.00	<i>200</i>	
3	WIRING CHECK	\$ 100.00	<i>30</i>	
TOTAL:		\$ 900.00		

ESTIMATE REPORT

TOTAL PARTS COST: \$ 3,420.00

TOTAL LABOUR COST: \$ 900.00

TOTAL REPAIR COST: \$ 4,320.00

total: 2410
ys: 1.9k.
02 Days.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

1.9k.