PING MOTOR PTE.LTD.

1 KAKI BUKIT AVE 6
#01-25 Auto bay @Kaki Bukit
Singapore 417883
Tel: 93419033

Not Arthrest Moras
17/7/24
1/5 # 2200

	VEHICLE No: SLG 9122	г		NETT ITEM
1PC 1PC 1PC 1PC 1PC 1PC 1SET 1PC	REAR BUMPER REAR BUMPER LOWER B REAR BUMPER REFLECTO REAR BUMPER RETAINER REAR BUMPER REINFORG REAR BUMPER LOWER U RAER BUMPER CLIPS RAER AIR VENT O/S REAR END PANEL	CAT/BE LACK CAT OR O/S SCA LO/S CAQ CEMENT CAR NDER COVER O/S TOICE ALL EMA		\$688.00 \$241.00 \$48.00 \$45.00 \$318.00 \$82.00 \$45.00 \$92.00 \$368.00 X
1PC	TAILLAMP O/S	11		\$695.00× \$2,622.00
			LESS 10%	\$2,359.80

TO CHECK WIRING	\$50.00 20
TO DISMANTLE & REFIX REAR REVERSE SENSOR	\$50.00 40
TO DISMANTLE & REFIX CUSHION UPHOLSTERY	\$80.00
TO SPRAY RUST PROOFING	\$50.00 3.0
TO RESET & REPROGRAMME SYSTEM	17 \$100.00 X
LABOUR FOR PANEL BEATING & REPLACED PARTS	\$800.00\$20
TO PUTTY & SPRAY PAINTING	\$850.00 60 17
	TOTAL \$4,339.80

LKK Auto Consultants hence notify
the Repairer of the following:

To resurvey before/after spray pointing
To display damaged party, Juding resurvey
Parts prices are subject to confirmation
Third party survey is on a "Without Projudice" bands
No illegal modification(s) is allowed
Supplementary item(s) must be resurveyed and, is subject to final approval from Insurance Company
Acknowledged by Repairer
Signature:
Date:

1403.1 1403.1 1350 2753.10 202