

ASS. REC. BY:

REF: MSG /Kenneth

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s JDof 059H

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value: \$ 10,500

IDAC Accident Report: _____ Consistent?: Yes or No

GIA / PR Seen: _____ Consistent?: Yes or No

R Est. Repairs: 07 days Res.: Yes or NoLum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Veh No: SKQ 3905A Yr Regn: 11, 14Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /Truck / Trailer or (A)Make: Mazda 6 C.C. 1998Colour: M. Grey A/C: Insured / Std / NI / NASp. Reading: 134749 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: JM 66J 10711-0147312Gen. Cond: Good / Fair / Poor / BurntSteering: In order / Jammed / Leaked / Burnt orBrake: In order / Jammed / Leaked / Burnt orMod: NI / S/Rim / STD A/Rim or

Tyre Size: F: _____

R: 225/55R17BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front _____ Rear _____

R/Bal. 9 mm R/Bal. 9 mmL/Bal. 9 mm L/Bal. 9 mmD.O.A. 13/7/24 D.O.I. 16/7/2024

Survey held at _____

Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or

O/S Rear & u/c

The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time _____ Action / Instruction _____

Date/Time, File Pass to?

☐ : Prel. Report

Days Of Repair: _____

1) _____

☐ : Final Report

Resurvey No. of Trip: _____

Date/Time, File Return to?

Survey Fee:

Transportation:

S - RS. SI

P. Repairs

Others

Add Fee: ☐ : Site Insp (\$)☐ : Interview (\$)☐ : Tech Invs (\$)☐ : Weekend (\$)

Report Format :

Lump Sum / I.B.I. (\$) _____

TOTAL



MOTORSPORTS

JD MOTORSPORTS PTE LTD

25 KAKI BUKIT RD 4 # 05-76 SYNERGY @ KB S417800

DATE : 16/7/2024
VEHICLE : SKQ3905A
MAKE/MODEL : MAZDA 6
CHASSIS NO : JM6GJ1071P0147312
MILLAGE :
TYRE SIZE : 225/55/R17
DOA : 13/7/2024

Not Notarized
1 Pay @
Money After Paying
7 days

List items

01 PC	REAR BUMPER
01 PC	REAR BUMPER RH SIDE RENTAINER
01 PC	REAR RH FENDER
01 PC	REAR RH INNER SHEILD
01 PC	REAR RH FENDER INNER PANEL
01 PC	REAR RH FENDER INNER TRIM BOARD
01 PC	REAR RH DOOR
01 PC	REAR RH DOOR INNER LOCK
01 PC	REAR RH DOOR CATCH LOCK
01 PC	REAR RH DOOR INNER PANEL BOARD
01 PC	REAR RH DOOR WEATHSTRIP
01 PC	REAR RH WHEEL BEARING
01 PC	REAR RH KNCKLER
01 PC	REAR RH LOWER ARM
01 PC	REAR RH UPPER ARM
01 PC	REAR RH TRAILING ARM
01 PC	REAR RH ABSORBER
01 PC	REAR RH SUSPENSION ARM

Buc/mg um
\$ 2,172.20
\$ 67.95
\$ 2,392.05
\$ 324.70
\$ 2,238.90
\$ 1,038.00
\$ 2,424.60
\$ 438.80
\$ 37.45
\$ 685.30
\$ 314.75
\$ 566.10
\$ 913.45
\$ 203.30
\$ 352.10
\$ 406.60
\$ 699.76
\$ 203.30
\$ 15,479.31

TOTAL PARTS COST

Special Net Item:

05 PC	REAR BUMPER CLIP @ \$6.00
08 PC	REAR RH INNER SHEILD CLIP @ \$6.00
01 PC	REAR RH RIM
01 PC	REAR RH TYRES
01 PC	WINDSCREEN SEALANT

\$ 30.00
\$ 48.00
\$ 850.00
\$ 250.00
\$ 80.00
\$ 1,258.00

Labour:

1. TO SUPPLY PARTS & LABOUR TO REPLACE ABOVE MENTIONED PARTS
2. TO SUPPLY PAINT & LABOUR TO SPRAY ACCIDENT AFFECT AREA
3. TO SUPPLY LABOUR TO REMOVE AND REFIX REAR WINDSCREEN
4. TO SUPPLY LABOUR TO DISMANTLE AND REFIX UNDER CARRIGE
5. TO SUPPLY LABOUR TO DISMANTLE REAR DOOR FACILITATE THE DOOR
6. TO SUPPLY LABOUR TO DISMANTLE REAR FENDER INNER PANEL UPHOLSTERY
7. TO SUPPLY LABOUR TO CONDUCT WHEEL ALIGMENT
8. TO SUPPLY LABOUR TO CONDUCT WHEEL BALANCING
9. TO SUPPLY LABOUR TO SPRAY ANTI RUST ON PANEL
10. TO SUPPLY LABOUR TO REWIRE REPLACE PARTS

\$ 1,500.00
\$ 1,000.00
\$ 250.00
\$ 300.00
\$ 250.00
\$ 250.00
\$ 150.00
\$ 50.00
\$ 250.00
\$ 200.00
\$ 4,200.00

TOTAL PARTS

SPECIAL NETT ITEM

TOTAL LABOUR

TOTAL COST OF REPAIR

\$ 15,479.31
\$ 1,258.00
\$ 4,200.00
\$ 20,937.31

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: