



MOTORSPORTS

JD MOTORSPORTS PTE LTD

25 KAKI BUKIT RD 4 # 05-76 SYNERGY @ KB S417800

DATE : 16/7/2024
VEHICLE : SKQ3905A
MAKE/MODEL : MAZDA 6
CHASSIS NO : JM6GJ1071P0147312
MILLAGE :
TYRE SIZE : 225/55/R17
DOA : 13/7/2024

Not Authorized
1 Day @ 5000p. Max
Return After 7 days

List items

01 PC	REAR BUMPER	1120.17	Buc/m3um	\$ 2,172.20	✓
01 PC	REAR BUMPER RH SIDE RENTAINER		\$ PTJ	67.95	✓
01 PC	REAR RH FENDER	1254.40	R1	2,392.05	✓
01 PC	REAR RH INNER SHEILD	118.20	cm	324.70	✓
01 PC	REAR RH FENDER INNER PANEL		R	2,238.90	X
01 PC	REAR RH FENDER INNER TRIM BOARD		in	1,038.00	X
01 PC	REAR RH DOOR	1312.10	Bilwarp	2,424.60	✓
01 PC	REAR RH DOOR INNER LOCK		\$ R	438.80	X
01 PC	REAR RH DOOR CATCH LOCK		\$ R	37.45	X
01 PC	REAR RH DOOR INNER PANEL BOARD		\$ in	685.30	X
01 PC	REAR RH DOOR WEATHSTRIP		\$ R	314.75	X
01 PC	REAR RH WHEEL BEARING	280.50	\$ R	566.10	✓
01 PC	REAR RH KNCKLER	482.30	\$ R	913.45	✓
01 PC	REAR RH LOWER ARM		\$ R	203.30	X
01 PC	REAR RH UPPER ARM		\$ R	352.10	X
01 PC	REAR RH TRAILING ARM		\$ R	406.60	X
01 PC	REAR RH ABSORBER	308.20	\$ R	699.76	✓
01 PC	REAR RH SUSPENSION ARM		\$ R	203.30	X
TOTAL PARTS COST				\$ 15,479.31	208

Special Nett Item:

05 PC	REAR BUMPER CLIP @ \$6.00	\$ R	30.00	✓
08 PC	REAR RH INNER SHEILD CLIP @ \$6.00	\$ R	48.00	✓
01 PC	REAR RH RIM	nd	850.00	680
01 PC	REAR RH TYRES	\$ R	250.00	X
01 PC	WINDSCREEN SEALANT	R	80.00	405n
				\$ 1,258.00

Labour:

1. TO SUPPLY PARTS & LABOUR TO REPLACE ABOVE MENTIONED PARTS	\$ 1,500.00	800l
2. TO SUPPLY PAINT & LABOUR TO SPRAY ACCIDENT AFFECT AREA	\$ 1,000.00	660l
3. TO SUPPLY LABOUR TO REMOVE AND REFIX REAR WINDSCREEN	\$ 250.00	120l
4. TO SUPPLY LABOUR TO DISMANTLE AND REFIX UNDER CARRIGE	\$ 300.00	120l
5. TO SUPPLY LABOUR TO DISMANTLE REAR DOOR FACILITATE THE DOOR	\$ 250.00	60l
6. TO SUPPLY LABOUR TO DISMANTLE REAR FENDER INNER PANEL UPHOLSTERY	\$ 250.00	100h
7. TO SUPPLY LABOUR TO CONDUCT WHEEL ALIGMENT	\$ 150.00	60l
8. TO SUPPLY LABOUR TO CONDUCT WHEEL BALANCING	\$ 50.00	20h
9. TO SUPPLY LABOUR TO SPRAY ANTI RUST ON PANEL	\$ 250.00	60l
10. TO SUPPLY LABOUR TO REWIRE REPLACE PARTS	\$ 200.00	20l
		\$ 4,200.00

TOTAL PARTS

SPECIAL NETT ITEM

TOTAL LABOUR

TOTAL COST OF REPAIR

\$ 15,479.31

\$ 1,258.00

\$ 4,200.00

\$ 20,937.31

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: