

FONG MOTORS

Vehicle No: SMF3518T (2018)

MAKE & MODEL: TOYOTA ALTIS

CHASSIS NUMBER: MR053REH604592210

TPA19.

Yen.

LIST ITEM

S/N	DESCRIPTION	QTY	UNIT PRICE	TOTAL PRICE
1	REAR NUMBER PLATE LAMP <i>new</i>	2	\$ 87.00	\$ 174.00
2	BOOTLID <i>Deleted</i>	1	\$ 859.60	\$ 859.60
3	BOOTLID INSULATOR <i>new</i>	1	\$ 176.40	\$ 176.40
4	BOOTLID LAMP <i>cut</i>	2	\$ 342.00	\$ 684.00
5	BOOTLID OUTER MOULDING (CHROME) <i>deleted</i>	1	\$ 426.00	\$ 426.00
6	BOOTLID DETECTOR <i>new</i>	1	\$ 385.00	\$ 385.00
7	BOOTLID LOGO	1	\$ 85.00	\$ 85.00
8	BOOTLID EMBLEM 'COROLLA' <i>new</i>	1	\$ 70.00	\$ 70.00
9	BOOTLID EMBLEM 'ALTIS'	1	\$ 70.00	\$ 70.00
10	BOOT LID HINGE <i>new</i>	2	\$ 70.00	\$ 140.00
11	BOOTLID TOP LOCK <i>new</i>	1	\$ 318.10	\$ 318.10
12	BOOTLID LOWER LOCK <i>new</i>	1	\$ 20.00	\$ 20.00
13	BOOTLID WEATHERSTRIP <i>cut</i>	1	\$ 195.00	\$ 195.00
14	REAR BOOTLID OUTER SWITCH BUTTON <i>new</i>	1	\$ 328.00	\$ 328.00
15	TAILLAMP <i>cut</i>	2	\$ 465.00	\$ 930.00
16	TAILLAMP LOWER BARCKET <i>new</i>	2	\$ 115.10	\$ 230.20
17	TAILLAMP PANEL <i>new</i>	2	\$ 198.00	\$ 396.00
18	REAR FENDER INNER TRIM <i>new</i>	2	\$ 350.60	\$ 701.20
19	REAR END PANEL <i>new</i>	1	\$ 695.30	\$ 695.30
20	REAR END PANEL TOP GARNISH <i>Deleted</i>	1	\$ 250.10	\$ 250.10
21	REAR FLOOR PANEL TOP BOARD <i>new</i>	1	\$ 271.10	\$ 271.10
22	REAR FLOOR PANEL <i>new</i>	1	\$ 940.20	\$ 940.20
23	REAR BUMPER <i>Deleted</i>	1	\$ 581.90	\$ 581.90
24	REAR BUMPER REINFORCEMENT <i>Deleted</i>	1	\$ 386.60	\$ 386.60
25	REAR BUMPER REINFORCEMENT BRACKET <i>new</i>	2	\$ 87.30	\$ 174.60
26	REAR BUMPER REFLECTOR <i>new</i>	2	\$ 75.10	\$ 150.20
27	REVERSE SENSOR <i>Deleted</i>	2	\$ 311.10	\$ 622.20
28	REVERSE CAMERA <i>and</i>	1	\$ 986.70	\$ 986.70
29	REVERSE SENSOR RING <i>new</i>	2	\$ 10.50	\$ 21.00
30	REVERSE SENSOR WIRE HARNESS <i>new</i>	1	\$ 437.50	\$ 437.50
31	REAR SPARE TYRE BOLT <i>new</i>	1	\$ 40.10	\$ 40.10
32	REAR EXHAUST PIPE	1	\$ 781.10	\$ 781.10
33	REAR EXHAUST PIPE MOUNTING <i>new</i>	1	\$ 38.90	\$ 38.90
34	REAR EXHAUST PIPE GASKET <i>new</i>	1	\$ 35.60	\$ 35.60
35	REAR EXHAUST PIPE HEAT SHIELD <i>new</i>	1	\$ 122.10	\$ 122.10

5499.50

4124.62

S.N: H50

TOTAL PRICE \$ 12,723.70

LESS 25% \$ 3,180.93

SUB TOTAL PRICE \$ 9,542.78

SPECIAL NETT ITEM

S/N	DESCRIPTION	QTY	UNIT PRICE	TOTAL PRICE
1	REAR NUMBER PLATE <i>new</i>	1	\$ 30.00	\$ 30.00
2	REAR NUMBER PLATE HOLDER <i>new</i>	1	\$ 30.00	\$ 30.00
3	REAR BUMPER CLIPS (SET) <i>new</i>	1	\$ 50.00	\$ 50.00
4	BOOT LID INSULATOR CLIP (SET) <i>new</i>	1	\$ 30.00	\$ 30.00

5	TAILLAMP CLIPS (SET)	2	\$ 15.00	\$ 30.00	x
6	TAILLAMP PANEL SEALANT	2	\$ 30.00	\$ 60.00	x
9	REAR FENDER INNER TRIM CLIPS (SET)	2	\$ 30.00	\$ 60.00	x
13	REAR END PANEL TOP GARNISH CLIPS (SET)	1	\$ 20.00	\$ 20.00	✓
14	REAR END PANEL INSULATION SEAL	1	\$ 60.00	\$ 60.00	x
15	REAR FLOOR PANEL INSULATION SEAL	1	\$ 200.00	\$ 200.00	x
16	REAR FLOOR PANEL SEALANT	1	\$ 60.00	\$ 60.00	x

50

TOTAL \$ 630.00

CLAIM DETAILS: LABOUR AND SPRAY PAINTING

S/N	JOB DESCRIPTION	PRICE	ADJUSTED COST
1	PANEL BEATING	\$ 1,200.00	600
2	TO SPRAY PAINT	\$ 1,000.00	600
3	TUFF COAT	\$ 150.00	30
4	WIRING CHECK	\$ 50.00	30
5	REMOVE UPHOLSTRY	\$ 150.00	40
6	REMOVE REVERSE SENSOR	\$ 100.00	50
7	REMOVE REAR CAMERA	\$ 100.00	50
8	TRANSFER BOOTLID MECHANISM	\$ 150.00	60
9	REMOVE REAR EXHAUST PIPE	\$ 150.00	x

TOTAL \$ 3,050.00

1460

TOTAL PARTS COST : \$ 10,172.78
TOTAL LABOUR COST : \$ 3,050.00
TOTAL REPAIR COST : \$ 13,222.78

Total: 6084.62

4/5: A8K

05 Days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

A.8K ✓