

2020 SPRAY PAINTING PTE LTD
8 KAKI BUKIT AVE 4
#03-19 PREMIER @KAKI BUKIT
SINGAPORE 415875

VEHICLE NO	: SLC2195A (2016)	DATE	12/6/2024
VEHICLE MODEL	: HONDA JAZZ	Xiao Chen.	
CHASSIS NO	: JHMGK5850GX202282		

CLAIM DETAILS: PARTS

CLAIM DETAILS: PARTS		QTY	UNIT PRICE	TOTAL
1	REAR NUMBER PLATE LAMP <i>Not new</i>	2	\$ 54.20	\$ 108.40
2	REAR BUMPER <i>Defunct</i>	1	\$ 545.20	\$ 545.20
3	REAR BUMPER SIDE HOLDER <i>Not new</i>	2	\$ 24.20	\$ 48.40
4	REAR BUMPER SIDE GRILLE <i>Lit int</i>	2	\$ 69 58.00	\$ 138.00
5	REVERSE SENSOR <i>Revised</i>	2	\$ 165.20	\$ 330.40
6	REVERSE SENSOR HOLDER <i>Not new</i>	2	\$ 20.50	\$ 41.00
7	REAR END PANEL <i>Defunct</i>	1	\$ 355.00	\$ 355.00
8	REAR END PANEL TOP GARNISH <i>Not new</i>	1	\$ 121.60	\$ 121.60
9	REAR END PANEL ANTENNA SENSOR <i>Cracked</i>	1	\$ 118.90	\$ 118.90
10	REAR END PANEL BUZZER <i>Not new</i>	1	\$ 85.60	\$ 85.60
11	TAILLAMP <i>Lit int ? can reuse?</i>	2	\$ 282.00	\$ 564.00
12	TAILLAMP PANEL OUTER <i>Not new</i>	2	\$ 176.20	\$ 352.40
13	TAILLAMP PANEL INNER <i>Not new</i>	2	\$ 217.50	\$ 435.00
14	TAILGATE <i>Defunct</i>	1	\$ 845.90	\$ 845.90
15	TAILGATE LOCK <i>Damaged X not damaged</i>	1	\$ 161.80	\$ 161.80
16	TAILGATE LOCK STRIKER <i>Not new</i>	1	\$ 25.90	\$ 25.90
17	TAILGATE WEATHERSTRIPE <i>Not new</i>	1	\$ 138.50	\$ 138.50
18	TAILGATE INNER TRIM BOARD <i>Cracked</i>	1	\$ 285.90	\$ 285.90
19	TAILGATE INNER HOLDER <i>Not new</i>	1	\$ 34.20	\$ 34.20
20	TAILGATE LAMP <i>Lit int ? can reuse?</i>	2	\$ 193.50	\$ 387.00
21	TAILGATE OUTER CHROME GARNISH <i>Not new</i>	1	\$ 286.90	\$ 286.90
22	TAILGATE WIPER MOTOR <i>Not new</i>	1	\$ 362.40	\$ 362.40
23	TAILGATE WIPER ARM <i>Not new</i>	1	\$ 71.20	\$ 71.20
24	TAILGATE WIPER ARM COVER <i>Not new</i>	1	\$ 20.90	\$ 20.90
25	TAILGATE GLASS MOULDING <i>Not new</i>	1	\$ 95.40	\$ 95.40
26	REAR FENDER INNER TRIM BOARD <i>Not new</i>	2	\$ 258.40	\$ 516.80
27	REAR FENDER INNER SHIELD <i>Not new</i>	2	\$ 119.90	\$ 239.80
28	REAR FENDER AIR VENT <i>Not new</i>	2	\$ 57.10	\$ 114.20
29	REAR FENDER WHEEL HOUSE <i>Not new</i>	2	\$ 530.20	\$ 1,060.40
30	SPARE TYRE PANEL TOP BOARD <i>Not new</i>	1	\$ 287.60	\$ 287.60
31	SPARE TYRE PANEL TOOLS SPONGE TRAY <i>Not new</i>	1	\$ 262.40	\$ 262.40
32	HONDA LOGO <i>Not new</i>	1	\$ 35.40	\$ 35.40
33	JAZZ WORDING <i>Not new</i>	1	\$ 40.40	\$ 40.40
34	REAR EXHAUST PIPE <i>Not new</i>	1	\$ 552.80	\$ 552.80
35	REAR EXHAUST PIPE MOUNTING <i>Not new</i>	1	\$ 38.90	\$ 38.90
36	REAR EXHAUST PIPE GASKET <i>Not new</i>	1	\$ 32.50	\$ 32.50

37	REAR EXHAUST PIPE HEAT SHIELD	NEW	1	\$	120.60	\$	120.60	X
38	FRONT NUMBER PLATE GARNISH	Delaid	1	\$	86.60	\$	86.60	✓
39	FRONT BUMPER	Distorted	1	\$	538.20	\$	538.20	✓
40	FRONT BUMPER SIDE HOLDER	NEW	2	\$	25.90	\$	51.80	X
41	FRONT BUMPER TOW COVER	NEW	1	\$	26.60	\$	26.60	+
42	FRONT BUMPER REINFORCEMENT	Bent	1	\$	295.80	\$	295.80	✓
43	FRONT BUMPER LOWER GRILLE	Lot	1	\$	180.40	\$	180.40	✓
44	FRONT BUMPER FOG LAMP	Not Rec	2	\$	274.60	\$	549.20	+
45	FRONT BUMPER FOG LAMP COVER	LH cracked	2	\$	86.40 76.40	\$	172.80	86.40 ✓
46	FRONT BUMPER SIDE LAMP	LH cracked	2	\$	184.70	\$	369.40	184.70 ✓
47	FRON GRILLE	cracked	1	\$	267.50	\$	267.50	✓
48	FRONT GRILLE OUTER GARNISH	3 smashed	1	\$	176.20	\$	176.20	✓
49	FRONT GRILLE LOWER MOULDING		1	\$	166.90	\$	166.90	✓
50	FRONT GRILLE LOGO	Missing	1	\$	35.90	\$	35.90	✓
51	HEADLAMP	cracked	2	\$	1,176.60	\$	2,353.20	✓
52	HEADLAMP LOWER BRACKET	cracked	2	\$	57.60	\$	115.20	✓
53	BONNET	Distorted	1	\$	633.60	\$	633.60	✓
54	BONNET LOCK	damaged	1	\$	72.80	\$	72.80	✓
55	BONNET HINGE	Bent	2	\$	48.90	\$	97.80	✓
56	BONNET WEATHERSTRIPE	NEW	2	\$	24.90	\$	49.80	+
57	BONNET INSULATOR	For	1	\$	179.20	\$	179.20	✓
58	FRONT FENDER	LH cracked	2	\$	442.60	\$	885.20	442.60 ✓
59	FRONT FENDER INNER SHIELD	NEW	2	\$	121.30	\$	242.60	+
60	FRONT FENDER GLASS MOULDING	NEW LH	2	\$	40.80	\$	81.60	40.80 ✓
61	FRONT SUPPORT PANEL	Distorted	1	\$	517.80	\$	517.80	✓
62	FRONT SUPPORT PANEL TOP COVER	NEW	1	\$	106.50	\$	106.50	+
63	AIR CON CONDENSER	Distorted	1	\$	846.50	\$	846.50	✓
64	AIR CON CONDENSER SIDE GUIDE	Delaid	2	\$	30.40	\$	60.80	✓
65	AIR CON FAN COWLING	cracked	1	\$	193.90	\$	193.90	✓
66	AIR CON FAN MOTOR	Bent	1	\$	368.10	\$	368.10	✓
67	AIR CON FAN BLADE	NEW	1	\$	79.40	\$	79.40	+
68	RADIATOR	Distorted	1	\$	1,187.90	\$	1,187.90	✓
69	RADIATOR FAN COWLING	?	1	\$	185.90	\$	185.90	+
70	RADIATOR FAN MOTOR	Not Rec	1	\$	378.40	\$	378.40	+
71	RADIATOR FAN BLADE	Not Rec	1	\$	85.90	\$	85.90	+
72	RADIATOR SPARE TANK	Not Rec	1	\$	76.90	\$	76.90	+
73	AIR DUCT	Delaid	1	\$	85.90	\$	85.90	✓
74	FRONT SAFETY BELT	Activated	2	\$	625.30	\$	1,250.60	✓
75	STEERING WHEEL AIR BAG	Activated	1	\$	1,605.20	\$	1,605.20	✓
76	DASHBOARD	For	1	\$	930.90	\$	930.90	✓
77	DASHBOARD AIR BAG	Activated	1	\$	2,236.40	\$	2,236.40	✓
78	AIR BAG SENSOR		2	\$	314.20	\$	628.40	✓
79	AIR BAG ECU		1	\$	886.70	\$	886.70	✓
80	WIPER PANEL GARNISH	cracked	1	\$	321.30	\$	321.30	✓

TOTAL PRICE: \$ 28,815.00
L 55 20% \$ 5,763.00
SUB TOTAL PRICE: \$ 23,052.00

20106
1608480

SPECIAL NETT ITEMS

	ITEMS	QTY	UNIT PRICE	TOTAL
1	REAR NUMBER PLATE	1	\$ 30.00	\$ 30.00
2	REAR NUMBER PLATE HOLDER	1	\$ 30.00	\$ 30.00
3	REAR BUMPER CLIPS	1 SET	\$ 50.00	\$ 50.00
4	REAR CAMERA	1	\$ 480.00	\$ 480.00
5	REAR END PANEL TOP GARNISH CLIPS	1 SET	\$ 20.00	\$ 20.00

6	REAR END PANEL SEALANT <i>Neu</i>	1 SET	\$ 60.00	\$ 60.00	✓✓
7	TAILGATE OUTER CHROME GARNISH CLIPS <i>neu</i>	1 SET	\$ 20.00	\$ 20.00	+
8	TAILGATE INNER TRIM BOARD CLIPS <i>neu</i>	1 SET	\$ 50.00	\$ 50.00	✓ 20 20
9	TAILGATE GLASS SEALANT <i>Neu</i>	1 SET	\$ 60.00	\$ 60.00	✓ 40
10	REAR FENDER INNER SHIELD CLIPS <i>2 sets</i>	2 SETS	\$ 20.00	\$ 40.00	+
11	REAR FENDER INNER TRIM BOARD CLIPS <i>2 sets</i>	2 SETS	\$ 30.00	\$ 60.00	+
12	FRONT NUMBER PLATE <i>Best</i>	1	\$ 30.00	\$ 30.00	✓ } 35
13	FRONT NUMBER PLATE HOLDER <i>Best</i>	1	\$ 30.00	\$ 30.00	✓
14	FRONT BUMPER CLIPS <i>2 sets</i>	1 SET	\$ 30.00	\$ 30.00	✓ 20
15	FRONT GRILLE CLIPS <i>2 sets</i>	1 SET	\$ 30.00	\$ 30.00	✓ 20
16	BONNET INSULATOR CLIPS <i>Neu</i>	1 SET	\$ 30.00	\$ 30.00	+
17	BONNET WEATHERSTRIPE CLIPS <i>not nec</i>	2 SETS	\$ 10.00	\$ 20.00	+
18	FRONT FENDER INNER SHIELD CLIPS <i>not nec</i>	2 SETS	\$ 30.00	\$ 60.00	+
19	FRONT FENDER GLASS SEALANT <i>Neu LIT</i>	2	\$ 30.00	\$ 60.00	30 X
20	FRONT SUPPORT PANEL TOP GARNISH CLIPS <i>neu</i>	1 SET	\$ 20.00	\$ 20.00	✓
21	AIR CON CONDENSER SIDE GUIDE CLIPS <i>neu</i>	2 SETS	\$ 10.00	\$ 20.00	✓ 10
22	RADIATOR COOLANT <i>Neu</i>	1	\$ 40.00	\$ 40.00	✓
23	BATTERY <i>not nec</i>	1	\$ 280.00	\$ 280.00	X
24	WIPER PANEL GARNISH CLIPS <i>Neu</i>	1 SET	\$ 30.00	\$ 30.00	✓ 20

TOTAL: \$ 1,580.00

450

LABOUR

	JOB	PRICE	ADJUSTED COST	APPROVED
1	PANEL BEATING, REMOVE AND REFIT PARTS	\$ 3,000.00	1600	1400
2	SPRAY PAINTING TO AFFECTED AREA	\$ 2,200.00	1800	1400
3	WIRING CHECK	\$ 100.00	60	40
4	TO APPLY TUFF COAT	\$ 250.00	100	40
5	TO REMOVE REVERSE SENSOR	\$ 100.00	50	40
6	TO REMOVE REAR CAMERA	\$ 100.00	50	40
7	TO REMOVE REAR VIDEO RECORDER	\$ 100.00	X	
8	TO REMOVE UPHOLSTERY	\$ 150.00	60	✓
9	TO TRANSFER TAILGATE FITTINGS	\$ 150.00	60	✓
10	TO REMOVE TAILGATE GLASS	\$ 180.00	120	✓
11	TO REMOVE REAR EXHAUST PIPE	\$ 150.00	X	
12	TO REMOVE FUEL TANK	\$ 150.00	X	
13	TO REMOVE CONDENSER & TO TOP UP AIR CON GAS	\$ 120.00	60	✓
14	TO REMOVE RADIATOR & TO TOP UP COOLANT	\$ 120.00	60	40
15	TO REMOVE DASHBOARD including passenger airbag	\$ 350.00	200	✓
16	TO REMOVE AIR BAGS	\$ 480.00	350	100
17	TO RESET AIR BAG SYSTEM	\$ 380.00	200	120
18	TOWING CHARGES ? towing invoice	\$ 60.00	✓ ?	

TOTAL: \$ 8,140.00

19 To remove seat belts

ESTIMATE REPORT

TOTAL PARTS COST: \$ 24,632.00 *24712.72*
TOTAL LABOUR COST: \$ 8,140.00 *8340*
TOTAL REPAIR COST: \$ 32,772.00 *33052.72*

total: 21614.80

1/5 17.3K

13-14 days

16 Days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Spray Painting

Front Bumper
Bonnet
Front Fender x2
Support Panel
Rear Bumper
End Panel
Tailgate
Rear Fender

Labour Front
4 Days: 800
Labour Rear
4 Days: 800

1600

William P. P. P.