



凱摩哆服務

KAI MOTOR TRADING

BLK 3007 UBI ROAD 1 #01-440, SINGAPORE 408701.
TEL: 6747 4006 FAX: 6743 7591 EMAIL: kaimotor@gmail.com
BUS. REG. NO: 44223100L GST NO: M90371531Y

專業服務：汽車意外保險賠償，拖車，汽車修理及維修服務，打嗎呷，噴漆。

Specialist in: Accidents Insurance Claim, Towing Service, Motor Vehicle Repairing, Panel Beating, Spray Painting.

Date: 16/07/2024

ATTN: Motor Claim Department
Your Insured Vehicle - GBG 6148 H

AIG ASIA PACIFIC INSURANCE PTE LTD.

78 Shenton Way
07-16 Chartis Building
Singapore 079120
Too Chul Fang
Tel 6741 4263 Fax 6741 4108

L.K.K (Adrain)

16.07.2024

2 to 3pm

Dear Sir / Mdm,

Accident Involving Vehicles Nissan Nv200 GBJ 7773 E & GBG 6148 H on 13/07/2024 at 12:30.

PAGE-1

To supply,

1pc	Rear Boot Cover	Deletd		\$ 2,200.00	Nett	✓
2pcs	Rear Boot Cover Hinge	Ren	\$ 86.00 x 2pcs	\$ 172.00	Nett	+
1pc	Rear Boot Lock	Ren		\$ 366.00	Nett	✓
1pc	Rear Boot Rubber	?		\$ 115.00	Nett	?
1pc	Rear Boot Inner Trim	Deletd		\$ 288.00	Nett	✓
1pc	Rear Boot "Nissan" Logo	?		\$ 97.00	Nett	✓
1pc	Rear Boot "Nv 200" Logo	Ren		\$ 145.00	Nett	✓
1pc	Rear Boot Handle	Ren		\$ 115.00	Nett	+
1pc	Rear Boot Garnish	?		\$ 388.00	Nett	?
2pcs	Tail Lamp LH & RH	Ren	\$427 x 2pcs	\$ 854.00	Nett	+
1pc	Rear Bumper	Deletd		\$ 665.00	Nett	✓
1pc	Rear End Panel Outer	?		\$ 227.00	Nett	?
1pc	Rear End Panel Inner	Ren		\$ 668.00	Nett	+
2pcs	Rear Side Retainer LH & RH	Ren	\$59 x 2pcs	\$ 118.00	Nett	+
1pc	Rear Wiper Motor	?		\$ 448.00	Nett	?
1pc	Front Bumper	Deletd		\$ 665.00	Nett	✓
1pc	Front Bumper Sponge	?		\$ 388.00	Nett	?
2pc	Front Bumper Side Retainer LH & RH	Ren	\$32 x 2pcs	\$ 64.00	Nett	+
1pc	Front Bumper reinforcement	?		\$ 1,170.00	Nett	?
				\$ 9,153.00	Nett	
			Less 10%	-\$ 915.30		
				\$ 8,237.70		



凱摩哆服務

KAI MOTOR TRADING

BLK 3007 UBI ROAD 1 #01-440, SINGAPORE 408701.
TEL: 6747 4006 FAX: 6743 7591 EMAIL: kaimotor@gmail.com
BUS. REG. NO: 44223100L GST NO: M90371531Y

專業服務：汽車意外保險賠償，拖車，汽車修理及維修服務，打嗎呷，噴漆。

Specialist in: Accidents Insurance Claim, Towing Service, Motor Vehicle Repairing, Panel Beating, Spray Painting.

Date: 16/07/2024

ATTN: Motor Claim Department
Your Insured Vehicle - GBG 6148 H

AIG ASIA PACIFIC INSURANCE PTE LTD.

78 Shenton Way
07-16 Chartis Building
Singapore 079120
Too Chol Fang
Tel 6741 4263 Fax 6741 4108

Dear Sir / Mdm,

Accident Involving Vehicles Nissan Nv200 GBJ 7773 E & GBG 6148 H on 13/07/2024 at 12:30.

PAGE-2

To supply,

	Page - 1 Balance		\$ 8,237.70
2pcs	Reverse Sensors <i>2pc</i>	\$481.90 x 2pcs	\$ 576.00 S/Nett <i>200</i>
1pc	Rear Windscreen Inner Seal <i>1pc</i>		\$ 226.00 S/Nett <i>120</i>
1pc	Rear Windscreen Sealant		\$ 226.00 S/Nett <i>60</i>
20pcs	Front and Rear Bumper Clips <i>20</i>	\$10.00 x 20pcs	\$ 200.00 S/Nett
2pcs	Front and Rear Number Plate <i>Front 2pc</i>	\$55 x 2pcs	\$ 110.00 S/Nett <i>50</i>
			\$ 9,575.70

To dismantl & replace damage parts, panel beat where necessary

To putty, apply primer & spray paint on the affected portion.

To remove and refix rear windscreen

To remove reverse sensor.

To check wiring functions.

\$ ~~850.00~~ *700*
\$ ~~900.00~~ *600*
\$ ~~180.00~~ *120*
\$ ~~150.00~~ *50*
\$ ~~80.00~~ *60*
\$ 11,735.70

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Adrian Lj
F/S 16/07/24
07 Days