

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/MSG24070259/UQP3M4
Date: 14/10/2024

REFERENCE

Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd.	Policy No:	1001291097		
Claimant Vehicle No :	FBR545B	Insured Vehicle No :	GQ5515B		
Date of Loss:	15/07/2024	Nature of Claim:	TP	Claim No:	366925

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	FBR545B	Engine No:	KCE1E1019036
Make & Model:	HONDA CB150X, 149cc	Chassis No:	MH1KCE119PK019160
Reg. Date:	11/06/2024 (Man. Year: 2024)	Odometer:	1434 km
Colour:	Red		
Engine Capacity:	149 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	100-80-17	Rear Tyre Size:	130-70-17
Front Left Side:	IRC 9 mm	Rear Left Side:	IRC 9 mm
Front Right Side:	0 mm	Rear Right Side:	0 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	1,553.00	420.00	1,133.00	72.96
Miscellaneous Items	0.00	0.00	0.00	
Labour	400.00	80.00	320.00	80.00
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	1,953.00	500.00	1,453.00	74.40

INSPECTION

Date of Assignment:	16/07/2024		
Date Inspected:	17/07/2024	Inspected At:	EROFIA MOTOR TRADING PTE LTD 1 KAKI BUKIT AVENUE 6 #02-62 SINGAPORE 417883
Estimated Period of Repair:	1.0 days		

Adjuster: MARCUS CHUA Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	(Last Synchronised: 30 Sep 2024)	
Parts:	N/A	HONDA CB150X 149cc (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for FBR545B)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR COVER	Repair	485.00 FL	*- FL
2	1		*REAR CENTRE COVER	Serviceable	180.00 FL	*- FL
3	1		*REAR FENDER	Serviceable	285.00 FL	*- FL
4	1		*SET NUMBER PLATE	Serviceable	38.00 FS	*- FS
5	1		*REAR BOX	Damaged	480.00 FS	*320.00 FS
6	1		*REAR BOX BRACKET	Bent	180.00 FS	*100.00 FS
					Sub Total (S\$)	1,648.00
					- List Item Discount on L Items 10.00/10.00% (S\$)	95.00
					Total Parts (S\$)	1,553.00

F=Franchise part. S=SpcNett. L=ListItemDisc.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO PROVIDE LABOUR	New	400.00	80.00
Gross Labour Cost (\$\$)			400.00	80.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >