

李 汽 车 贸 易

GST REG NO. 201918537M

ERZAT LEE MOTOR TRADING PTE LTD

SYNERGY@KB, 25 KAKI BUKIT ROAD 4 #03-37 SINGAPORE 417800

REG. NO. 201918537M

EMAIL : enquiry@erzatleemotor.com

Office : 69661751

ESTIMATE COST OF REPAIR

Date: 15-Jul-24

Estimate no.

1422

Plate No. FBV9635U

Model. Y16

Surveyor's columns

S/N	DESCRIPTION (s)	PRICE (\$)	REMARK	PRICE (\$)
1	FORK SET	\$ 350.00	X	
2	FORK T-UNDER BRACKET	\$ 280.00	X	
3	STEERING CONE	\$ 180.00	X	
4	FRONT TYRES SHAFT	\$ 120.00	X	
5	FRONT FENDER BRACKET R	\$ 80.00	X	
6	FRONT FENDER L	\$ 80.00	X	
7	HANDLE BAR	\$ 160	280.00	X
8	HANDLE BALANCER	\$ 150.00	90	
9	BRAKE LEVER	\$ 100.00	X	
10	CLUTH LEVER	\$ 100.00	X	
11	MIRROR SET	\$ 150.00	X	
12	IU UNIT	\$ 155.80	X	
13	IU BRACKET	\$ 50.00	X	
14	FRONT NUMBER PLATE	\$ 20.00	10 S/N	
15	FRONT PANEL COVER	\$ 120.00		
16	INNER PANEL	\$ 180.00		
17	EXHAUST COVER	\$ 150.00		
18	EXHAUST CAP	\$ 120.00		
19	FRONT FOOTREST SET	\$ 150.00		
20	FRONT FOOTREST BAR	\$ 220.00		
21	GEAR PEDAL	\$ 180.00		
22	REAR SWING ARM	\$ 600.00		
23	REAR SWING ARM COVER	\$ 80.00		
24	RAER BOX	\$ 450.00	380	
25	RAER RACK	\$ 300.00	X	
26	COVERSET	\$ 550.00		
27	LABOUR	\$ 500.00	300	

Less 10% \$ 569.58

\$ 5,695.80

Sub Total : \$ 5,126.22

GST 9% \$ 461.36

Total: \$ 5,587.58

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts price is subject to confirmation

• Third party survey is subject to confirmation

• No illegal modification is allowed

• Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Estimate given are base on visible damages ONLY before dismantling of the vehicle

This is computer generated no signature is required.

Not Author
LKK
motor
16/7/24
L/S \$ 2400
Telught. Affly-
4 days

1-3055
102
2749.50
10
300
3055.50
202
2847.