

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6256 3561 FAX: 6256 4315 Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile					
MS			Ref:	CS/LIP24070261/Tqh3m4	
		AY #25-01 NORTH TOWER	Date:	18/09/2024	
	SINGAPORE 04858		Code:	LIP	
4		Dallan Barthadana - T			
1.	Policy Particulars :- THIRD PARTY CLAIM Insured Veh. SGW 1023Z Veh. Inspected SLK 6554D				
		SGW 10232	-		
	Policy No. Claim No.	AVS24/2188	Coverage Excess	\$0.00	
		KAHARUDIN		15/07/2024	
•	Assign From		Assign Date	13/07/2024	
2.	Make & Model	HONDA SHUTTLE	C.C	1496	
	Engine No.	L15B3535525	Year of Reg.	23/01/2017	
	Chassis No.	GK81004719	Colour	WHITE	
	Odometer	333980 KM	Steering	IN ORDER	
	Brakes	IN ORDER	General	GOOD	
	Modification(s)	RIMS: SPORTS RIM	100		
3.					
J.		Size	Make	Balance (mm)	
	R/H Front Tyre	205/50R16	FALKEN	6	
	L/H Front Tyre	205/50R16	FALKEN	6	
	R/H Rear Tyre	205/50R16	FALKEN	6	
	L/H Rear Tyre	205/50R16	FALKEN	6	
4.					
THE VEHICLE SUSTAINED DAMAGES AT THE REAR O/S PORTION.					
DAMAGES SEE DETAILS.					
5.	5. General Information				
	Accident Date	13/07/2024	Inspection Date	16/07/2024	
	Survey held at	2, KAKI BUKIT ROAD 2 #01-09 - REPA	AIRER: LBC DELIV	ERY PTE LTD	
5a. Remarks					
A) THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.					
5b. Estimate Days of Repair					

ESTIMATED NORMAL PERIOD FOR REPAIR: 4 Working Days